

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources
Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

| | | | |
|-----------------|---------------------------|----------------------|----------------------------------|
| Name of Company | Chevron USA Inc. | Contact | Stephen Gwin |
| Address | 15 Smith Rd, Midland, TX. | Telephone No. | 575-263-0427 Cell - 575-408-0073 |
| Facility Name | Red Hill 2 Battery | Facility Type | Battery |
| Surface Owner | Mineral Owner | API No. 30-025-41546 | |

LOCATION OF RELEASE

| | | | | | | | | |
|-------------|---------|----------|-------|---------------|------------------|---------------|----------------|--------|
| Unit Letter | Section | Township | Range | Feet from the | North/South Line | Feet from the | East/West Line | County |
| P | 2 | 25S | 33E | 330 | South Line | 340 | East Line | Lea |

Latitude 32.153237 N Longitude 103.535237W

NATURE OF RELEASE

| | | | | | |
|-----------------------------|---|---|----------------------|----------------------------|----------|
| Type of Release | Flare | Volume of Release | 6,795 mcf | Volume Recovered | |
| Source of Release | Flare | Date and Hour of Occurrence | 4/1/2015 - 5/31/2015 | Date and Hour of Discovery | 4/1/2015 |
| Was Immediate Notice Given? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No <input type="checkbox"/> Not Required | If YES, To Whom? | Tomas Oberding | | |
| By Whom? | Stephen Gwin | Date and Hour | | | |
| Was a Watercourse Reached? | <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No | If YES, Volume Impacting the Watercourse. | | | |

If a Watercourse was Impacted, Describe Fully.*

RECEIVED

By OCD District 1 at 8:51 am, Jul 01, 2015



Describe Cause of Problem and Remedial Action Taken.*

Flaring is due to DCP intermittent compressor issues at their Antelope Ridge Facility. The flare is operated as a safety device.

Describe Area Affected and Cleanup Action Taken.*

N/A

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

| | | | |
|--|---|--|--|
| Signature:  | OIL CONSERVATION DIVISION | | |
| Printed Name: Stephen Gwin | Approved by Environmental Specialist:  | | |
| Title: Health and Environment Specialist | Approval Date: 07/01/2015 | Expiration Date: // | |
| E-mail Address: Stephen.gwin@chevron.com | Conditions of Approval: // | Attached <input type="checkbox"/> 241333 1RP-3708 | |
| Date: 6/1/2015 | Phone: 575-263-0427 | | |

* Attach Additional Sheets If Necessary

nKJ1518232069
pKJ1518232230