APPROVED

By Olivia Yu at 1:18 pm, Dec 08, 2017

NMOCD approves of the proposed delineation for 1RP-3979.

1RP-3979 DELINEATION PLAN Devon Lease Illegal Dumping Spill Lea County, New Mexico

LAI Project No. 17-0201-01

November 7, 2017

Prepared for: Penroc Oil Corporation 1515 Calle Sur, Suite 174 Hobbs, New Mexico 88240

Prepared by: Larson & Associates, Inc. 507 North Marienfeld Street, Suite 205 Midland, Texas 79701

Mark J. Larson, P.G. Certified Professional Geologist #10490 Sarah R. Johnson Staff Geologist




Table of Contents

1.0 INTRODUCTION	1
1.1 Background	1
1.2 Physical Setting	
1.3 Remediation Action Levels	
2.0 DELINEATION PLAN	4
3.0 REMEDIATION PLAN	5

Figures

Figure 1 Topographic Map

Figure 2 Aerial Map Showing Proposed Sample Points

Appendices

Appendix A Initial C-141 and Documents Produced By Devon Energy Production

Appendix B Photographs

INTRODUCTION

Larson & Associates, Inc. (LAI) has prepared this delineation plan on behalf of Penroc Oil Corporation (Penroc) for submittal to the New Mexico Oil Conservation (OCD) District I for a spills related to illegal dumping at four (4) locations near leases operated by Penroc and previously operated Devon Energy Production (Devon), in Lea County, New Mexico. The leases include:

- Altbeir 10 State #1H, in Unit N (SE/4, SW/4), Section 10, Township 18 South, Range 36 East;
- Dopplebock 8 State Com #1H, in Unit B (NW/4, NE/4), Section 8, Township 18 South, Range 36
 East;
- Dunkel 7 State #1H, in Unit E (SW/4, NW/4), Section 17, Township 18 South, Range 36 East; and
- Guadalcanal State Com #1H, in Unit D (NW/4, NW/4), Section 34, Township 17 South, Range 36 East.
 - Figure 1 presents a topographic map.

1.1 Background

On August 26, 2015, a land owner discovered unusual discoloration and tire tracks on his property and notified the nearest lease operator, Devon, about the illegal dumping of produced fluids in the vicinity of the four (4) Devon leases. The illegal dumping was reported to the OCD (verbal communication with Thomas Oberding) on September 1, 2015. The initial C-141 was submitted on September 2, 2015. The OCD assigned remediation permit number 1RP-3979.

LAI was requested by Penroc to prepare this delineation plan. LAI determined that GPS coordinates presented on the initial C-141 were incorrect. LAI relied on legal description provided on the initial C-141 as well as photographs and drawings provided by Devon to locate the spills. The C-141 describes each spill based on proximity to the nearest Devon lease. On November 1 and 6, 2017 LAI personnel conducted reconnaissance visits using the legal descriptions, drawings and photographs. LAI describes the physical setting based on the spill areas rather than lease locations as some spills were not close to the identified leases. Appendix A presents the initial C-141 and photographs and maps produced by Devon.

1.1.1 Altbeir 10 State #1H

LAI personnel collected photographs at the Altbeir 10 State #1H in similar orientation and direction as photographs by Devon. LAI personnel mapped the visible spill area with a Trimble sub-meter GPS receiver. A spill area was observed just off the lease road to the north of the now plugged and abandoned Altbeir 10 State #1 well. The vegetative cover has improved since the spill was initially reported but scarring is visible. LAI mapped the impact area as about 9,400 square feet or about 0.22 acre. Figure 2a presents an aerial map. Appendix B presents photographs.

Devon also presented photographs and a map for an area of discolored vegetation about 2,000 feet west of the well, however, LAI personnel were unable to locate this area with information provided by Devon.

1.1.2 Dopplebock 8 State Com #1H

LAI personnel collected photographs at the Dopplebock 8 State Com #1H in similar orientation and direction as photographs taken by Devon and mapped the visible spill area using a Trimble sub-meter GPS receiver. An area of discolored vegetation similar to what Devon photographed was visible along the east side of the lease road leading up to the tank battery. The area of discolored vegetation measures approximately 6,200 square feet or about 0.14 acre. There were no visible signs of impact within the tank battery pad. Figure 2b presents an aerial map. Appendix B presents photographs.

1.1.3 Dunkel 7 State #1H

LAI personnel collected photographs at the Dunkel 7 State #1H in similar orientation and direction as photographs taken by Devon and mapped the visible spill area using a Trimble sub-meter GPS receiver. An area of discolored vegetation was also observed about 1 mile south of the Dunkel 7 State #1H location and measured about 5,700 square feet or about 0.13 acre. The spill is situated predominately on the lease road with a runoff into the pasture on either side. Figure 2c presents an aerial map. Appendix B presents photographs.

1.1.4 Guadalcanal State Com #1H

LAI personnel conducted a site reconnaissance at the Guadalcanal State Com #1H on November 1, 2017. No impacted vegetation or discolored soil was observed in the vicinity of the well or tank battery. LAI observed an area of discolored soil near the lease entrance about 2 miles west of the location. Figure 2d presents an aerial map. Appendix B presents photographs.

1.2 Physical Setting

The physical setting for is as follows:

1.2.1 Altbeir 10 State #1H

- The surface elevation is approximately 3,822 feet above mean sea level (msl);
- The surface topography slopes gently towards the southeast;
- There are no surface water features within 1,000 feet of the Site;
- The soils are designated as "Portales loam, 0 to 3 percent slopes", consisting of 0 to 14 inches of loan underlain by 14 to 35 inches of clay loam;
- The surface geology is the Ogallala Formation (lower Pliocene to middle Miocene) consisting of alluvial and eolian deposits, and petrocalcic soils of the southern High Plains;
- Groundwater occurs in the Ogallala formation at approximately 55 feet below ground surface (bgs) (1991);
- The nearest fresh water well is located in Unit G (SW/4, NE/4) in Section 10, Township 18 South, Range 36 East about 0.40 miles northeast of the Site.

1.2.2 Dopplebock 8 State Com #1H

- The surface elevation is approximately 3,860 feet above msl;
- The surface topography slopes gently towards the northeast;
- There are no surface water features within 1,000 feet of the Site;
- The soils are designated as "Kimbrough-Lea complex, dry, 0 to 3 percent slopes", consisting of 0 to 3 inches of gravelly loam underlain by 3 to 10 inches of loam;
- The surface geology is the Ogallala Formation (lower Pliocene to middle Miocene) consisting of alluvial and eolian deposits, and petrocalcic soils of the southern High Plains;
- Groundwater occurs in the Ogallala formation at approximately 57 feet bgs (1986);
- The nearest freshwater well is located in Unit G (SW/4, NE/4), Section 8, Township 18 South, Range 36 East about 0.40 miles southwest of the Site.

1.2.3 Dunkel 7 State #1H

- The surface elevation is approximately 3,855 feet above msl;
- The surface topography slopes gently towards the southeast;

- There are no surface water features within 1,000 feet of the Site;
- The soils are designated as "Kimbrough-Lea complex, dry, 0 to 3 percent slopes", consisting of 0 to 3 inches of gravelly loam underlain by 3 to 10 inches of loam;
- The surface geology is the Ogallala Formation (lower Pliocene to middle Miocene) consisting of alluvial and eolian deposits, and petrocalcic soils of the southern High Plains;
- Groundwater occurs in the Ogallala formation at approximately 51 feet bgs (1986);
- The nearest freshwater well is located in Unit J (NW/4, SE/4), Section 17, Township 18 South, Range 36 East about 0.45 miles east of the Site.

1.2.4 Guadalcanal State Com #1H

- The surface elevation is approximately 3,850 feet above msl;
- The surface topography gently slopes towards the southeast;
- There are no surface water features within 1,000 feet of the Site;
- The soils are designated as "Portales and Gomez fine sandy loams", consisting of 0 to 8 inches of fine sandy loam underlain by 8 to 60 inches of clay loam;
- The surface geology is the Ogallala Formation (lower Pliocene to middle Miocene) consisting of alluvial and eolian deposits, and petrocalcic soils of the southern High Plains;
- Groundwater occurs in the Ogallala formation at approximately 56 feet bgs (1986);
- The nearest freshwater well is located in Unit M (SW/4, SW/4), Section 34, Township 17 South, Range 36 East about 0.75 miles southeast of the Site;

1.3 Recommended Remediation Action Levels

Recommended remediation action levels were calculated for benzene, BTEX and TPH based on the following criteria established by the OCD in "Guidelines for Remediation of Leaks, Spills and Releases, pp. 6-7, August 13, 1993":

1.3.1 Altbeir 10 State #1H

Criteria	Result	Score
Depth-to-Groundwater	50 – 99 Feet	10
Wellhead Protection Area	No	0
Distance to Surface Water Body	>1,000 Horizontal Feet	0

The following RRAL apply to the release for ranking score: 10

Benzene 10 mg/Kg
 BTEX 50 mg/Kg
 TPH 1,000 mg/Kg

1.3.2 Dopplebock 8 State Com #1H

Criteria	Result	Score
Depth-to-Groundwater	50 – 99 Feet	10
Wellhead Protection Area	No	0

Distance to Surface Water Body	>1,000 Horizontal Feet	0
--------------------------------	------------------------	---

The following RRAL apply to the release for ranking score: 10

Benzene 10 mg/Kg
 BTEX 50 mg/Kg
 TPH 1,000 mg/Kg

1.3.3 Dunkel 7 State #1H

Criteria	Result	Score
Depth-to-Groundwater	50 – 99 Feet	10
Wellhead Protection Area	No	0
Distance to Surface Water Body	>1,000 Horizontal Feet	0

The following RRAL apply to the release for ranking score: 10

Benzene 10 mg/Kg
 BTEX 50 mg/Kg
 TPH 1,000 mg/Kg

1.3.4 Guadalcanal State Com #1H

Criteria	Result	Score
Depth-to-Groundwater	50 - 99 Feet	10
Wellhead Protection Area	No	0
Distance to Surface Water Body	>1,000 Horizontal Feet	0

The following RRAL apply to the release for ranking score: 10

Benzene 10 mg/Kg
 BTEX 50 mg/Kg
 TPH 1,000 mg/Kg

Depth to groundwater between 50 and 99 feet bgs requires vertical delineation for chloride to 600 milligrams per kilogram and maintained a minimum 10 feet further in depth.

2.0 DELINEATION PLAN

LAI proposes to delineate the observed impacts at four (4) sites. Soil samples will be collected within each spill area at 1 foot intervals to approximately 4 feet bgs and 2 foot intervals to approximately 12 feet bgs using direct push technology (DPT) depending on subsurface conditions. Additional samples with be collected in each cardinal direction (north, south, east and west) of the spill areas for horizontal delineation. The samples with be delivered under chain of custody and preservation to Permian Basin Environmental Lab (PBEL) located in Midland, Texas. The laboratory will analyze the upper sample (0 to 1 foot) for benzene, toluene, ethylbenzene and xylenes (BTEX), total petroleum hydrocarbons (TPH), including gasoline range organics (GRO), diesel range organics (DRO) and oil range organics (ORO) by

EPA SW-846 Methods 8021B and 8015M, respectively. Additional samples will be analyzed to determine the vertical extent of these compounds should the laboratory report concentrations above the RRAL. All samples will be analyzed for chloride by EPA Method and 300 until the delineation requirements are achieved. Pending laboratory results, further delineation will be determined to reach cleanup level standards. Figures 2a, 2b, 2c and 2d present the proposed soil sample locations.

3.0 REMEDIAITON PLAN

Penroc will include a remediation plan in the delineation report to be submitted to the OCD upon receipt of the laboratory report.

Figures






Figure 2a - Aerial Map



Figure 2b - Aerial Map



Figure 2c - Aerial Map



Figure 2d - Aerial Map

Appendix A

Initial C-141 and Documents Produced By Devon Energy Production

I 1625 N. French Dr., Hobbs, NM 88240 <u>District II</u> 811 S. First St., Artesia, NM 88210 <u>District III</u> 1000 Rio Brazos Road, Aztec, NM 87410 <u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexic Energy Minerals and Natural

RECEIVED
By JKeyes at 2:07 pm, Nov 12, 2015

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

ivelease indiffication and Corrective Actio	Release	Notification	and	Corrective	Action
---	---------	--------------	-----	------------	--------

						OPERA'	ГOR		🛚 Initia	ıl Report		Final Report
						Contact R				411.441.44		
							No. 575-390-54	35				
Facility Na	me Altbeir	10 State 1H				Facility Ty	oe Oil			······································		
Surface Ow	ner State			Mineral C	wner	State			API No	. 30-025-4	2290	
				LOCA	TION	OF REI	LEASE					
Unit Letter	Section	Township	Range	Feet from the		South Line	Feet from the	East/V	Vest Line	County		
N	10	188	36E	230	8	South	1980	V	Vest	Lea		
Latitude: N 32'76'85.22" Longitude: W 103'34'45.64" NATURE OF RELEASE												
Type of Rele	ase Spill			IVAI	UKE	Volume of			Volume F	Recovered		
Produced W	ater					Unknown			None			
Source of Re							lour of Occurre	nce		Hour of Di	scover	y
Illegal dump Was Immedi						If YES, To	or 22, 2015 Whom?	İ	August 20	6, 7:00 AM		
			Yes 🗌	No 🗌 Not Re	quired		nas Oberding					
By Whom?						Date and l						
Ruben Garci	ia						1, 2015 @ 2:00					
Was a Water	renurse Re	ached?				September 1, 2015 @ 1:50 PM If YES, Volume Impacting the Watercourse						
			Yes 🖂	No		** 1 ** 25, 7	, turne timpacemb	the ,				
If a Waterco	urse was It	npacted, Des	eribe Full	y.*		<u> </u>						
Describe Car	ase of Prob	lem and Rem	iedial Act	ion Taken.*								
Describe Cause of Problem and Remedial Action Taken.* On September 1, 2015 Land owner was out checking his land when he noticed there was discoloration and tire tracks on his land. He went to the nearest location and notified Devon lease operator and advised him of the illegal dumping. There was an unknown amount of produced water that had been dumped on the pasture.												
Describe Arc Devon Secui		-		aken.* is investigating t	he situ	ation.						
I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.												
Signature: Co	orina N	loya					OIL CON	<u>SERV</u>	<u>ATION</u>	DIVISIO	<u>)N</u>	
Printed Name	: Corina M	loya				Approved by	Environmental S	pecialis	<i>Ja…¥.</i> t:	Uga ·		
Title: Field A	dmin Sup _l	ort				Approval Da	.e: 11/12/2015		Expiration	Date: 01/12	:/2016	and in a second
E-mail Addre	ss: corina. ı	noya@dvn.co	om			Conditions o		E 15 . U.		Attached	. 🗀	TAXABLE PROPERTY OF THE PROPER
Date: 9	.2.2015	Р	hone: 575.	.746.5559			samples required r NMOCD guide		rate and	IRP 3979)	

^{*} Attach Additional Sheets If Necessary

<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Release Notification and Corrective Action												
						OPERA T	FOR	⊠ Init	al Report	\Box	Final Report	
Name of Co	mpany D	evon Energy	Producti	on		Contact Rudy Zuniga						
Address 64						Telephone No. 575-390-5435						
Facility Nat	me Dopple	bock 8 State	Com 1F		I	Facility Typ	oe Oil					
6 6 0				150. 10		^		1	20.025	41.604		
Surface Ow	ner State	<u>}</u>		Mineral C	Jwner :	State		APIN	o. 30-025-	41694		
						OF REI						
Unit Letter Section Township B 18S S6E 200 North South Line Feet from the North/South Line Feet from the East/West Line County Lea												
Latitude: N 32'76'87.75" Longitude: W 103'37'45.81"												
NATURE OF RELEASE												
Type of Rele	ase Spill			11/21	UILL	Volume of		Volume	Recovered			
Produced W						unknown	Reiense	none	Accordica			
Source of Re	lease					Date and I	lour of Occurre	nce Date an	d Hour of D	iscover	y	
Illegal dump							or 22, 2015	August	26, 7:00 AM			
Was Immedi	ate Notice	*****	V	No Not Re	المستنيم	If YES, To						
			res	NO NOT KE	quirea	BLM	nas Oberding					
By Whom?						Date and I	łour					
Ruben Garci	a					September	1, 2015 @ 2:00					
Was a Water	course Res	ched?			·····		· <u>1, 2015 @ 1:50</u> dume Impacting		n			
.,,			Yes 🗌	No		11 125, **		the watercours				
If a Waterco	urse was Ir	npacted, Des	cribe Full	y.*								
Describe Cau	ise of Prob	lem and Rem	edial Act	ion Taken.*								
On Septembe	er 1, 2015 I	and owner v	vas out ch	ecking his land v	vhen he	noticed the	re was discolorat	tion and tire trac	ks on his lar	ıd. He v	went to the	
			lease oper	ator and advised	him of	the illegal d	umping. There v	vas an unknown	amount of p	roduce	d water that	
had been dur	mped on th	e pasture.										
Describe Are	a Affected	and Cleanur	Action T	aken.*								
		-		is investigating t	he situa	tion.						
Y 1	C. 41 4 41	- C			4 4 4	1 / 6		1 . 1 . 1 . 1		(0.01)	, ,	
requisitions al	ly mat me n Loperators :	normanon gr are required to	ven above	is true and compl d/or file eertain re	ete to tn	ie best of my atifications a	knowledge and u	nderstand that pu	rsuant to NM Jasses which	OUD II	iles and	
				c of a C-141 repo								
should their o	perations ha	ave failed to a	dequately	investigate and re	mediate	contaminati	on that pose a thr	eat to ground wat	er, surface w	ater, hu	man health	
or the environ	ment. In ac	ldition, NMO	CD accep	tance of a C-141 i	eport de	oes not reliev	e the operator of	responsibility for	compliance v	with any	other	
federal, state,	or local law	s and/or regu	lations.									
0		•					OIL CON:	<u>SERVATION</u>	<u>I DIVISI</u>	<u>NC</u>		
Signature: Co	orina M	loya										
Printed Name	: Corina M	oya			/	Approved by	Environmental S	pecialist:				
Title: Field A	dmin Sunn	ort				Approval Dat	e:	Expiration	Date:			
			***************************************		 	-Phrona Ma		i zmpriudo.				
E-mail Addre	ss: corina.r	moya@dvn.co	om		(Conditions of	`Approval:		Attached	i 🗌		
Date:	9.2.2015	p	hone: 575	746.5559								

^{*} Attach Additional Sheets If Necessary

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico Energy Minerals and Natural Resources

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.

Form C-141 Revised August 8, 2011

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505

Release Notification and Corrective Action											
						OPERA T	ΓOR	🛭 lnitia	al Report 🔲 Final Report		
		evon Energy				Contact R					
		Rivers Hwy	Artesia, N	M 88220			No. 575-390-54	35			
Facility Na	me Dunke	17 State 1H				Facility Ty	oe oil				
Surface Ov	vner State			Mineral (Owner	State		API No	. 30-025-41693		
				LOCA	TION	OF REI	LEASE				
Unit Letter 4	Section 7	Township 188	Range 36E	Feet from the 200		South Line South	Feet from the 865	County Lea			
Latitude: N 32'76'84.12" Longitude: W 103'40'01.27" NATURE OF RELEASE											
Type of Rele	ase Spill			IVAI	UKE	Volume of		Volume l	Recovered		
Produced W						Unknown	recease	none			
Source of Re		_					lour of Occurre	1	Hour of Discovery		
Illegal Dump Was Immed						August 21 If YES, To	or 22, 2015	August 2	6, 2015		
TY 45 IIIIIICU	iate Notice		Yes [No 🗌 Not Re	quired		nas Oberding				
By Whom?						Date and I					
Ruben Garc	ia					September 1, 2015 @ 2:00 PM September 1, 2015 @ 1:50 PM					
Was a Water	rcourse Re	ached?	Yes 🗵	No		If YES, Volume Impacting the Watercourse					
If a Waterco	urse was Ii	npacted, Des	cribe Full	y.*							
Describe Ca	use of Prob	lem and Rem	edial Act	ion Taken.*	· · · · · · · · · · · · · · · · · · ·						
nearest locat	Describe Cause of Problem and Remedial Action Taken.* On September 1, 2015 Land owner was out checking his land when he noticed there was discoloration and tire tracks on his land. He went to the nearest location and notified Devon lease operator and advised him of the illegal dumping. There was an unknown amount of produced water that had been dumped on the pasture.										
Describe Arc	ea Affected	and Cleanup	Action 1	aken.*							
Devon Secur	ity was cal	led out to loca	ation and	is investigating t	he situa	ıtion.					
regulations al public health should their o	I operators or the environment of the operations had needed.	are required to conment. The ave failed to a ddition, NMO	report an acceptanc dequately CD accep	d/or file eertain ro e of a C-141 repo investigate and ro	elease no rt by the emediate	otifications and NMOCD me contaminati	nd perform correct arked as "Final R on that pose a threat the operator of	etive actions for rel eport" does not rel eat to ground wate responsibility for c	suant to NMOCD rules and eases which may endanger ieve the operator of liability r, surface water, human health ompliance with any other		
Signature: C o	orina k	loya					OIL CON	<u>SERVATION</u>	DIVISION		
Printed Name	: Corina M	loya				Approved by	Environmental S	pecialist:			
Title: Field A	dmin Supp	ort				Approval Dat	e:	Expiration	Date:		
E-mail Addre	ss: corina.1	noya@dvn.co	m			Conditions of	Approval:		Attached		
Date: 9	9.2.2015	Ph	one: 575.	746,5559					1		

^{*} Attach Additional Sheets If Necessary

District I 1625 N. French Dr., Hobbs, NM 88240 District II 813 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505


State of New Mexico Energy Minerals and Natural Resources


Form C-141
Revised August 8, 2011


Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC.


Release Notification and Corrective Action												
			·			OPERATOR Initial Report Final R						
							Contact Rudy Zuniga					
				NM 88220			No. 575-390-54	35				
Facility Na	me Guada	lcanal State	Com IFI			Facility Ty	pe OII					
Surface Ov	vner State)		Mineral	Owner	State		API No	. 30-025-	41373		
				LOCA	ATION	OF REI	LEASE					
Unit Letter M	Section 25	Township 17S	Range 36E	Feet from the 100	1	orth/South Line Feet from the East/West Line County South 360 West Lea						
Latitude: N 32'81'31.52" Longitude: W 103'31'65.44" NATURE OF RELEASE												
Type of Rele	aca C nill		***************************************	NAT	URE	Volume of		\$7.a.l	Recovered			
Produced W						Unknown	Reiease	None	Recovered			
Source of Re					· · · · · · · · · · · · · · · · · · ·	1	Hour of Occurre		Hour of D			
Illegal dump Was Immed						August 21 If YES, To	or 22, 2015	August 2	6, 7:00 AM	· · · · · · · · · · · · · · · · · · ·		
Trus Illinous	iate . voice		Yes [No Not R	equired		nas Oberding					
By Whom?						Date and						
Ruben Garc	12					September 1, 2015 @ 2:00 PM September 1, 2015 @ 1:50 PM						
Was a Water	rcourse Re					If YES, Volume Impacting the Watercourse						
		لـا	Yes 🗵	No								
If a Waterco	urse was I	mpacted, Des	cribe Ful	ly.*								
Describe Car	use of Prob	lem and Ren	nedial Act	ion Taken.*								
On Septemb	er 1, 2015	Land owner v	was out cl	ecking his land	when ho	noticed the	re was discolorat	tion and tire tracl	s on his lar	id. He went to the		
nearest locat	ion and no	tified Devon	lease oper	rator and advise	d him of	f the illegal d	umping. There v	was an unknown a	mount of p	roduced water that		
had been du	mped on th	ie pasture.										
Decembe And	a Affaatad	and Cleanu	Astion	Calcan *								
				l is investigating	the situ	ation.						
								inderstand that pur				
								tive actions for rel				
								eport" does not rel		ater, human health		
or the enviror	nnent. In a	ddition, NMC	CD accep					responsibility for o				
federal, state,	or local lay	vs and/or regu	llations.				011 001	OF DAY A BY ON	DWW	*>		
Signature: Co	orina k	1oya					OIL CON	<u>SERVATION</u>	DIVISIO	<u>JN</u>		
Printed Name	:: Corina N	Ioya				Approved by	Environmental S	pecialist:				
Title: Field A	dmin Supj	port				Approval Da	te:	Expiration	Date:	MANAGEMENT // MINISTER STATE OF THE STATE OF		
E-mail Addre	ss: corina.	moya@dvn.c	0 m			Conditions o	f Approval:		Attached	i 🔲		
Date: 9	2 2015	Pho	ne: 575 74	6 5550								

^{*} Attach Additional Sheets If Necessary


































Appendix B

Photographs



Altbeir 10 State 1H Site Location



Altbeir Site Prior to Remediation Viewing West, November 1, 2017



Altbeir Site Prior to Remediation Viewing North, November 1, 2017



Altbeir Site Prior to Remediation Viewing East, November 1, 2017



Altbeir Site Prior to Remediation Viewing South, November 1, 2017



Dopplebock 8 State Com 1H Site Location



Dopplebock Site Prior to Remediation Viewing North, November 1, 2017



Dopplebock Site Prior to Remediation Viewing Northwest, November 1, 2017



Dopplebock Site Prior to Remediation Viewing South, November 1, 2017



Dunkel 7 State 1H Prior to Remediation viewing North, November 1, 2017



Guadacanal State Com 1H Site Locaation



Guadacanal Site Viewing South, November 6, 2017



Guadacanal Site Prior to Remediation Viewing North, November 6, 2017



Guadacanal Site Prior to Remediation Viewing South, November 6, 2017