Mr. Burton:

A couple of questions regarding the closure report for 1RP-4773:

- 1. There is a mistake in the liner thickness. Please verify that a 20 mil liner was emplaced, not a 0.20 mil liner.
- 2. Were bottom confirmation samples taken for laboratory analyses at the excavated areas represented by SP2, SP3, SP11, SP13, SP16, and SP18 that were not lined? This was a condition specified on the approved delineation report regarding the proposed remedial activities.

Please be advised that this release occurred on State surface. Mark Naranjo will be the correspondent for NMSLO in the interim.

Thanks, Olivia

From: Mike Burton [mailto:marineburton@gmail.com]
Sent: Thursday, October 26, 2017 12:47 PM
To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>
Subject: Linn CMU North Inj. #52 closure report

Olivia,

Please see the attached link and the attached C-141 final. Thank you for your help.

https://files.acrobat.com/a/preview/eaee37f1-0ebd-4715-816a-4421c20ff413

Michael Ray Burton 575-499-5306 USMC VET