From: Yu, Olivia, EMNRD

To: <u>"Tara Hodges"; mnaranjo@slo.state.nm.us</u>
Cc: <u>Melanie Nolan; ballen@sesi-nm.com</u>

Subject: RE: Holly Energy Partners 8inch Crouch Line Work Plan

Date: Tuesday, January 23, 2018 2:23:00 PM

Mr. Allen:

Please clarify these concerns regarding 1RP-4885:

- 1. As there are 3 NMOSE identified water wells within 1000 ft. of the release location, adjust RRALS accordingly.
- 2. What were the approximate distances of the 4 test trenches for delineation from the release point?
- 3. At what depths were the samples taken from the walls of these trenches?
- 4. Are there field data for delineation between the surface and bottom of TT5 at 7 ft. bgs?
- 5. The laboratory results do not indicate that the soil has been contaminated. Is the inference that all 10 bbls of unrecovered oil are within the 3 ft. radius of pipeline?

Thanks,

Olivia Yu Environmental Specialist NMOCD, District I Olivia.yu@state.nm.us 575-393-6161 x113

OCD approval does not relieve the operator of liability should their operations fail to adequately investigate and remediate contamination that may pose a threat to ground water, surface water, human health or the environment. In addition, OCD approval does not relieve the operator of responsibility for compliance with any other federal, state, local laws and/or regulations.

From: Tara Hodges [mailto:office2@sesi-nm.com]

Sent: Monday, January 15, 2018 2:11 PM

To: Yu, Olivia, EMNRD <Olivia.Yu@state.nm.us>; mnaranjo@slo.state.nm.us **Cc:** Melanie Nolan <Melanie.Nolan@hollyenergy.com>; ballen@sesi-nm.com

Subject: Holly Energy Partners 8inch Crouch Line Work Plan

Hello!

I have attached, per Bob Allen SESI, the proposed work plan for the Holly Energy Partners 8 inch Crouch Line. Please review and let us know if you have any questions.

Thank You

Tara Hodges

Safety & Environmental Solutions, Inc. 703 East Clinton Street Hobbs, NM 88240

Office: (575) 397-0510