APPROVED

By Olivia Yu at 10:14 am, Apr 09, 2018

NMOCD approves of the proposed delineation plan for 1RP-3299.

# 1RP-3299 DELINEATION PLAN Panther Federal #003 Crude Oil Spill Lea County, New Mexico

Latitude: N32° 47′ 15.43″ Longitude: W-103° 48′ 22.60″

LAI Project No. 17-0175-08

February 20, 2018

Prepared for: Legacy Reserves Operating, LP 303 West Wall Street, Suite 1300 Midland, Texas 79701

Prepared by: Larson & Associates, Inc. 507 North Marienfeld Street, Suite 205 Midland, Texas 79701

Mark J. Larson, P.G. Certified Professional Geologist #10490

Sarah R. Johnson Staff Geologist

This Page Intentionally Left Blank

#### **Table of Contents**

1.0 INTRODUCTION	1
1.1 Background	1
1.2 Physical Setting	1
1.3 Remediation Action Levels	
2.0 DELINEATION PLAN	2
3.0 REMEDIATION PLAN	2

### Figures

Figure 1	Topographic Map
Figure 2	Aerial Map Showing Proposed Sample Locations

#### Attachments

Attachment A	Initial C-141
Attachment B	Photographs

1RP-3229 Delineation Plan Panther Federal #003 Crude Oil Spill February 20, 2018

## **1.0 INTRODUCTION**

Larson & Associates, Inc. (LAI), has prepared this delineation plan on behalf of Legacy Reserves Operating, LP (Legacy) for submittal to the New Mexico Oil Conservation Division (OCD) District 1 for a crude oil spill at the Panther Federal #003 (Site) located in Unit K (NE/4, SW/4), Section 31, Township 17 South, Range 32 East in Lea County New Mexico. The geodetic position is North 32° 47' 15.43" and West 103° 48' 22.60". Figure 1 presents a topographic map. Figure 2 presents an aerial map.

#### 1.1 Background

The spill occurred due to a small leak in a flow line, releasing approximately 2 barrels (bbl) of crude oil. No fluid was recovered. The date of occurrence is unknown. The release was contained to the lease road with minor overspray in the pasture on either side of the lease road. The affected area measures approximately 300 square feet. The initial C-141 was submitted on August 16, 2014 and assigned remediation permit number 1RP-3299. Appendix A presents the initial C-141.

#### 1.2 Physical Setting

The physical setting is as follows:

- The surface elevation is approximately 3,855 feet above mean sea level (msl);
- The surface topography gradually to the southwest;
- There are no surface water features within 1,000 feet of the Site;
- The soils are designated as "Kermit soils and dune land, 0 to 12 percent slopes", consisting of 0 to 60 inches of fine sand;
- The geology is Eolian and piedmont deposits (Holocene to middle Pleistocene)- interlayed eolian sands and piedmont-slope deposits;
- Groundwater occurs in the Ogallala formation at approximately 65 feet below ground surface (bgs) (1977);
- According to the New Mexico Office of the State Engineer (OSE) website the nearest freshwater well is located in Unit F (SE/4, NW/4) in Section 4, Township 8 South, Range 32 East approximately 2.09 miles southeast of the Site.

#### **1.3** Recommended Remediation Action Levels

Recommended remediation action levels (RRAL) have been calculated for benzene, BTEX and TPH based on the following criteria established by the OCD in *"Guidelines for Remediation of Leaks, Spills and Releases, pp. 6-7, August 13, 1993"*:

Criteria	Result	Score
Depth-to-Groundwater	50 – 99 Feet	10
Wellhead Protection Area	No	0
Distance to Surface Water Body	>1000 Horizontal Feet	0

10

The following RRAL apply to the release ranking score:

- Benzene 10 mg/Kg
- BTEX 50 mg/Kg
- TPH 1,000 mg/Kg

1RP-3229 Delineation Plan Panther Federal #003 Crude Oil Spill February 20, 2018

Depth to groundwater between 50 and 99 feet requires vertical delineation of chloride to 600 milligrams per kilogram (mg/Kg) and maintained to a minimum 5 feet farther in depth.

# 2.0 DELINEATION PLAN

LAI proposes to collect soil samples at three (3) locations within the spill area. The samples will be collected at 1 foot intervals to approximately 4 feet bgs and 2 foot intervals to approximately 12 feet bgs using direct push technology (DPT) depending on subsurface conditions. Additional samples will be collected in each cardinal direction (north, south, east and west) of the spill area at the same depth intervals for horizontal delineation. The soil samples will be delivered under chain of custody and preservation to Xenco Laboratories (Xenco) in Midland, Texas. The upper samples (i.e. 0 to 1 foot) will be analyzed for benzene, toluene, ethylbenzene and xylenes (BTEX) and total petroleum hydrocarbons (TPH), including gasoline range organics (GRO), diesel range organics (DRO) and oil range organics (ORO) by EPA SW-846 Methods 8021B and 8015M, with additional samples analyzed as needed for delineation. All samples will be analyzed for chloride by EPA Method 300. Pending laboratory results, further delineation may be required to reach cleanup level standards. Appendix B presents photographs.

### 3.0 REMEDIAITON PLAN

Legacy will include a remediation plan in the delineation report to be submitted to the OCD upon receipt of the laboratory report.

Figures




Figure 1 - Topographic Map



Appendix A Initial C-141

State of New Mexico Energy Minerals and Natural Resources

> **Oil Conservation Division** 1220 South St. Francis Dr. Santa Fe, NM 87505

**HOBBS OCD** 

Initial Report

Form C-141 SEP 0 2 2014 Revised August 8, 2011

Final Report

Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC. **RECEIVED** 

**Release Notification and Corrective Action OPERATOR** 

Name of Company - Legacy Reserves Operating, LP							rian Cunninghar			
Address – 303 W. Wall St. Midland, TX 79701 Facility Name – Panther Federal No. 003										
Facility Nan	ne – Panth	er Federal N	0.003			Facility Typ	e – Flow Line			
Surface Owner – Federal Mineral Owner						er -Federal API No. 30-025-36324				
				LOCA	TIO	N OF RE	LEASE			
Unit Letter K	Section 31	Township 17S	Range 32E	Feet from the 1650		South Line South	Feet from the 1650	County Lea		
			La				le - 103°4	8 '21.60"		
NATURE OF RELEASE       Type of Release - Hydrocarbon     Volume of Release - 2 bbl     Volume Recovered - 0										
Type of Release - Hydrocarbon Source of Release - Flow Line						Volume of Release - 2 bbl     Volume Recovered - 0       Date and Hour of Occurrence -     Date and Hour of Discovery				
Was Immediate Notice Given? If YES, To Whom?										
By Whom? Date and Hour   Was a Watercourse Reached? If YES, Volume Impacting the Watercourse.										
If a Wateroon	rse was Im	pacted, Descri	_				<u></u>			
Describe Area The affected a soil and dispo	a Affected area is main use of it. Le	and Cleanup A hly a lease roa egacy will rep nformation gi	Action Tak d with lig lace with o ven above	ken.* ht-moderate spray clean soil appropr e is true and comp	in the plate for lete to the total sector the sector the sector sector sector the sector sect	pasture on bo the surroundi he best of my	th sides of the leas ng area. The affect knowledge and u	se road. Legacy cted area is appro- nderstand that pu	nediately shut down and repaired. intends to remove the affected eximately 300 ft <sup>2</sup> .	
public health should their o or the enviror	or the environment or the environment of the enviro	ronment. The ave failed to a	acceptand idequately OCD accep	ce of a C-141 report investigate and re	ort by th emediat	e NMOCD m e contaminati	arked as "Final R ion that pose a three the operator of r	eport" does not r eat to ground wa responsibility for	elieve the operator of liability er, surface water, human health compliance with any other	
Signature: 🏹	6-	OIL CONSERVATION DIVISION						N DIVISION		
Printed Name	<u> </u>	n Cur	ning	1ªm	Approved by Environmental Specialist:					
Title: Prod	uction	Forer	han	<u> </u>		Approval Da	te: 09-02-19	Expiratio	n Date:	
E-mail Addre Date: 8/2	6/14	unning hai	Phone:	1992-52 lp.c. 1432-234-9		Conditions o R	f Approval: 2 mclute aits n male	per NMOCO	Attached [] IRP-329	
Attach Addit	tional She	ets If Necess	ary			$\sigma$	The second secon		091id 24097	
									NTO 19 24 5509	
						7	SEF	0 5 201	DTALY NO DO	
			****							

Appendix " Photographs



Site Prior to Remediation Viewing East, September 11, 2017



Site Prior to Remediation Viewing South, September 11, 2017



Site Prior to Remediation Viewing West, September 11, 2017