

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

## Release Notification and Corrective Action

### OPERATOR

☐ Initial Report ☒ Final Report

Name of Company	Devon Energy Production Company	Contact	Michael Shoemaker
Address	6488 Seven Rivers Hwy Artesia, NM 88210	Telephone No.	575-748-3371
Facility Name	Rio Blanco 33 Federal #1	Facility Type	Salt Water Disposal
Surface Owner	Private	Mineral Owner	Federal
		API No	30-025-36359

### LOCATION OF RELEASE

Unit Letter	Section	Township	Range	Feet from the	North/South Line	Feet from the	East/West Line	County
N	33	22S	34E	1000	South	1620	West	Lea

Latitude: 32.3436928 Longitude: -103.4783325

### NATURE OF RELEASE

Type of Release	Produced water	Volume of Release	310 BBLS	Volume Recovered	310 BBLS
Source of Release	Produced water storage tank	Date and Hour of Occurrence	6/4/2017 9:18@ pm	Date and Hour of Discovery	6/4/2017 9:18@ pm
Was Immediate Notice Given?	<input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom?	BLM-Shelly Tucker OCD-Olivia Yu		
By Whom?	David Simmons, Assistant Production Foreman	Date and Hour	BLM - 8/29/2016 @ 11:48 pm OCD - 8/29/2016 @ 11:58 pm		
Was a Watercourse Reached?	<input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse	N/A		

If a Watercourse was Impacted, Describe Fully.\* N/A


#### Describe Cause of Problem and Remedial Action Taken.\*

Lightning struck a 500BBL fiberglass produced water tank causing it to catch fire and structurally compromising it. The wells were immediately shut in. The fire department assisted in extinguishing the fire. Approximately 310 BBLS of produced water was in the tank when lightning struck. A vacuum truck recovered approximately 310bbls produced water. All fluid stayed inside the earthen berm containment on location.

#### Describe Area Affected and Cleanup Action Taken.\*

The release was contained within the earthen berm on the facility. Confirmation soil samples were taken. The impacted area was vertically/horizontally delineated and remediated by Talon/LPE per NMOCD guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Michael Shoemaker	OIL CONSERVATION DIVISION		
Printed Name: Michael Shoemaker	Approved by Environmental Specialist: 		
Title: Environmental Professional	Approval Date: 9/5/2018	Expiration Date: xx/xx/xxxx	
E-mail Address: mike.shoemaker@dvn.com	Conditions of Approval:		Attached <input type="checkbox"/>
Date: 08/16/18 Phone: 575.746-5594	Like approval from BLM.		

\* Attach Additional Sheets If Necessary

1RP-4734