Submit 3 Copies To Appropriate District  Office  State of New Mexico  Office  Energy Minerals and New 1 P	Form C-103
District I Energy, Minerals and Natural Resources	May 27, 2004
1625 N. French Dr., Hobbs, NM 87240 S OCD District II OII CONSERVATION DIVISION	WELL API NO.
1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-36529
District III 1220 South St. Francis Dr.	5. Indicate Type of Lease
1301 W. Grand Ave., Artesia, NM 88210 District III 1000 Rio Brazos Rd., Aztec, NM 87419 16 District IV Santa Fe, NM 87505	STATE FEE X
1220 S. St. Francis Dr., Santa Fe, NM 87505	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS  (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	7. Lease Name or Unit Agreement Name:
1. Type of Well: Oil Well  Gas Well  Other	8. Well Number
2. Name of Operator	002
CIMAREX ENERGY CO. OF COLORADO ATTN: ZENO FARRIS	9. OGRID Number 162683
3. Address of Operator	10. Pool name or Wildcat
600 N. MARIENFELD, SUITE 600, MIDLAND, TEXAS 79701	SKACGS; GLORIETA, NORTHWEST
4. Well Location	I SNAGS; GLORIETA, NORTHWEST
Unit Letter h: 1850 feet from the NORTH line and Section 08 Township 20S Range 37E	NMPM County LEA
11. Elevation (Show whether DR, RKB, RT, GR, et	(c.)
3,550' - CR  Pit or Below-grade Tank Application □ or Closure □	
1.	
Pit type STEEL Depth to Groundwater Distance from nearest fresh water well * Distance from nearest surface water *	
Pit Liner Thickness: mil Below-Grade Tank: Volumebbk; Construction	on Material * NONE WITHIN 1,000'.
12. Check Appropriate Box to Indicate Nature of Notice,  NOTICE OF INTENTION TO:  PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK  TEMPORARILY ABANDON CHANGE PLANS COMMENCE DRILLI	SEQUENT REPORT OF:  ALTERING CASING
DILL OR ALTER CARRIE .	ABANDONMENT
OTHER: OTHER: OTHER:	Pivatic
12 Describe proposed on a value of the control of t	to the Division
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give of starting any proposed work). SEE RULE 1103. For Multiple Completions: Attach or recompletion.  PROPOSED PROCEDURE FOR PLUG AND ABANDOMENT:	ABANDONMENT  Protion Division Must be notified wellbo.  CIPC WELL M/ EXAME
PROTOCOLO PROCEDE POR PLOG AND ABANDOMENT:	, refations
2) PUMP A 25 SX. CMT. PLUG @ 3,861'-3,661'(T/S.A.); WCC X TAG CMT. PLUG.  3) PUMP A 25 SX. CMT. PLUG @ 3,293'-3,093'(T/QN.); PUMP A 25 SX. CMT. PLUG @ 2,616'-2,416'(T/YATES).  4) PUMP A 25 SX. CMT. PLUG @ 1,215'-1,015'(8-5/8"CSG.SHOE X T/SALT); WCC X TAG CMT. PLUG.  5) MIX X CIRC. TO SURF. A 10 SX. CMT. PLUG @ 63'-3'.  6) DIG CUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASINGS X INSTALL DRY HOLE MARKER.	
4) PUMP A 25 SX. CMT. PLUG @ 1,215'-1,015'(8-5/8"CSG.SHOE X T/SALT); T 5) MIX X CIRC. TO SURF. A 10 SX. CMT. PLUG @ 63'-3'. 6) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASING	PLUG @ 2,616'-2,416'(T/YATES). WOC X TAG CMT. PLUG. SS X INSTALL DRY HOLE MARKER.
<ul> <li>4) PUMP A 25 SX. CMT. PLUG @ 1,215'-1,015' (8-5/8"CSG.SHOE X T/SALT); v</li> <li>5) MIX X CIRC. TO SURF. A 10 SX. CMT. PLUG @ 63'-3'.</li> <li>6) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASING hereby certify that the information above is true and complete to the best of my knowledge.</li> </ul>	PLUG @ 2,616'-2,416' (T/YATES).  WOC X TAG CMT. PLUG.  SS X INSTALL DRY HOLE MARKER.
4) PUMP A 25 SX. CMT. PLUG @ 1,215'-1,015'(8-5/8"CSG.SHOE X T/SALT); T 5) MIX X CIRC. TO SURF. A 10 SX. CMT. PLUG @ 63'-3'. 6) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASING	PLUG @ 2,616'-2,416' (T/YATES).  WCC X TAG CMT. PLUG.  SS X INSTALL DRY HOLE MARKER.  e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
4) PUMP A 25 SX. CMT. PLUG @ 1,215'-1,015' (8-5/8"CSG. SHOE X T/SALT); v 5) MIX X CIRC. TO SURF. A 10 SX. CMT. PLUG @ 63'-3'. 6) DIG OUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASING hereby certify that the information above is true and complete to the best of my knowledge tank has been will be constructed or closed according to NMOCD guidelines X, a general permit SIGNATURE	PIUG @ 2,616'-2,416' (T/YATES).  WOC X TAG OMT. PIUG.  SS X INSTALL DRY HOLE MARKER.  e and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan
4) PUMP A 25 SX. CMT. PLUG @ 1,215'-1,015' (8-5/8"CSG. SHOE X T/SALT); v 5) MIX X CIRC. TO SURF. A 10 SX. CMT. PLUG @ 63'-3'. 6) DIG CUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASING thereby certify that the information above is true and complete to the best of my knowledge tank has been will be constructed or closed according to NMOCD guidelines X, a general permit of SIGNATURE  E-mail address:  Grype or print name DAVID A. EYLER	PIUG @ 2,616'-2,416' (T/YATES).  WCC X TAG CMT. PIUG.  S X INSTALL DRY HOLE MARKER.  e and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan  DATE
4) PUMP A 25 SX. CMT. PLUG @ 1,215'-1,015' (8-5/8"CSG. SHOE X T/SALT); v 5) MIX X CIRC. TO SURF. A 10 SX. CMT. PLUG @ 63'-3'. 6) DIG CUT X CUT OFF WELLHEAD 3' B.G.L.; WELD ON STEEL PLATE TO CASING thereby certify that the information above is true and complete to the best of my knowledge tank has been will be constructed or closed according to NMOCD guidelines X, a general permit of SIGNATURE  E-mail address:  Grype or print name DAVID A. EYLER	PLUG @ 2,616'-2,416' (T/YATES).  WCC X TAG CMT. PLUG.  SS X INSTALL DRY HOLE MARKER.  e and belief. I further certify that any pit or below— or an (attached) alternative OCD-approved plan  DATE 02/14/12  eyler@milagro-res.com

