Submit 3 Copies To Appropriate District Office State of New Mexico	Form C-103
<u>District I</u> Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240	WELL API NO.
District II 1301 W. Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION	30-025-237 // 5. Indicate Type of Lease
District III 1220 South St. Francis Dr. 1000 Rio Brazos Rd., Aztec, NM 87410	STATE FEE 🗸
District IV 1220 S. St. Francis Dr., Santa Fe, NM 2750 Santa Fe, NM 2750 Santa Fe, NM	6. State Oil & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH	Kingwood
PROPOSALS.) 1. Type of Well:	8. Well Number
Oil Well Gas Well Other	1
2. Name of Operator Chevron USA Inc	9. OGRID Number
3. Address of Operator	10. Pool name or Wildcat
15 Smith Rd, Midland, TX 79705 4. Well Location	Paddock
	1
. Not non the min take	1650 feet from the East line
Section 25 Township 21-S Range 36-E NMPM Lea County 11. Elevation (Show whether DR, RKB, RT, GR, etc.)	
Pit or Below-grade Tank Application (For pit or below-grade tank closures, a form C-144 must be attached) Pit Location: UL J Sect 25 Twp 21S Rng 36E Pit type Steel Depth to Groundwater 148 Distance from nearest fresh water well Over 1000'	
Distance from nearest surface water Below-grade Tank Location UL Sect Twp Rng ;	
1780 feet from the South line and 1650 feet from the East line (Steel Tank)	
12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data 323031-723	
NOTICE OF INTENTION TO: SUB- PERFORM REMEDIAL WORK PLUG AND ABANDON REMEDIAL WORK	SEQUENTREPORTOR. S
TEMPORARILY ABANDON	LLING OPNS. PLUG AND FEEL STATES
PULL OR ALTER CASING	ID
OTHER: OTHER:	The same of the sa
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date	
of starting any proposed work). SEE RULE 1103. For Multiple Completions: At or recompletion.	each wellbore diagram of proposed completion
1. Notify OCD 24 hrs prior to MI and RU. 2. RIH Tag CIBP @5100, , spot 25sx, plug 5100-4900(Paddock)WOC Tag. 8. Perf 8 5/8 @ 375 sqz 75sx plug 375-250 (12 3/4 Shoe) WOC Tag. 9. 10sx Surf, Install Dry Hole Marker.	
3. Displace hole w/MLF, 9.5# Brine w/25# gel P/BBL. 4. Perf 4 holes @ 4100 sqz 50sx, plug 4100-3900 (S.Andres)WOC Tag.	Dry noie marker.
5. Cut 5 1/2 CSG @ 2800, L/D CSG.	
 Spot 90sx plug 2850-2600 (8 5/8 Shoe Stub) WOC Tag. Perf 8 5/8 @ 1250, sqz 90sx plug 1250-1100 (T-Salt) WOC Tag. 	
I hereby certify that the information above is true and complete to the best of my knowledge and belief. I further certify that any pit or below-grade tank has been/will be constructed or closed according to NMOCD guidelines , a general permit or an (attached) alternative OCD-approved plan.	
SIGNATURE TITLE Consultar	DATE 4/20/05
Type or print name	Telephone No. 432-561-8600
(This space for State use) White Illuly and the state use	
Chris Williams	District Supervisor
APPPROVED BY / / / / TITLE	

THE OIL CONSERVATION DIVISION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS.

