Submit 3 Copies To Appropriate District Office	State of New Me		Form C-103
District I	Energy, Minerals and Natu	ral Resources	May 27, 2004 WELL API NO.
1625 N. French Dr., Hobbs, NM 88240 District II	OH CONGERNATION	DIMIGION	30.025.27954
1301 W. Grand Ave., Artesia, NM 88210	Grand Ave., Artesia, NM 88210 OIL CONSERVATION DIVISION		5. Indicate Type of Lease
<u>District III</u> 1000 Rio Brazos Rd., Aztec, NM 87410			STA TE XX FEE 🔽
<u>District IV</u> 1220 S. St. Francis Dr., Santa Fe, NM	Santa Fe, NM 87	/505	6. State Oil & Gas Lease No.
87505			
	CES AND REPORTS ON WELLS		7. Lease Name or Unit Agreement Name
(DO NOT USE THIS FORM FOR PROPOSE DIFFERENT RESERVOIR. USE "APPLICATION"	ALS TO DRILL OR TO DEEPEN OR PL ATION FOR PERMIT" (FORM C-101) FO	UG BACK TO A OR SUCH	Mae F. Curry
PROPOSALS.) 1. Type of Well: Oil Well XX	Gas Well Other		8. Well Number
2. Name of Operator	Gas Wolf Galler		9. OGRID Number
BP America Production Company			000778
3. Address of Operator			10. Pool name or Wildcat
P.O. Box 1089, Eunice, NM 88231			Eunice Monument Grbg SA
4. Well Location Unit Letter A:	330 feet from the N	line and 660	feet from the E line
Section 7		inie and000 Range 37E	NMPM Lea County
Section /	11. Elevation (Show whether DR)		
	3526' GR	, 1012, 111, 011, 010.)	
Pit or Below-grade Tank Application or	Closure 🗌		
Pit typeSteelDepth to Groun	dwater73'Distance from nearest for	resh water well2640'_	Distance from nearest surface water_> 1000'_
Pit Liner Thickness: mil	Below-Grade Tank: Volume	bbls; Co	nstruction Material
12. Check A	ppropriate Box to Indicate N	ature of Notice,	Report or Other Data
NOTICE OF INT			
NOTICE OF INT PERFORM REMEDIAL WORK ☐			SEQUENT REPORT OF:
TEMPORARILY ABANDON	PLUG AND ABANDON XX CHANGE PLANS	REMEDIAL WORK COMMENCE DRIE	
PULL OR ALTER CASING	MULTIPLE COMPL	CASING/CEMENT	
			
OTHER:		OTHER:	
OTHER: 13. Describe proposed or complete of starting any proposed work.	eted operations. (Clearly state all	OTHER: pertinent details, and	give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete	eted operations. (Clearly state all	OTHER: pertinent details, and	give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work.	eted operations. (Clearly state all	OTHER: pertinent details, and	give pertinent dates, including estimated date
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion.	eted operations. (Clearly state all k). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: Att	give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work.	eted operations. (Clearly state all k). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: Att	give pertinent dates, including estimated date ach wellbore diagram of proposed completion
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS.	eted operations. (Clearly state all pk). SEE RULE 1103. For Multip	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259'
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @	eted operations. (Clearly state all pk). SEE RULE 1103. For Multip S: 3656-3802' CEMENTED NE	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259'
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH	eted operations. (Clearly state all plants). SEE RULE 1103. For Multiples: 3656-3802' CEMENTED NE	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259'
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @	eted operations. (Clearly state all place). SEE RULE 1103. For Multiples: 3656-3802' CEMENTED NE 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE. WOC & TAG. (BE SURE CM'	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL T TOP IS @ 3526')	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259'
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR	eted operations. (Clearly state all pk). SEE RULE 1103. For Multipks: 3656-3802' CEMENTED NEW 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE . WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & 1000 control of the c	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL T TOP IS @ 3526')	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259'
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU.	eted operations. (Clearly state all pk). SEE RULE 1103. For Multipks: 3656-3802' CEMENTED NEW 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE . WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & 1000 control of the c	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL T TOP IS @ 3526')	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259' T GEL W/12.5#PER BBE
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS	eted operations. (Clearly state all pk). SEE RULE 1103. For Multipks: 3656-3802' CEMENTED NEW 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE. WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & F. POH LOAD CSG TO SURF.	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL T TOP IS @ 3526') RECORD.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259° T GEL W/12.5#PER BBE
OTHER: 13. Describe proposed or complete of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU.	eted operations. (Clearly state all plan). SEE RULE 1103. For Multiples: 3656-3802' CEMENTED NEW 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE. WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & TAG. POH LOAD CSG TO SURF.	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL I TOP IS @ 3526') RECORD.	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259. T GEL W/12.5#PER BBE
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS	eted operations. (Clearly state all pk). SEE RULE 1103. For Multip S: 3656-3802' CEMENTED NEW TBG TO 3980'. DISPLACE WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & THE OIL BE NO	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL T TOP IS @ 3526') RECORD. CONSERVAT	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259° T GEL W/12.5#/PER BBE
OTHER: 13. Describe proposed or completed of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS	eted operations. (Clearly state all pk). SEE RULE 1103. For Multip S: 3656-3802' CEMENTED NEW TBG TO 3980'. DISPLACE WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & THE OIL BE NO	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL T TOP IS @ 3526') RECORD. CONSERVAT	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259. T GEL W/12.5#PER BBE
OTHER: 13. Describe proposed or completion of starting any proposed work or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS INSTALL PA MARKER	eted operations. (Clearly state all pk). SEE RULE 1103. For Multipks: 3656-3802' CEMENTED NEW 13982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & THE OIL BE NO BEGINN	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL T TOP IS @ 3526') RECORD. CONSERVAT TIFIED 24 HOL ING OF PLUG	I give pertinent dates, including estimated date ach wellbore diagram of proposed completion as a second se
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS INSTALL PA MARKER	eted operations. (Clearly state all pk). SEE RULE 1103. For Multip S: 3656-3802' CEMENTED NEW 13982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & THE OIL BE NO BEGINN	OTHER: Descripent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL IT TOP IS @ 3526') RECORD. CONSERVAT TIFIED 24 HOL LING OF PLUG	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259. T GEL W/12.5#PER BBE 100 THE
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS INSTALL PA MARKER I hereby certify that the information at grade tank has been with the constructed or grade tank has been with the constructed	eted operations. (Clearly state all place) S: 3656-3802' CEMENTED NE 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE WOC & TAG. (BE SURE CM' OSS SALT TOP. WOC, TAG & F. POH LOAD CSG TO SURF. THE OIL BE NO BEGINN bove is true and complete to the belosed according to NMOCD guidelines [OTHER: Dertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL I TOP IS @ 3526') RECORD. CONSERVAT TIFIED 24 HOUSING OF PLUG est of my knowledge , a general permit	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259. T GEL W/12.5#PER BBE TO THE IRS PRIOR TO THE GING OPERATIONS. and belief. I further certify that any pit or belower an (attached) alternative OCD-approved plan
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS INSTALL PA MARKER	eted operations. (Clearly state all plants) seek. SEE RULE 1103. For Multiples: 3656-3802' CEMENTED NEW 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & F. POH LOAD CSG TO SURF. THE OIL BE NO BEGINN Dove is true and complete to the belosed according to NMOCD guidelines [ITLE]	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL I TOP IS @ 3526') RECORD. CONSERVAT TIFIED 24 HOUSING OF PLUG est of my knowledge , a general permit [] of Scheduler	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259. T GEL W/12.5#PER BBE STOTAL STO
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS INSTALL PA MARKER I hereby certify that the information a grade tank has been will be constructed or constru	eted operations. (Clearly state all plants) seek. SEE RULE 1103. For Multiples: 3656-3802' CEMENTED NEW 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & F. POH LOAD CSG TO SURF. THE OIL BE NO BEGINN Dove is true and complete to the belosed according to NMOCD guidelines [ITLE]	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL I TOP IS @ 3526') RECORD. CONSERVAT TIFIED 24 HOUSING OF PLUG est of my knowledge , a general permit [] of Scheduler	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259. T GEL W/12.5#PER BBE STOTAL STO
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS INSTALL PA MARKER I hereby certify that the information at grade tank has been with be constructed or a SIGNATURE.	eted operations. (Clearly state all plants) seek. SEE RULE 1103. For Multiples: 3656-3802' CEMENTED NEW 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & F. POH LOAD CSG TO SURF. THE OIL BE NO BEGINN Dove is true and complete to the belosed according to NMOCD guidelines [ITLE]	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL I TOP IS @ 3526') RECORD. CONSERVAT TIFIED 24 HOUSING OF PLUG est of my knowledge , a general permit [] of Scheduler	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259. T GEL W/12.5#PER BBE STOTAL STO
OTHER: 13. Describe proposed or completion of starting any proposed wor or recompletion. TD: 4500' PBD: 4450' OLD PERFORMIRUPU. LD PMP & RODS. POH W/TBG. RUWL. SET CIBP @ LOAD CSG & TEST TO 500#. RIH SPOT 25 SXS CMT. PULL ABOVE PUH TO 1380'. SPOT 25 SXS ACREPUH TO 500'. SPOT CMT TO SUR RDPU. CUT OFF WH & ANCHORS INSTALL PA MARKER I hereby certify that the information a grade tank has been will be constructed or constru	eted operations. (Clearly state all plants) seek. SEE RULE 1103. For Multiples: 3656-3802' CEMENTED NEW 3982'. DUMP 35' CMT W/BAI W/TBG TO 3980'. DISPLACE WOC & TAG. (BE SURE CM'OSS SALT TOP. WOC, TAG & F. POH LOAD CSG TO SURF. THE OIL BE NO BEGINN Dove is true and complete to the belosed according to NMOCD guidelines [ITLE]	OTHER: pertinent details, and le Completions: Att W PERFS: 4032-42 LER. RDWL. HOLE W/9.6# SAL I TOP IS @ 3526') RECORD. CONSERVAT TIFIED 24 HOUSING OF PLUG est of my knowledge , a general permit [] of Scheduler	give pertinent dates, including estimated date ach wellbore diagram of proposed completion 259. T GEL W/12.5#PER BBEO ION DIVISION THE IRS PRIOR TO THE GING OPERATIONS. and belief. I further certify that any pit or below- or an (attached) alternative OCD-approved plan DATE 04.27.05

control -


WELLBORE SCHEMATIC

32**4**

25 SX AT SURFACE

5 1/2" TOC CIRC. TO SURFACE

8-5/8" casing @ 440' CIRCULATED TO SURFACE



MAE F. CURRY # 2 UL A, 330' FNL & 660' FEL SECTION 7 - T21S -R 37E LEA COUNTY NEW MEXICO API 30-025-27954 GR 3526' KB: 10'

25 SX ACROSS TOP OF SALT 1380'

50' ABOVE LINER TOP

3 1/2" X 9.3# LINER TOP OF LINER @ 3676' TOC 3698'