

Submit 1 Copy To Appropriate District Office

District I - (575) 393-6161
1625 N. French Dr., Hobbs, NM 88240
District II - (575) 748-1283
811 S. First St., Artesia, NM 88210
District III - (505) 334-6178
1000 Rio Brazos Rd., Aztec, NM 87410
District IV - (505) 476-3460
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy, Minerals and Natural Resources

OIL CONSERVATION DIVISION
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-103
October 13, 2009

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)		WELL API NO. 30-025-20227
1. Type of Well: Oil Well ☒ Gas Well ☐ Other ☐		5. Indicate Type of Lease STATE ☒ FEE ☐
2. Name of Operator CrownQuest Operating, LLC		6. State Oil & Gas Lease No. B-9505
3. Address of Operator P.O. Box 53310, Midland, TX 79710		7. Lease Name or Unit Agreement Name New Mexico AT State
4. Well Location Unit Letter F : 1980 feet from the N line and 1980 feet from the W line Section 15 Township 14S Range 33E NMPM County Lea		8. Well Number 6
11. Elevation (Show whether DR, RKB, RT, GR, etc.) 4208 GR		9. OGRID Number 213190
		10. Pool name or Wildcat Saunders Permo Upper Penn

12. Check Appropriate Box to Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:
PERFORM REMEDIAL WORK ☐ PLUG AND ABANDON ☒
TEMPORARILY ABANDON ☐ CHANGE PLANS ☐
PULL OR ALTER CASING ☐ MULTIPLE COMPL ☐
DOWNHOLE COMMINGLE ☐

SUBSEQUENT F
REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING/CEMENT JOB ☐

INT TO PA **Pmx**
P&A NR _____
P&A R _____

OTHER: ☐

OTHER: _____

13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of proposed completion or recompletion.

- 25 1. Set 4 1/2 CIBP @ 9310'. Circulate hole w/ MLF. Pressure test csg. Spot 20 sx cmt @ 9310-9210'.
2. Spot 20 sx cmt @ 7000-6900'.
3. Set 4 1/2 CIBP @ 4650'. Circulate hole w/ MLF. Pressure test csg. Spot 20 sx cmt @ 4650-4550'.
4. Spot 30 sx cmt @ 4190-3919'. WOC & Tag (Shoe, Stub, San Andres)
5. Spot 35 sx cmt @ 2600-2500'. (Yates, Btm of Salt)
6. Spot 25 sx cmt @ 1800-1700. WOC & Tag (T/Salt)
7. Spot 90 sx cmt @ 416' Surface. PERF @ 416' ATTEMPT TO SQZ W/ 50 SX WOC & TAG
8. Cut off wellhead, verify cmt to surface, weld on Dry Hole Marker. PERF @ 100'. CIRC TO SURFACE

25 sx MIN.

Spud Date:

NOTIFY OCD 24 HOURS PRIOR TO
BEGINNING PLUGGING OPERATIONS

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Abigail Montgomery TITLE Agent DATE 2-23-17
Type or print name Abigail Montgomery E-mail address: abbym@bcmmandassociates.com PHONE: 432-580-7161
For State Use Only
APPROVED BY: Mark Whitaker TITLE Petroleum Engr. Specialist DATE 02/23/2017
Conditions of Approval (if any):

Wellbore Schematic (From Surface to TD)

Printed: 2/21/2017

Page 1



