State of New Mexico Energy, Minerals and Natural Resources Department

Form C-103 Revised 5-27-2004

	OIL CONSERVAT	ION DIVISION		
DISTRICT I 1625 N French Dr , Hobbs, NM 88240	1220 South St.	Francis Dr.	WELL API NO 30-025-37480	
DISTRICT II	OCT 18 2010	1 0/303	5 Indicate Type of Lease	
DISTRICT II 1301 W Grand Ave, Artesia, NM 88210 DISTRICT III	t to zuiu		STATE X	FEE
<u>DISTRICT III</u>	HOBBSOCO	Ī	6 State Oil & Gas Lease No	•
1000 Rio Brazos Rd, Aztec, NM 87410				
SUNDRY	NOTICES AND REPORTS ON WELLS	S	7 Lease Name or Unit Agreeme	ent Name
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A			North Hobbs (G/SA) Unit	/
	E "APPLICATION FOR PERMIT" (Form C-101)	for such proposals)	Section 25	
Type of Well Oil Well	Gas Well Other Inject	or	8 Well No 741	/
2 Name of Operator			9. OGRID No 157984	
Occidental Permian Ltd. 3. Address of Operator			10 Pool name or Wildcat	Hobbs (G/SA)
HCR 1 Box 90 Denver City	TX 79323		10 Tool hame of windcat	HOUUS (G/SA)
4 Well Location	111 17525			
Unit Letter A 360	Feet From The North	1294 Feet	From The East	Line
Section 25	Township 18-S	Range 37-E	NMPM	Lea County
	11 Elevation (Show whether DF, RKB, I 3677' GL	RT GR, etc)		
Pit or Below-grade Tank Applicatio	or Closure			
Pit Type Depth of Ground Water Distance from nearest fresh water well Distance from nearest surface water				
Pit Liner Thickness mi				
12. C	heck Appropriate Box to Indicate Nature	e of Notice, Report, or Ot	her Data	
	NTENTION TO:		EQUENT REPORT OF	:
PERFORM REMEDIAL WORK] PLUG AND ABANDON [RI	EMEDIAL WORK	ALTERING	CASING
,	¬ —	OMMENCE DRILLING ORNI		
TEMPORARILY ABANDON	_ CHANGE PLANS C	OMMENCE DRILLING OPN	S PLUG&AE	BANDONMENT
		ASING TEST AND CEMENT		BANDONMENI []
PULL OR ALTER CASING	Multiple Completion C			BANDONMENT
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre	Multiple Completion Coat X O	ASING TEST AND CEMENT THER:	JOB	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed	Multiple Completion Coat X O	ASING TEST AND CEMENT THER: Is, and give pertinent dates,	JOB	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1	Multiple Completion Compate X O' Operations (Clearly state all pertinent detail 03. For Multiple Completions: Attach wellby	ASING TEST AND CEMENT THER: Is, and give pertinent dates,	JOB	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed	Multiple Completion Compate X O' O' Operations (Clearly state all pertinent detail 03. For Multiple Completions: Attach wellbe quipment.	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co	including estimated date of stampletion or recompletion.	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection e 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs.	Multiple Completion	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify O	including estimated date of stampletion or recompletion. CD Hobbs	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection et 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze.	Multiple Completion	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co	including estimated date of stampletion or recompletion. CD Hobbs	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection et 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1	Multiple Completion Completion X O' Operations (Clearly state all pertinent detail 03. For Multiple Completions: Attach well be quipment. Condition office 24 h	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify Onours prior to running	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection et 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers.	Multiple Completion	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify Onours prior to running	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart of Program Manual	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection e 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N	Multiple Completion	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify O nours prior to running ground Injection Contro ter shall be set within to	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart DI Program Manual or less then 100 feet	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection et 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers.	Multiple Completion	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify Onours prior to running	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart DI Program Manual or less then 100 feet	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection e 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N	Multiple Completion	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify O nours prior to running ground Injection Contro ter shall be set within to	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart DI Program Manual or less then 100 feet	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection e 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N	Multiple Completion	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify O nours prior to running ground Injection Contro ter shall be set within to	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart DI Program Manual or less then 100 feet	
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection e 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N 9. Return well to injection.	Multiple Completion	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify O nours prior to running ground Injection Contro eer shall be set within co ermost injection perfs of	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart of Program Manual or less then 100 feet or open hole.	arting any .
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection et 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N. 9. Return well to injection.	Multiple Completion At Condition O' O' O' O' O' O' O' O' O' O	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify Onours prior to running ground Injection Contro eer shall be set within co ermost injection perfs of	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart DI Program Manual or less then 100 feet or open hole.	arting any .
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection e 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N 9. Return well to injection.	Multiple Completion X O at X O O O O O O O O O O O O O	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co- of Approval: Notify Onours prior to running ground Injection Controver shall be set within commost injection perfs of the set of the set within the commost injection perfs of the set of the set within th	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart DI Program Manual or less then 100 feet or open hole.	arting any .
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection et 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N. 9. Return well to injection.	Multiple Completion At At Conditions Conditions Sow NEFE HCL acid. Per Underguiper Il 6 c Pack of the upper The strue and complete to the best of my knowledguiper Il 6 c Pack of the upper Il	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co- of Approval: Notify Onours prior to running ground Injection Controver shall be set within the proposed injection perfs of the proposed injection and the polan of the polan injection and the polan injection in the polan injection inject	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart or Program Manual or less then 100 feet or open hole.	arting any
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection e 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N 9. Return well to injection. I hereby certify that the information above constructed or closed according to NMOCD guidel SIGNATURE	Multiple Completion At At Condition Office 24 h Solution Office 24 h MOCD. At at A per Undergood of the upper It is true and complete to the best of my knowledgen in the completion of the upper A general permit	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co- of Approval: Notify Onours prior to running ground Injection Controver shall be set within the cermost injection perfs of the and belief. I further certify the or an (attached) alternative plan TITLE Administrative A	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart or Program Manual or less then 100 feet or open hole.	arting any s been/will be 10/14/2010
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection et 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N 9. Return well to injection. Thereby certify that the information above constructed or closed according to NMOCD guidel SIGNATURE TYPE OR PRINT NAME Mendy	Multiple Completion At At Condition Office 24 h Solution Office 24 h MOCD. At at Condition Office 24 h Per Underguish of the upper It is true and complete to the best of my knowledgen of the upper A general permit	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co- of Approval: Notify Onours prior to running ground Injection Controver shall be set within the proposed injection perfs of the proposed injection and the polan of the polan injection and the polan injection in the polan injection inject	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart DI Program Manual or less then 100 feet or open hole. at any pit or below-grade tank ha OCD-approved DATE	arting any
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection et 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 1 6. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N 9. Return well to injection. I hereby certify that the information abore constructed or closed according to NMOCD guidel SIGNATURE TYPE OR PRINT NAME Mendy For State Use Only	Multiple Completion At At Condition Office 24 h Office 25 h Office 26 h Office 26 h Office 26 h Office 26 h Office 27 h Office 27 h Office 26 h Office 26 h Office 27 h Office 28 h Office 29 h Office 29 h Office 20 h Offi	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co- of Approval: Notify Onours prior to running ground Injection Controver shall be set within the cermost injection perfs of the control of the cermost injection perfs of the cermost injection per	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart of Program Manual or less then 100 feet or open hole. at any pit or below-grade tank ha OCD-approved associate DATE TELEPHONE NO.	arting any s been/will be 10/14/2010 806-592-6280
PULL OR ALTER CASING OTHER: Squeeze perf/Acid tre 13. Describe Proposed or Completed proposed work) SEE RULE 1 1. Kill well. POOH w/injection et 2. Clean out to 4230'. 3. Set CIBP and squeeze perfs. 4. Test squeeze. 5. Acid treat well w/1500 gal of 16. Perform scale squeeze. 7. RIH w/dual injection packers. 8. Test casing and chart for the N 19. Return well to injection. Thereby certify that the information above constructed or closed according to NMOCD guidel SIGNATURE TYPE OR PRINT NAME Mendy	Multiple Completion At At Condition Office 24 h Office 25 h Office 26 h Office 26 h Office 26 h Office 26 h Office 27 h Office 27 h Office 26 h Office 26 h Office 27 h Office 28 h Office 29 h Office 29 h Office 20 h Offi	ASING TEST AND CEMENT THER: Is, and give pertinent dates, pore diagram of proposed co of Approval: Notify Onours prior to running ground Injection Controver shall be set within the certification perfs of the control of the certification of	including estimated date of stampletion or recompletion. CD Hobbs MIT Test & Chart of Program Manual or less then 100 feet or open hole. at any pit or below-grade tank ha OCD-approved associate DATE TELEPHONE NO.	arting any s been/will be 10/14/2010