

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION, C.

AUG 7 10 51 AM '68

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease State <input type="checkbox"/> Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.
7. Unit Agreement Name
8. Farm or Lease Name Santa Fe Pacific
9. Well No. 3
10. Field and Pool, or Wildcat Crossroads Siluro Devonian
12. County Lea

**SUNDRY NOTICES AND REPORTS ON WELLS**  
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL ☒ GAS WELL ☐ OTHER ☐

2. Name of Operator  
Mobil Oil Corporation

3. Address of Operator  
P. O. Box 633, Midland, Texas 79701

4. Location of Well  
UNIT LETTER M 660 FEET FROM THE West LINE AND 660 FEET FROM  
THE South LINE, SECTION 26 TOWNSHIP 9-S RANGE 36-E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input checked="" type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Run a casing scraper and clean out the well to TD of 12,263'.
- Run a Gamma Ray-Neutron Log from TD through the minimum logging interval.
- Squeeze the Devonian open hole section (12,240' - 12,263' -23') with Trinity Inferno neat cement. Attempt to obtain a PBTD of approximately 12,235'.
- Spot 500 gals of 15%, non-emulsion, HCl acid in the bottom of the well. Perforate the Devonian formation with 2 jet shots per foot over the intervals selected from the log. Perforating should be done using a 5" retrievable gun with charges capable of obtaining a minimum hole size of 0.5" and a minimum penetration of 8.0", based on standard testing procedures.
- Acidize the Devonian perforations with 1,000 gals of 15%, non-emulsion, HCl acid. Treat at 3 to 5 bbls/min.
- Swab, clean up, and test the well.
- Return the well to production.

8. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>W. A. Mills</u>	TITLE <u>Authorized Agent</u>	DATE <u>8-5-68</u>
APPROVED BY <u>John W. Rungar</u>	TITLE	DATE
CONDITIONS OF APPROVAL, IF ANY:		