

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-		7. Unit Agreement Name
2. Name of Operator Great Western Drilling Company		8. Farm or Lease Name ODC "C"
3. Address of Operator P. O. Box 1659 Midland, Texas		9. Well No. 1
4. Location of Well UNIT LETTER P 660 FEET FROM THE East LINE AND 660 FEET FROM THE South LINE, SECTION 5 TOWNSHIP 9-S RANGE 37-E NMPM.		10. Field and Pool, or Wildcat Allison-Pennsylvanian
15. Elevation (Show whether DF, RT, GR, etc.) 4023 GR		12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

The hole will be loaded with 10 # mud. The pay zone 9662 - 9666 will be covered with a 25 sack plug 9700 to 9575'. We plan to cut and pull 6000' of 4 1/2". A 25 sack plug will be placed @ 5500', 25 sacks @ 4160 (shoe of 7 5/8). This 7 5/8" will be cut and pulled at some 600'. A 25 sack plug will be placed in the stub, 25 sacks in the shoe of the 10 3/4 @ 276' and 10 sacks @ surface.

A cleanup and marker will be made.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED O. H. Crews TITLE Administrative Coordinator DATE June 2, 1965

APPROVED BY [Signature]
CONDITIONS OF APPROVAL, IF ANY:

TITLE [Signature] DATE [Signature]