

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
<b>00-1506</b>

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator <b>AZTEC OIL &amp; GAS COMPANY</b>	8. Farm or Lease Name <b>STATE "S"</b>
3. Address of Operator <b>P. O. BOX 837, HOBBS, NEW MEXICO 88240</b>	9. Well No. <b>1</b>
4. Location of Well UNIT LETTER <b>F</b> <b>1980</b> FEET FROM THE <b>North</b> LINE AND <b>1980</b> FEET FROM THE <b>West</b> LINE, SECTION <b>32</b> TOWNSHIP <b>9-S</b> RANGE <b>38-E</b> NMMP.	10. Field and Pool, or Wildcat <b>Sawyer-San Andres Gas</b>
15. Elevation (Show whether DF, RT, GR, etc.) <b>3948 KB</b>	12. County <b>Lea</b>

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to Plug & Abandon this well in the following manner:

1. Set 100' cement plug over perforations at T.D.
2. Set 100' cement plug at Top Salt either inside casing or open hole if casing pulled.
3. Set 100' cement plug at shoe of Surface Casing.
4. Set 10 sxs. cement plug at Surface with Dry Hole Marker.
5. Level and clear location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

original signed by  
LESTER L. DUKE

SIGNED \_\_\_\_\_ TITLE District Superintendent DATE December 6, 1972

APPROVED BY Joe D. Ramey DATE DEC 8 1972  
CONDITIONS OF APPROVAL, IF ANY: Dist. I, Supv.