## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

liebas office occ

## MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A copy will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Dommission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

## Indicate Nature of Notice by Checking Below

N'					
Notice of Intention to Change Plans		Notice of Intention to Temporarily Abandon Well		Notice of Intention to Drill Deeper	
NOTICE OF INTENTION TO PLUG WELL		Notice of Intention to Pluo Bacx		Notice of Intention to Set Liner	
Notice of Intention to Squeeze	X	Notice of Intention to Acidize	x	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate	x	Notice of Intention (Other) See Below		Notice of Intention (Other)	
OIL CONSERVATION COMMIS SANTA FE, NEW MEXICO	SSION	TEXACO, Inc.,P.O. (Place)	Box 72	8, Hobbs. N. M. May 21 (Date)	. 1962
Gentlemen:					
Following is a Notice of Inten	tion to do	certain work as described below at	the Sta	te of New Mexico "BN" NC	r-1
(Company )	or Operator	)	******	Well No. 1 in	Unit)
<u>NN</u> 1/4 SM 1/4 of Sec	25	т. 11-S в 32-Е	NMPM	Moore (Wolfcemp)(Pe	nn) P
(40-acre Subdivision)		,, <u>-</u>		· · · · · · · · · · · · · · · · · · ·	1
Lea	Cou	inty.			
		ll we propose to do the	TOTTO	wrug:	
<ul> <li>Kill well with lease</li> <li>Pressure test 5-1/2" leak, with a retrievable</li> <li>8302' to 8345' and 8</li> <li>Set retrievable plug</li> <li>Sqz 5-1/2" csg perfs</li> <li>Drill out cement.</li> <li>Perf 5-1/2" csg from</li> <li>Acidize csg perfs fr</li> <li>Swab acid residue an</li> <li>Wash out sand and re</li> <li>Re-install tubing st</li> <li>Switch lower zone to</li> </ul>	crude csg f able B e BP a 234 t in Mo from 8234 t om 8234 d flow cover : ring, tubin er loa	oil. rom surface to approx. P and hookwall packer. nd hookwall packer, swa o 8260' to determine wa del D Packer and dump 5 8234' to 8345' with 200 to 8238', 8241' to 824 4' to 8260' with 1000 g upper zone to clean. retrievable plug. seal nipples, and Otis g and upper zone to ann d oil and return to pro	8200', b test ter so 0' san sx of 4', and als 15 Slidin ulus fo	to 100 psi to test for each perforated interval urce and producing capaci d on top. low water loss cement. d 8252: to 8260: with one freg acid. g Side Door. or production. Swab lower h.	l from ity.
<ul> <li>Kill well with lease</li> <li>Pressure test 5-1/2" leak, with a retrievabl 8302' to 83h5' and 8</li> <li>Set retrievable plug</li> <li>Sqz 5-1/2" csg perfs</li> <li>Drill out cement.</li> <li>Perf 5-1/2" csg from</li> <li>Acidize csg perfs fr</li> <li>Swab acid residue an</li> <li>Wash out sand and re</li> <li>Re-install tubing st</li> <li>Switch lower zone to</li> <li>Test each zone recov</li> </ul>	crude csg f able B e BP a 234 t in Mo from 8234 t om 8234 d flow cover : ring, tubin er loa	oil. rom surface to approx. P and hookwall packer. nd hookwall packer, swa o 8260' to determine wa del D Packer and dump 5 8234' to 8345' with 200 to 8238', 8241' to 824 4' to 8260' with 1000 g upper zone to clean. retrievable plug. seal nipples, and Otis g and upper zone to ann d oil and return to pro	8200', b test ter so 0' san 5x of 4', and als 15 Slidin ulus fo duction	to 100 psi to test for each perforated interva- urce and producing capaci- d on top. low water loss cement. d 8252: to 8260: with one for reg acid.	l from ity.
<ul> <li>Kill well with lease</li> <li>Pressure test 5-1/2" leak, with a retrievabl 8302' to 83h5' and 8</li> <li>Set retrievable plug</li> <li>Sqz 5-1/2" csg perfs</li> <li>Drill out cement.</li> <li>Perf 5-1/2" csg from</li> <li>Acidize csg perfs fr</li> <li>Swab acid residue an</li> <li>Wash out sand and re</li> <li>Re-install tubing st</li> <li>Switch lower zone to</li> <li>Test each zone recov</li> </ul>	crude csg f able B e BP a 234 t in Mo from 8234 t om 8234 d flow cover : ring, tubin er loa	oil. rom surface to approx. P and hookwall packer. nd hookwall packer, swa o 8260' to determine wa del D Packer and dump 5 8234' to 8345' with 200 to 8238', 8241' to 824 4' to 8260' with 1000 g upper zone to clean. retrievable plug. seal nipples, and Otis g and upper zone to ann d oil and return to pro 	8200', b test ter so 0' san sx of 4', and als 15' Slidin ulus fo duction ACO_In ASSIS	to 100 psi to test for each perforated interva- urce and producing capaci- d on top. low water loss cement. d 8252: to 8260: with one for reg acid.	l from ity. e JSPF. r zone.
<ul> <li>Kill well with lease</li> <li>Pressure test 5-1/2" leak, with a retrievabl 8302' to 83h5' and 8</li> <li>Set retrievable plug</li> <li>Sqz 5-1/2" csg perfs</li> <li>Drill out cement.</li> <li>Perf 5-1/2" csg from</li> <li>Acidize csg perfs fr</li> <li>Swab acid residue an</li> <li>Wash out sand and re</li> <li>Re-install tubing st</li> <li>Switch lower zone to</li> <li>Test each zone recov</li> </ul> Approved	crude csg f able B e BP a 234 t in Mo from 8234 t om 8234 d flow cover : ring, tubin er loa	oil. rom surface to approx. P and hookwall packer. nd hookwall packer, swa o 8260' to determine wa del D Packer and dump 5 8234' to 8345' with 200 to 8238', 8241' to 824 4' to 8260' with 1000 g upper zone to clean. retrievable plug. seal nipples, and Otis g and upper zone to ann d oil and return to pro 	8200', b test ter so 0' san sx of 4', and als 15 Slidin ulus fo ACO_Inc ASSIS Send	to 100 psi to test for each perforated interva- urce and producing capaci- d on top. low water loss cement. d 8252: to 8260: with one for g acid. g Side Door. or production. Swab lower h. Comprany or Operator	l from ity. e JSPF. r zone.
<ul> <li>Kill well with lease</li> <li>Pressure test 5-1/2" leak, with a retrievabl 8302' to 83h5' and 8</li> <li>Set retrievable plug Sqz 5-1/2" csg perfs</li> <li>Drill out cement.</li> <li>Perf 5-1/2" csg from Acidize csg perfs fr Swab acid residue an Wash out sand and re</li> <li>Re-install tubing st Switch lower zone to Test each zone recov</li> <li>Approved OIL CONSERVATION COMMIS</li> </ul>	crude csg f able B e BP a 234 t in Mo from 8234 t om 8234 d flow cover : ring, tubin er loa	oil. rom surface to approx. P and hookwall packer. nd hookwall packer, swa o 8260' to determine wa del D Packer and dump 5 8234' to 8345' with 200 to 8238', 8241' to 824 4' to 8260' with 1000 g upper zone to clean. retrievable plug. seal nipples, and Otis g and upper zone to ann d oil and return to pro 	8200', b test ter so 0' san sx of 4', and als 15 Slidin ulus fo duction ACO In ACO In Assis Send J. G. 1	to 100 psi to test for each perforated interval urce and producing capacid d on top. low water loss cement. d 8252: to 8260: with one for gracid. g Side Door. for production. Swab lower h. Company or Operator Manual tant District Superintene Communications regarding well to:	l from ity. e JSPF. r zone. dent