

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
E-8447

SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator A. F. Roberts, Jr.	8. Farm or Lease Name Gulf State
3. Address of Operator c/o Oil Reports & Gas Services, Inc., Box 763, Hobbs, New Mexico 88240	9. Well No. 3
4. Location of Well UNIT LETTER J 2130 FEET FROM THE South LINE AND 1980 FEET FROM THE East LINE, SECTION 18 TOWNSHIP 11S RANGE 34E N.M.P.M.	10. Field and Pool, or Wildcat Inbe Permo Penn
15. Elevation (Show whether DF, RT, GR, etc.) 4206 DF	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>
OTHER <input type="checkbox"/>	OTHER <input type="checkbox"/>
PLUG AND ABANDON <input checked="" type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
CHANGE PLANS <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work; SEE RULE 1103.

It is proposed to plug and abandon as follows:
Set cast iron bridge plug @ 9700 & cap with 35' cement
Cut & pull 5 1/2" casing from approx 8000
100' plug across 5 1/2" casing stub
100' plug at top of Abo at 7680
100' plug at top of Glorieta at 5400
100' plug across 8 5/8" casing shoe at 4020
Cut & pull 8 5/8" casing from approx 1500
(Note: top of Salt at 2085, base of Salt at 2440; if 8 5/8" casing
pulled from below these points a 100' plug at top of Salt and a 100'
plug at base of Salt)
100' plug across 8 5/8" casing stub
100' plug across 13 3/8" casing shoe at 433
10 sack plug at surface with regulation marker
Mud between all plugs

*74 hour notice to O.C.C. before setting
bottom plug*

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Wm. H. Hall TITLE Agent DATE 5/25/73

APPROVED BY John R. Runyon TITLE _____ DATE _____
CONDITIONS OF APPROVAL, IF ANY: