

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No. K-5060
7. Unit Agreement Name
8. Farm or Lease Name STATE "CZ"
9. Well No. 1
10. Field and Pool, or Wildcat WILDCAT
12. County LEA

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. <input checked="" type="checkbox"/> OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER-
2. Name of Operator Pan American Petroleum Corp.
3. Address of Operator Box 68, Hobbs, N.M. 88240
4. Location of Well UNIT LETTER L , 1980 FEET FROM THE SOUTH LINE AND 660 FEET FROM THE WEST LINE, SECTION 27 TOWNSHIP 9-S RANGE 35-E N.M.P.M. 15. Elevation (Show whether DF, RT, GR, etc.) 4138' R.D.B.

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Production declined to 380 x 20 BWPD. On an effort to increase productivity well was fraced w/ 11000 gal oil containing .82 #/gal. Cleaned and sand and reran pumping equipment. Tested for appx. 12 days. After workover, pumped 0.80 + 102 BW in 24 hours. Since there no longer exists a repair possibility, we propose to plug and abandon as follows:

Spot 25 54 cement plug across perforations 4825-62'. Cut and pull casing at free point, appx 4000'. (4 1/2" oil string)

Spot 50 54 cement plug in + out of 4 1/2" stub.

Spot 10 54 cement plug at surface and erect P&A marker.

Make final cleanup and restore ground to contour.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED	TITLE Area Supt	DATE 1-21-66
APPROVED BY 1-REY	TITLE	DATE

012-NMOCC-14
1-JWB
1-305D
CONDITIONS OF APPROVAL, IF ANY: