

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

# NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
OG 670	
7. Unit Agreement Name	
Flying "M" (SA) Unit Tr. 4	
8. Farm or Lease Name	
9. Well No.	
2	
10. Field and Pool, or Wildcat	
Flying "M" (SA)	
12. County	
Lea	

## SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT --" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <u>Water Injection Well</u>	
2. Name of Operator	
Coastal States Gas Producing Company	
3. Address of Operator	
P. O. Box 235, Midland, Texas 79701	
4. Location of Well	
UNIT LETTER <u>J</u> , <u>1980</u> FEET FROM THE <u>south</u> LINE AND <u>1980</u> FEET FROM <u>east</u> LINE, SECTION <u>17</u> TOWNSHIP <u>9-S</u> RANGE <u>33-E</u> NMPM.	
15. Elevation (Show whether DF, RT, GR, etc.)	
4385 GR	

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

### NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

### SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
CASING TEST AND CEMENT JOB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

4-8-74 - 4-10-74

1. Set Baker CIBP w/3 sx. cmt. @ 4350'. WOC 12. hrs.
2. Cut & pull 1460' 4-1/2" csg.
3. Set 45 sx. plug @ 1460'.
4. Set 50 sx. plug @ 300'.
5. Set 10 sx. plug @ surface.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED J.B. Shepherd TITLE Dist. Prod. Manager DATE June 26, 1974

APPROVED BY W.B. Satterlin TITLE OIL & GAS INSPECTOR DATE JUN 9 1980

CONDITIONS OF APPROVAL, IF ANY: