

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

3a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.
K-362

<p align="center">SUNDRY NOTICES AND REPORTS ON WELLS</p> <p align="center"><small>(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)</small></p>		
1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name	
2. Name of Operator Sun Oil Company	8. Field or Lease Name Harris State	
3. Address of Operator P. O. Box 1861 Midland, Texas 79701	9. Well No. 3	
4. Location of Well UNIT LETTER <u>J</u> <u>2310</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>East</u> LINE, SECTION <u>23</u> TOWNSHIP <u>10S</u> RANGE <u>32E</u> NMPM.	10. Field and Pool, or Wildcat Mescalero San Andres	
15. Elevation (Show whether DF, RT, GR, etc.) DF - 4321	12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
-------------------------	-----------------------

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting, any proposed work) SEE RULE 1103.

12/1/70 Ran tubing to 225', circulate hole with water; spot 125 sack cement plug; pull tubing to 420' and spot 50 sack plug 220-420; spot 10 sack plug 0-25; set marker. Clear location and fill all pits.

Casing left in hole:
352 ft. 8-5/8"
3544 ft. 4 1/2" w/bridge plug @ 4133'

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>RW Hughes</u>	TITLE <u>Proration Clerk</u>	DATE <u>Dec. 31, 1970</u>
APPROVED BY <u>John W. Runyan</u>	TITLE <u>Geologist</u>	DATE <u>MAR 25 1971</u>
CONDITION OF APPROVAL, IF ANY:		