

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

AUG 3 11 41 AM '67

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input checked="" type="checkbox"/>	Fee <input type="checkbox"/>
5. State Oil & Gas Lease No.	
K-362	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- <input type="checkbox"/>		7. Unit Agreement Name	
2. Name of Operator Sunray DX Oil Company		8. Farm or Lease Name Harris State	
3. Address of Operator P. O. Box 1416 - Roswell, New Mexico		9. Well No. 3	
4. Location of Well UNIT LETTER J 2310 FEET FROM THE South LINE AND 2310 FEET FROM THE East LINE, SECTION 23 TOWNSHIP 10-S RANGE 32-E NMPM.		10. Field and Pool, or Wildcat Mescalero-San Andres	
15. Elevation (Show whether DF, RT, GR, etc.) 4321 DF		12. County Lea	

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>		CASING TEST AND CEMENT JOBS <input type="checkbox"/>	
OTHER Perforate Additional Section <input checked="" type="checkbox"/>		OTHER <input type="checkbox"/>	

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Move in and rig up pulling unit
2. Pull rods and tubing
3. Run PFC log and perf selected intervals
4. Acidize intervals with Dowell XFW acid
5. Put well on pump and recover load
6. Test and produce

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED <u>John Hastings</u>	TITLE <u>District Engineer</u>	DATE <u>8-1-67</u>
APPROVED BY _____ TITLE _____ DATE _____		
CONDITIONS OF APPROVAL, IF ANY:		