COPIES RECEIVED	
	Form C-103 Supersedes Old
TRIBUTION	C-102 and C-103
NEW MEXICO OIL CONSERVATION COM	MISSION Effective 1-1-65
	Sa. Indicate Type of Lease
J.S.G.S.	
AND OFFICE	State Fee A 5. State Oll & Gas Lease No.
PERATOR	5. State OII & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS	
(DO NOT USE THIS FORM FOR PROPOSALS TO BRILL ON TO BEEPEN OR PLUG BACK TO A DIFFERENT USE "APPLICATION FOR PERMIT	
	7, Unit Agreement Name
GIL GAS WELL OTHER-	9. Farm or Lease Name
Name of Operator	
Tipperary Oil & Gas Corporation	Bell
Address of Operator	9. Well No.
500 W. Illinois Midland, Texas 79701	2
Location of Well	10. Field and Pool, or Wildcat
UNIT LETTERA554FEET FROM THENOT TH	554 North Bagley Upper P
THE East LINE, SECTION 21 TOWNSHIP 11 S RANGE 3	<u>З Е</u> ммрм. (////////////////////////////////////
15. Elevation (Show whether DF, RT, GR, etc.)	12. County
<u> 111111111111111111111111111111111111</u>	Lea ////////
Check Appropriate Box To Indicate Nature of Notic NOTICE OF INTENTION TO:	subsequent report of:
PERFORM REMEDIAL WORK PLUG AND ABANDON X REMEDIAL WORK	ALTERING CASING
COMMENCE DRILL	
PULL OF ALTER CASING CASING TEST AND	
	· · · · · · · · · · · · · · · · · · ·
OTHER	
(c) I have the deside and size part	inent dates, including estimated date of starting any proposed
<ol> <li>Describe Proposed or Completed Operations (Clearly state all pertinent details, and give perti- work) SEE RULE 1103.</li> </ol>	
work) SEE RULE 1103.	
work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr	com 6438 and reran 4 1/2"
work) SEE RULE 1103. Casing collapsed at 6438. Pulled casing fr	
work) SEE RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch b 5206. Pulled casing from 5206.	com 6438 and reran 4 1/2" bowl, parted casing at
<pre>work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch k 5206. Pulled casing from 5206. It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approximate</pre>	TOM 6438 and reran 4 1/2" Dowl, parted casing at PYRE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE DIGININING OF HOURS PRIOR TO THE C-103
<pre>work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch k 5206. Pulled casing from 5206. It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approximate</pre>	Tom 6438 and reran 4 1/2" bowl, parted casing at PYRE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE DIGINNING OF HOURS PRIOR TO THE C-103
<pre>work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch b 5206. Pulled casing from 5206. It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approxima Spot 25 sacks at 7 5/8" stub</pre>	Tom 6438 and reran 4 1/2" bowl, parted casing at PYRE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE LIGINNING OF HOURS PRIOR TO THE C-103
<pre>work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch k 5206. Pulled casing from 5206. It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approxima Spot 25 sacks at 7 5/8" stub Spot 25 sacks at 7 5/8" stub</pre>	Tom 6438 and reran 4 1/2" bowl, parted casing at WHE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE LIGINNING OF PLUCGING OPERATIONS FOR THE C-103 PLUCGING OPERATIONS FOR THE C-103 ALE 1 - 2700
<pre>work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch k 5206. Pulled casing from 5206. It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approxima Spot 25 sacks at 7 5/8" stub Spot 25 sacks at 7 5/8" stub Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at top of Anhydrite at 15</pre>	Tom 6438 and reran 4 1/2" bowl, parted casing at WHE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE LIGINNING OF PLUCGING OPERATIONS FOR THE C-103 PLUCGING OPERATIONS FOR THE C-103 ACCEPTED - 2700
<pre>work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch b 5206. Pulled casing from 5206. It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approxima Spot 25 sacks at 7 5/8" stub Spot 25 sacks at 7 5/8" stub Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at top of Anhydrite at 15 Spot 25 sacks at 10 3/4" shoe at 300-//</pre>	Tom 6438 and reran 4 1/2" Dowl, parted casing at WHE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE LIGINNING OF HOURS PRIOR TO THE LIGINNING OF PLUCSING OPERATIONS FOR THE C-103 ADDROVED. ADDROVED. 530 530
<pre>work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch k 5206. Pulled casing from 5206. It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approxima Spot 25 sacks at 7 5/8" stub Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at top of Anhydrite at 15 Spot 25 sacks at 10 3/4" shoe at 300-// Spot 10 sacks at surface with regulation</pre>	Tom 6438 and reran 4 1/2" bowl, parted casing at PARE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE LIGINNING OF PLUCING OPERATIONS FOR THE C-103 PLUCING OPERATIONS FOR THE C-103 AND VED. 530 530 530 530 530 530 530 530
<pre>work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch k 5206. Pulled casing from 5206. It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approxima Spot 25 sacks at 7 5/8" stub Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at 10 3/4" shoe at 300 -/. Spot 10 sacks at surface with regulation Rotary mud between all plugs</pre>	Tom 6438 and reran 4 1/2" bowl, parted casing at PARE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE LIGINNING OF PLUCING OPERATIONS FOR THE C-103 PLUCING OPERATIONS FOR THE C-103 AND VED. 530 530 530 530 530 530 530 530
<pre>work) see RULE 1103. Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch k 5206. Pulled casing from 5206. It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approxima Spot 25 sacks at 7 5/8" stub Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at top of Anhydrite at 15 Spot 25 sacks at 10 3/4" shoe at 300-// Spot 10 sacks at surface with regulation</pre>	Tom 6438 and reran 4 1/2" Dowl, parted casing at WHE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE LIGINNING OF HOURS PRIOR TO THE LIGINNING OF PLUCHING OPERATIONS FOR THE C-103 ADDROVED. ADDROVED. 530 00 9000
<ul> <li>Work) SEE RULE 1103.</li> <li>Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch k 5206. Pulled casing from 5206.</li> <li>It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approxima Spot 25 sacks at 7 5/8" stub Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at 10 3/4" shoe at 300 -/- Spot 10 sacks at surface with regulation Rotary mud between all plugs Clear and level location</li> </ul>	Tom 6438 and reran 4 1/2" bowl, parted casing at WHE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE LIGININING OF PLUCGING OPERATIONS FOR THE C-103 PLUCGING OPERATIONS FOR THE C-103 ATELY 2700 530 530 530 530 530 530 530 5
<ul> <li>Work) SEE RULE 1193.</li> <li>Casing collapsed at 6438. Pulled casing fracture casing with casing bowl. Unable to latch be 5206. Pulled casing from 5206.</li> <li>It is proposed to plug and abandon as follows for 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approximate Spot 25 sacks at 7 5/8" stub</li> <li>Spot 25 sacks at 7 5/8" stub</li> <li>Spot 25 sacks at 10 3/4" shoe at 300 -/. Spot 10 sacks at surface with regulation Rotary mud between all plugs</li> <li>Clear and level location</li> </ul>	Tom 6438 and reran 4 1/2" owl, parted casing at WHE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE D.GINNING OF HOURS PRIOR TO THE C.103 PLUCGING OPERATIONS FOR THE C.103 ATEL - 2700 530 530 530 530 530 530 544 544 550 560 570 570 570 570 570 570 570 57
<ul> <li>Work) SEE RULE 1103.</li> <li>Casing collapsed at 6438. Pulled casing fr casing with casing bowl. Unable to latch k 5206. Pulled casing from 5206.</li> <li>It is proposed to plug and abandon as follo Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approxima Spot 25 sacks at 7 5/8" stub Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at top of Anhydrite at 15 Spot 25 sacks at 10 3/4" shoe at 300 -// Spot 10 sacks at surface with regulation Rotary mud between all plugs Clear and level location</li> </ul>	Tom 6438 and reran 4 1/2" bowl, parted casing at WHE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE DIGININING OF HOURS PRIOR TO THE C-103 PLUCGING OPERATIONS FOR THE C-103 ATEL 9- 2700 530 530 530 530 530 530 544 544 550 550 550 550 550 55
<ul> <li>Work) SEE RULE 1103.</li> <li>Casing collapsed at 6438. Pulled casing fraction for casing with casing bowl. Unable to latch by 5206. Pulled casing from 5206.</li> <li>It is proposed to plug and abandon as follow Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approximate Spot 25 sacks at 7 5/8" stub</li> <li>Spot 25 sacks at 7 5/8" stub</li> <li>Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at 10 3/4" shoe at 300 -//. Spot 10 sacks at surface with regulation Rotary mud between all plugs</li> <li>Clear and level location</li> </ul>	Tom 6438 and reran 4 1/2" bowl, parted casing at WHE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE DISINNING OF PLUCSING OPERATIONS FOR THE C-103 PLUCSING OPERATIONS FOR THE C-103 APPROVED. 530 530 530 530 544 Date <u>11-15-76</u>
<ul> <li>work) SEE RULE 1103.</li> <li>Casing collapsed at 6438. Pulled casing fracting with casing bowl. Unable to latch b 5206. Pulled casing from 5206.</li> <li>It is proposed to plug and abandon as follows Spot 100 sacks at 4 1/2" stub at 5206 Spot 25 sacks at 7 5/8" shoe at 3750 Cut &amp; pull 7 5/8" casing from approximate Spot 25 sacks at 7 5/8" stub</li> <li>Spot 25 sacks at 7 5/8" stub</li> <li>Spot 25 sacks at top of Yates at 2450 Spot 25 sacks at 10 3/4" shoe at 300 -// Spot 10 sacks at surface with regulation Rotary mud between all plugs</li> <li>Clear and level location</li> </ul>	Tom 6438 and reran 4 1/2" bowl, parted casing at WHE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE DIGINNING OF HOURS PRIOR TO THE CIO3 PLUCING OPERATIONS FOR THE CIO3 ATEL 9- 2700 530 530 530 530 530 530 530 5

RECEIVED NC 171976 OIL CONSERVATION GUMM. HOBBS, N. M.