DISTRIBUTION SANTA FE FILE U.S.G.S. LAND OFFICE OPERATOR	NEW MEXICO OIL CONSERVATION COMMAR 8 11 45	MMISSION Effective 1-1-65 State Type of Lease State Gas Lease No. K-3918
DO NOT USE THIS FORM FO	NDRY NOTICES AND REPORTS ON WELLS OF PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT CATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)	NT RESERVOIR.
1. OIL GAS WELL WELL	OTHER- Test W.11	7. Unit Agreement Name
2. Name of Operator		8. Farm or Lease Name
Cities Service C	AI CO.	State BP 9. Well No.
Box 69 - Hobbs, New Mexico		9. WEIT NO.
4. Location of Well		10. Field and Pool, or Wildcat
UNIT LETTER	660 FEET FROM THE North LINE AND	1980 FEET FROM Undesignated
THE WEST LINE, S	TOWNSHIP 108 RANGE 15. Elevation (Show whether DF, RT, GR, etc.,	36E NMPM.
	4021 DF	Ina (IIIIIIII
	ck Appropriate Box To Indicate Nature of Notice FINTENTION TO:	
	THAT ENTITION TO	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK	PLUG AND ABANDON 🗶 REMEDIAL WORK	ALTERING CASING
TEMPORARILY ABANDON	COMMENCE DRILL	ING OPNS. PLUG AND ABANDONMENT
But 1 an 11 mm a 1 mm	! I	
PULL OR ALTER CASING	CHANGE PLANS CASING TEST AND	
OTHER		CEMENT JOB
OTHER		
other 17. Describe Proposed or Complete work) SEE RULE 1103. We propose to plug 1. Lead hole w 2. Set 25 sax p 3. Set 25 sax p 4. Set 10 sax p P & A location	above captioned well in the following ith must laden fluid. lug across San Andres perfs. 4916 to a lug one half in and one half out of 51 lug out surface to 30° w/4" Marker extends	inent dates, including estimated date of starting any proposed manner: 1709. " casing 8 cut point. nding 4. above ground to designate
17. Describe Proposed or Complete work) SEE RULE 1103. We propose to plug 1. Lead hole w 2. Set 25 sax p 3. Set 25 sax p 4. Set 10 sax p P & A location 5. Clean location	above captioned well in the following ith musi laden fluid. lug across San Andres perfs. 4916 to a lug one half in and one half out of 51 lug e surface to 30° v/4" Marker extension. can of all debris & equipment, fill pit	manner: 709. 1 casing 9 cut point. Iding A' above ground to designate.
17. Describe Proposed or Complete work) SEE RULE 1103. We propose to plug 1. Lead hole w 2. Set 25 sax p 3. Set 25 sax p 4. Set 10 sax p P & A location 5. Clean location	above captioned well in the following ith musi laden fluid. lug across San Andres perfs. 4916 to a lug one half in and one half out of 5 lug o surface to 30° v/4" Marker extension. can of all debris & equipment, fill pit	manner: 709. " easing 9 cut point. Iding 4' above ground to designate. S & collar.