1-	State of No.				
Submit 3 Copies to Appropriate	State of Ne Energy, Minerals and Natur			Form C-103 ' Revised 1-1-89	
District Office	OT CONSEDUA	τιΛ	NIDIVICION		
DISTRICT I P.O. Box 1980, Hobbs, NM 88240	OIL CONSERVA P.O. Bo	x 208	8	Well APINO. 30-025-21754	
DISTRICT II P.O. Drawer DD, Artesia, NM \$8210	Santa Fe, New Me	Fe, New Mexico 87504-2088		5. Indicate Type of Lesse STATE FEE X	
DISTRICT III 1000 Rio Brazos Rd., Aziec, NM 87410				6. State Oil & Gas Lease No.	
	ICES AND REPORTS ON	WEI	15		
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)			7. Lease Name or Unit Agreement Name		
			Flying "M" (SA) Unit TF.26		
1. Type of Well:					
OE CAS WELL	OTHER				
2. Name of Operator	noration			8. Well No. $\frac{1}{1}$	
Coastal Oil & Gas Cor 3. Address of Operator				9. Pool name or Wildcat	
211 N. Robinson, Suit	<u>e 1700, Oklahoma Cit</u>	ty, (<u>0K 73102</u>	Flying "M" San Andres	
4. Well Location P 21	20 Fast	•	• • 520	Feet From The North Line	
	20 Feet From The East		Line and	Feet From The Line	
Section 28	Township 95			NMPM Lea County	
	//////		DF, RKB, RT, GR, etc.)		
	4333.6' (Nature of Notice D	most or Other Data	
11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:					
E7	-				
	PLUG AND ABANDON		REMEDIAL WORK		
	CHANGE PLANS		COMMENCE DRILLING		
PULL OR ALTER CASING			CASING TEST AND CE		
OTHER:			OTHER:	[
12 Describe Processed or Completed Ones	ntions (Clearly state all pertinent det	wils, an	l	ling estimated date of starting any proposed	
work) SEE RULE 1103.					
1. MIRU Pulling Unit. POOH with rods, pump and 2-7/8" tubing.					
2. TIH with packer on $2-3/8$ " tubing. Set packer at \pm 4350'.					
 Load 2-3/8" x 4-1/2" annulus with fresh water and pressure up to 400 psi. Acidize well with 500 gals of 15% HCL. Swab back bad. 					
 Actuate well with 300 gais of 15% http://www.back.bad. Treat well with 350 bbls of Pfizer's Floperm 500. Flush with 75 bbls of lease crude. 					
6. Shut well in for 5-7 days.					
7. POOH with 2-3/8" tubing and packer.					
8. TIH with 2-3/8" production tubing, pump, and rods.					
9. Return well to production. PDMO Pulling Unit.					

I hereby certify that the information above is true and complete to the best of my knowled SKINATURE	ge md buid. TTLE Sr. Petroleum Engineer	DATE12/20/91 (405) TELETHONE NO. 239-7031
(This space for State Use) (2014 ARE 2020) & MERCEN (25XTON) PHONE RELATION APPROVED BY	- mus	