			MATE		Form C-103 Supersedes Old
DISTRIBUTION SANTA FE	H NF	W MEXICO OIL CONSE	RVATION COMMISSION	C. C.	C-102 and C-103 Effective 1-1-65
FILE	+		ranger and the second		
U.S.G.S.					a. Indicate Type of Lease
LAND OFFICE		·		,	State Fee
OPERATOR					5. State Oil & Gas Lease No.
	_ ''				
SI (do not use this form i use "af	UNDRY NOTICES FOR PROPOSALS TO DRILL PPLICATION FOR PERMIT	AND REPORTS ON OR TO DEEPEN OR PLUG BA	WELLS CK TO A DIFFERENT RESERVOIR PROPOSALS.)		7. Unit Agreement Name
OIL GAS WELL	OTHER+				, Ont Agreement Ivamo
2. Name of Operator Stolts & Company	7				8. Farm or Lease Name
3. Address of Operator		Box 763, Hobi	os. New Mexico		9. Well No
4. Location of Well	_				10. Field and Pool, or Wildcat N. Bagley Kiddle Penn
UNIT LETTER	. 510	FROM THE HOTTH	LINE AND	FEET FROM	W. Destel with Levil
THE Bast LINE	, section 21	township 11 8	RANGE 33 E	NМРМ.	
	15. 1	Elevation (Show whether 4265	DF, RT, GR, etc.)		12. County
	heck Appropriate OF INTENTION T		ature of Notice, Repo	rt or Othe	er Data REPORT OF:
TEST ON PENEDIAL WORK		PLUG AND ABANDON	REMEDIAL WORK		ALTERING CASING
PERFORM REMEDIAL WORK		1200 11112 112111	COMMENCE DRILLING OPNS.	Ħ	PLUG AND ABANDONMENT
TEMPORARILY ABANDON		CHANGE PLANS	CASING TEST AND CEMENT JOS	, I	
PULL OR ALTER CASING		CHANGE LEANS			
			OTHER		
OTHER			OTHER	·	
other	leted Operations (Clear	ly state all pertinent deta		including e	stimated date of starting any proposed
17. Describe Proposed or Complework) SEE RULE 1103. Coments 50/50 1 pressur	ed 4 1/2º 11.6 Posmix Incor. re tested casi	# J-55 and N-60 Plug down 5:15 ng with 1,000#	casing at 10,198 A.M. 8/22/66. W	with 42 0C 24 he	25 sacks ours and
17. Describe Proposed or Complework) SEE RULE 1103. Coments 50/50 1 pressure	od 4 1/2" 11.6 Posmix Incor. re tested easi.	# J-55 and N-60 Plug down 5:15 ng with 1,000#	easing at 10,198 A.M. 8/22/66. W for 30 minutes, to	with 42 0C 24 he	25 saeks ours and
17. Describe Proposed or Complework) SEE RULE 1103. Coments 50/50 1 pressur	od 4 1/2" 11.6 Posmix Incor. re tested easi.	# J-55 and N-60 Plug down 5:15 ng with 1,000#	casing at 10,198 A.M. 8/22/66. W	with 42 0C 24 he	25 sacks ours and
17. Describe Proposed or Complework) SEE RULE 1103. Coments 50/50 pressure 18. I hereby certify that the info	od 4 1/2" 11.6 Posmix Incor. re tested easi.	J-55 and N-80 Plug down 5:15 ng with 1,000	easing at 10,198 A.M. 8/22/66. W for 30 minutes, to	with 42 0C 24 he	25 saeks ours and