DISTRIBUTION SAME A FEB NEW MEXICO OIL CONSERVATION COMMISSION Substitute 11-465 Substitute 11-4	NO. OF COPIES RECEIVED				Form C-103		
NEW MEXICO OIL CONSERVATION COMMISSION Control Cont	DISTRIBUTION	TION			_ •		
Substitution Subs	SANTA FE	NEW	MEXICO OIL CON	SERVATION COMMISSION			
Solid Control Solid Contro	FILE						
SUNDRY NOTICES AND REPORTS ON WELLS DO NOT USE THIS PROVISE SECURITY OF SECURITY OF YOUR STEELS ON WELLS TO NOTICE SECURITY OF SECURITY	U.S.G.S.				1 — "	_	
SUNDRY NOTICES AND REPORTS ON WELLS OTHER. AND ADDRESS OF THE TRIP SECURITY OF THE SECURITY	LAND OFFICE				State X	Fee,	
SUNDER NOTICES AND REPORTS ON WELLS 1.	OPERATOR				5. State Oil & Gas Le	ease No.	
1. Name of Operator Amini Cil Corporation Assistant of Operator Amini Cil Corporation Assistant of Operator 400 Wall Towers West: Midland, Texas 79701 10. Fleid and Pool, or Wildow Text room and off the West wildow of the Complete State of the Complete State of State of Complete State of Stat		·	·	·	K-2443		
The common of th	(DO NOT USE THIS FOR USE *	SUNDRY NOTICES AND FOR PROPOSALS TO DRILL OF APPLICATION FOR PERMIT -	ND REPORTS ON PLUG	WELLS BACK TO A DIFFERENT RESERVOIR. CH PROPOSALS.)			
And there is depended to Completed Control to the Control to the Control to the Control to the Completed Control to the Contro	1.				7. Unit Agreement No	ime	
400 Wall Towers West: Midland, Texas 79701 1. Location of Well 1. Location of Well 10. Field and Pool, or Wildoot Vada Poon 11. County 12. County 13. Elevation (Show whether Dr. RT. GR. etc.) 14253 RKB Check Appropriate Box To Indicate Nature of Notice, Report of Other Data Notice of Intention To: Subsequent Report of: PLUS AND ABANDON TEMPORALITY ASANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly store all pertinent details, and give pertinent dates, including estimated date of starting any proposed works. See RUL E 1708. Pull or ALTER CASING No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf. 20 county No. 2 Top of cement behind 5½ casing @7000'. No. 3 Pull 5½ casing from 7000'. No. 4 Set 25 sk plug on top 5½ casing stub, No. 5 Set 25 sk plug @9980' on top of Glorieta. No. 6 Set 50 sk plug @990' on top of Glorieta. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub, No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location. 18. I bereby certify that the information above is true and complete to the best of my knowledge and ballef. 210012 April 24 Casing by Joe D. Report No. 1 Report 14 Casing Casing Stub. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location.		8. Farm or Lease Nan	ne				
400 Wall Towers West: Midland, Texas 79701 1. Location of Well Wast Line, section 30 Township 10-S RANGE 34-F Wast Line, section 30 Township 10-S RANGE 34-F Wast Line, section 30 Township 10-S RANGE 34-F REMEDIAL WORK ALTERINE CASING FLUE AND ARANGON TEXNSHIP ARANGON FLUE AND ARANGON TEXNSHIP ARANGON FLUE AND ARANGON TEXNSHIP ARANGON FLUE AND ARANGON FLUE AND ARANGON TEXNSHIP ARANGON FLUE AND ARANGON FLUE AND ARANGON TEXNSHIP ARANGON FLUE AND ARANGON TEXNSHIP ARANGON FLUE AND ARANGON FLUE AND ARANGON TEXNSHIP ARANGON FLUE AND ARANGON TEXNSHIP ARANGON TEXNSHIP ARANGON FLUE AND ARANGON TEXNSHIP ARANGON FLUE AND ARANGON TEXNSHIP ARANGON TOTALS TOTALS TO COMMITTED ARANGON TOTALS TOTALS TOTALS TO COMMITTED ARANGON TOTALS TOT	Amini Oil Corporati	Iane-St	Lane-State				
10. Fleds and Pool, or Wildows Wash Line, Section 30 Township 10-S Names 34-F NAME 11. Elevation (Show whether DF, RT, GR, etc.) 12. Country 13. Elevation (Show whether DF, RT, GR, etc.) 14. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF: **PLUS AND ABANDON** **PLUS AND A	400 Wall Towers V	West: Midland. T	exas 79701				
The West Line, section 30 township 10-S hance 34-E hand. 13. Elevation (Show whether DF, RT, GR, etc.) 4253 RKB 12. Country 4253 RKB 12. Country 13. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: Subsequent report of: Subsequent report of:	4. Location of Well					r Wildcat	
15. Elevation (Show whether DF, RT, GR, etc.) 4253 RKB Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PELUS AND ADAMOON	UNIT LETTERM	,660 PERT P	NOM THE <u>South</u>	LINE ANDF	EET FROM Vada Penn	anna a	
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABILITY MARKDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 105. Plugging Procedure: No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf. @10002 - 10014'. No. 2 Top of cement behind 5½" casing @7000'. No. 3 Pull 5½" casing from 7000'. No. 4 Set 25 sk plug @35350' on top 5½" casing stub. No. 5 Set 25 sk plug @4300' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location.	THEWest_ LI	NE, SECTION30	_ TOWNSHIP10-	S range 34-E	_ нмрм. (()))))))		
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORABILITY MARKDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all periment details, and give periment dates, including estimated date of starting any proposed work) SEE RULE 105. Plugging Procedure: No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf. @10002 - 10014'. No. 2 Top of cement behind 5½" casing @7000'. No. 3 Pull 5½" casing from 7000'. No. 4 Set 25 sk plug @35350' on top 5½" casing stub. No. 5 Set 25 sk plug @4300' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location.	mmmm	12. County	HHHH				
Check Appropriate Box To Indicate Nature of Notice, Report or Other Data NOTICE OF INTENTION TO: PERFORM REMEDIAL WORK TEMPORALITY ABANDON THENCARLY ABANDON THE							
PLUG AND ARABODON TEMPORATED ALL WORK COMMENCE DRILLING OPAS. CHANGE PLAND OTHER 17. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, including estimated date of starting any proposed work) see Rule 1 105. Plugging Procedure: No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf. @10002 - 10014'. No. 2 Top of cement behind 5½" casing @7000'. No. 3 Pull 5½" casing from 7000'. No. 4 Set 25 sk plug on top 5½" casing stub. No. 5 Set 25 sk plug @95350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location.	16.	Check Appropriate B		Nature of Notice, Report	or Other Data		
TEMPORABLY ABANDON PULL OR ALTER CASING OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Plugging Procedure: No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf.	NOTIC	E OF INTENTION TO:	ł	SUBSE	QUENT REPORT OF:		
PULL OR ALTER CASINE OTHER OTHER 17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) see roll 17. To S. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf. @10002 - 10014'. No. 2 Top of cement behind 5½" casing @7000'. No. 3 Pull 5½" casing from 7000'. No. 4 Set 25 sk plug @10002 on top of Glorieta. No. 5 Set 25 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location.	PERFORM REMEDIAL WORK	Р	LUG AND ABANDON X	REMEDIAL WORK	ALTERING (CASING	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE' 1763. Plugging Procedure: No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf.	TEMPORARILY ABANDON			COMMENCE DRILLING OPNS.	PLUG AND A	BANDONMENT	
17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE NULE 1703. Plugging Procedure: No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf.	PULL OR ALTER CASING	c	HANGE PLANS	CASING TEST AND CEMENT JOB			
17. Describe Proposed or Completed Operations (Clearly state all persinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1703. Plugging Procedure: No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf.				OTHER			
Plugging Procedure: No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf. @10002 - 10014'. No. 2 Top of cement behind $5\frac{1}{2}$ " casing @7000'. No. 3 Pull $5\frac{1}{2}$ " casing from 7000'. No. 4 Set 25 sk plug on top $5\frac{1}{2}$ " casing stub. No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location.	OTHER	· ,		 			
Plugging Procedure: No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf. @10002 - 10014'. No. 2 Top of cement behind $5\frac{1}{2}$ " casing @7000'. No. 3 Pull $5\frac{1}{2}$ " casing from 7000'. No. 4 Set 25 sk plug on top $5\frac{1}{2}$ " casing stub. No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location.	17. Describe Proposed or Con	pleted Operations (Clearly	state all pertinent de	tails, and give pertinent dates,	including estimated date of start	ing any proposed	
No. 1 Set 30 sk plug @9980, and fill hole w/9.5 laden fluid, perf. @10002 - 10014'. No. 2 Top of cement behind $5\frac{1}{2}$ " casing @7000'. No. 3 Pull $5\frac{1}{2}$ " casing from 7000'. No. 4 Set 25 sk plug on top $5\frac{1}{2}$ " casing stub. No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location.	work) SEE RULE 1105.				-	•	
@10002 - 10014'. No. 2 Top of cement behind $5\frac{1}{2}$ " casing @7000'. No. 3 Pull $5\frac{1}{2}$ " casing from 7000'. No. 4 Set 25 sk plug on top $5\frac{1}{2}$ " casing stub. No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of $8-5/8$ " csg. No. 7 Pull $8-5/8$ " casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at $11-3/4$ " casing, set marker & clean up location.	Plugging Procedure	:					
@10002 - 10014'. No. 2 Top of cement behind $5\frac{1}{2}$ " casing @7000'. No. 3 Pull $5\frac{1}{2}$ " casing from 7000'. No. 4 Set 25 sk plug on top $5\frac{1}{2}$ " casing stub. No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of $8-5/8$ " csg. No. 7 Pull $8-5/8$ " casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at $11-3/4$ " casing, set marker & clean up location.							
No. 2 Top of cement behind $5\frac{1}{2}$ " casing @7000'. No. 3 Pull $5\frac{1}{2}$ " casing from 7000'. No. 4 Set 25 sk plug on top $5\frac{1}{2}$ " casing stub. No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location.	No. 1	Set 30 sk plug	en fluid, perf.				
No. 3 Pull 5½" casing from 7000'. No. 4 Set 25 sk plug on top 5½" casing stub. No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.			_	•			
No. 4 Set 25 sk plug on top $5\frac{1}{2}$ " casing stub. No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location. 16. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED APPROVED BY Orig. Signal by Joe D. Renny TITLE PATE: 10-21-71							
No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location. 16. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED APPROVED BY Orig. Signed by Joe D. Renny TITLE PATE: 10-21-71	No. 3						
No. 5 Set 25 sk plug @5350' on top of Glorieta. No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED APPROVED BY Orig. Signed by Joe D. Renny TITLE PATE: 10-21-71	No. 4	Set 25 sk plug on top $5\frac{1}{2}$ " casing stub.					
No. 6 Set 50 sk plug @4000' in bottom of 8-5/8" csg. No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED HARMAN TITLE Agent DATE 10-21-71 Orig. Signed by Joe D. Ranky	No. 5	·					
No. 7 Pull 8-5/8" casing from 1400', set 25 sk plug at stub. No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED Signed by Joe D. Ranger TITLE PAGENTY TITLE PAGENT DATE: 10-21-71							
No. 8 Set 25 sk plug base of surface @360'. No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location. 16. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED HORIZON TITLE Agent DATE 10-21-71 Orig. Signed by Joe D. Renney TITLE DATE 10-21-71							
No. 9 Set 10 sk plug in top at 11-3/4" casing, set marker & clean up location. 18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED HOLLOWING TITLE Agent DATE 10-21-71 Orig. Signed by Joe D. Realey TITLE DATE 10-21-71							
18. I hereby certify that the information above is true and complete to the best of my knowledge and belief. SIGNED AGENT DATE 10-21-71 Orig. Signed by Joe D. Ramey Title DATE 1071					nulan C =1 == .		
Orig. Signed by Joe D. Resney TITLE Agent DATE 10-21-71	NO. 9	ser to sk brug	in top at 11-	-3/4" casing, set m	arker & clean up lo	cation.	
Orig. Signed by Joe D. Resney TITLE Agent DATE 10-21-71							
Orig. Signed by Joe D. Resney TITLE Agent DATE 10-21-71							
Orig. Signed by Joe D. Resney TITLE Agent DATE 10-21-71							
Orig. Signed by Joe D. Restey TITLE Agent DATE 10-21-71						<u> </u>	
Orig. Signed by Joe D. Renney Title DATE: 21 1071	18. I hereby certify that the in	formation above is true and	complete to the best	of my knowledge and belief.			
Orig. Signed by Joe D. Renney Title DATE: 21 1071	Xnxi.	Hade	. /	λ			
APPROVED BY JOE D. Remay TITLE DATE OF 107	SIGNED / COURS	+ NUCLIVEM	TITLE	Agent ·	DATE 10-21-	71	
APPROVED BY JOE D. Remay TITLE DATE OF 107	Or	ig. Signal ha					
APPROVED BY	Jo.	e D. Reiney	T171 F		BATEN OF THE	a 10 74	
	DI CONDITIONE OF ADDRESS				"Tith 2	5 13/1 - 	