Porm 9-331 "May 1963)

OIL X

2. NAME OF OPERATOR

UN"ED STATES DEPARTME OF THE INTERIOR (Other Instruction verse side)

SUBMIT IN TRIPE-ATE.

Form approved. Budget Bureau No. 42-R1424. 5. LEASE DESIGNATION AND SERIAL NO.

6. IF INDIAN, ALLOTTEE OR TRIBE NAME

NM-918

	GEOLOGICAL SURVEY					
SUNDRY	NOTICES	AND	REPORTS	ON	WELLS	

(Do not use this form for proposals to drill or to deepen or plug back to a different reservoir.

Use "APPLICATION FOR PERMIT—" for such proposals.)

7. UNIT AGREEMENT	BKAK
SW-558	
8. FARM OR LEASE N	AMB
Federal I	H

Midwest Oil Corporation

OTHER

3. ADDRESS OF OPERATOR

Box 2010, Hobbs, New Mexico 88240
LOCATION OF WELL (Report location clearly and in accordance with any State requirements.*

See also space 17 below.)

At surface

660' from the North and 1980' from the West

10. FIELD AND POOL, OR WILDCAT

Vada Penn. 11. SEC., T., E., M., OR BLK. AND SURVEY OR AREA

18-9-35

9. WELL NO.

Section 18, Township 9, Range 35. 15. ELEVATIONS (Show whether DF, RT, GR, etc.) 14. PERMIT NO.

12. COUNTY OR PARISH | 13. STATE New Mex.

16.

Check Appropriate Box To Indicate Nature of Notice, Report, or Other Data

SUBSEQUENT SEPORT OF : NOTICE OF INTENTION TO: BEPAIRING WELL PULL OR ALTER CASING WATER SHUT-OFF TEST WATER SHUT-OFF ALTERING CASING FRACTURE TREATMENT MULTIPLE COMPLETE FRACTURE TREAT X SHOOTING OR ACIDIZING ABANDONMENT* ABANDON' SHOOT OR ACIDIZE CHANGE PLANS REPAIR WELL (NOTE: Report results of multiple completion on Well Completion or Recompletion Report and Log form.) (Other)

- 17. DESCRIBE PROPOSED OR COMPLETED OPERATIONS (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work. If well is directionally drilled, give subsurface locations and measured and true vertical depths for all markers and sones pertinent to this work.)
- Spot a 25 sx. plug at TD to cover existing perforations. 1.
- Load hole with mud laden fluid 2.
- Recover production casing from approximately 5000' 3.
- Spot a 35 sx. plug at stub of 5-1/2" casing 4.
- Spot a 50 sx. plug in and out of base of intermediate casing set 5. @ 4046'
- Shoot and recover 8-5/8" casing from approximately 1000' and spot 6. a 50 sx. plug.
- Spot a 50 sx. plug in and out of base of 11-3/4" set at 320' 7.
- Spot a 10 sx. top hole plug and erect a regulation marker. 8.

8. I hereby certify that the foregoing is true and correct	Agent 5/16/73
SIGNED MICH MICHELL TITLE	Agent DATE
(This space for Federal or State office use)	1 APP 1073 00
APPROVED BY TITLE	MAY 21 1913 PATE
CONDITIONS OF APPROVAL, IF ANY:	ARTHUR R. BROWN ARTHUR R. BROWN Ons on Reverse Side
	ARTHUR ENGLISH
*See Instruction	ons on Reverse Side