

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

MUNICIPALITY OF ALBUQUERQUE O. C. C.  
 JAN 19 2 49 PM '66

Form C-103  
 Supersedes Old  
 C-102 and C-103  
 Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
Fee	

**SUNDRY NOTICES AND REPORTS ON WELLS**  
 (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR.  
 USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- DRY - PLUG & ABANDON	7. Unit Agreement Name NONE
2. Name of Operator TEXACO Inc.	8. Farm or Lease Name A. B. Hogan
3. Address of Operator P. O. Box 728 - Hobbs, New Mexico	9. Well No. 1
4. Location of Well UNIT LETTER <u>D</u> <u>660</u> FEET FROM THE <u>North</u> LINE AND <u>660</u> FEET FROM THE <u>West</u> LINE, SECTION <u>3</u> TOWNSHIP <u>8-S</u> RANGE <u>34-E</u> NMPM.	10. Field and Pool, or Wildcat Wildcat

15. Elevation (Show whether DF, RT, GR, etc.) 4302' (D. F.)	12. County Roosevelt
--	-------------------------

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:		SUBSEQUENT REPORT OF:	
PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Total Depth - 4650'  
 7 5/8" O. D. Casing Cemented at 360'  
 4 1/2" O. D. Casing Cemented at 4650'

We propose to plug and abandon subject well as follows:

1. Spot 20 Sx. plug from 4350' to 4616', perforations 4436' to 4549'.
2. Cut off and pull 4 1/2" O. D. Casing, cut off spot to be approx. 3000'.
3. Spot 25 Sx. plug 50' into 4 1/2" O. D. Casing stub.
4. Spot 25 Sx. plug 2100' to 2200'. (Top of Salt at 2150').
5. Spot 25 Sx. plug 300' to 400'.
6. Spot 10 Sx. Surface plug inside 7 5/8" O. D. Surface Casing. Clean location for inspection by NMOC, install 4" steel marker extending 4' above ground level. Plug and abandon to be complete on or about Jan. 24, 1966

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED Dan Gillett TITLE Assistant District Superintendent DATE January 19, 1966

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
 CONDITIONS OF APPROVAL, IF ANY: