

Submit 3 Copies  
to Appropriate  
District Office

State of New Mexico  
Energy, Minerals and Natural Resources Department

Form C-103  
Revised 1-1-89

DISTRICT I  
P.O. Box 1980, Hobbs, NM 88240

DISTRICT II  
P.O. Drawer DD, Artesia, NM 88210

DISTRICT III  
1000 Rio Brazos Rd., Aztec, NM 87410

**OIL CONSERVATION DIVISION**  
310 Old Santa Fe Trail, Room 206  
Santa Fe, New Mexico 87503

WELL API NO.	30-025-33160
5. Indicate Type of Lease	STATE <input type="checkbox"/> FEE <input checked="" type="checkbox"/>
6. State Oil & Gas Lease No.	

<b>SUNDRY NOTICES AND REPORTS ON WELLS</b> (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)	
1. Type of Well: OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER	7. Lease Name or Unit Agreement Name GECKO LOWE et. al.
2. Name of Operator GECKO	8. Well No. 1-Y
3. Address of Operator 310 W. Wall, Suite 702, 2B 106 MIDLAND, TEXAS 79701	9. Pool name or Wildcat WILDCAT
4. Well Location Unit Letter <u>C</u> : <u>984</u> Feet From The <u>NORTH</u> Line and <u>2306</u> Feet From The <u>WEST</u> Line Section <u>35</u> Township <u>13S</u> Range <u>37E</u> NMPM <u>LEA</u> County	
10. Elevation (Show whether DF, RKB, RT, GR, etc.) <u>3854'</u> GL	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data	
<b>NOTICE OF INTENTION TO:</b>	<b>SUBSEQUENT REPORT OF:</b>
PERFORM REMEDIAL WORK <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>
OTHER: <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
	CASING TEST AND CEMENT JOB <input type="checkbox"/>
	OTHER: <input type="checkbox"/>

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

1. Cut 8 5/8" casing at 1500' KB.
2. Set 100' stub plug ( 50' into and 50' out of 8 5/8" casing stub). Plug calculated to be 60 sxs of cement. Will tag plug.
3. Set 100' plug ( 50' into and 50' out of ) at 13 3/8" casing shoe @ 496' KB. Plug calculated to be 115 sxs.
4. Set 10 sxs Surface plug.
5. Weld on DH marker.

VERBAL APPROVAL FROM PAUL KAUTZ

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE Steve L. Thomson TITLE PRESIDENT DATE 3/4/97  
TYPE OR PRINT NAME STEVE L. THOMSON TELEPHONE NO. (915) 686-0121

(This space for State Use)

MAR 17 1997

APPROVED BY \_\_\_\_\_ TITLE \_\_\_\_\_ DATE \_\_\_\_\_  
CONDITIONS OF APPROVAL, IF ANY: