

DISTRICT I
P.O. Box 1980, Hobbs, NM 88240DISTRICT II
P.O. Drawer DD, Artesia, NM 88210DISTRICT III
1000 Rio Brazos Rd., Aztec, NM 87410

OIL CONSERVATION DIVISION

P.O. Box 2088

Santa Fe, New Mexico 87504-2088

WELL API NO.	3002502940
5. Indicate Type of Lease	STATE ☒ FEE ☐
6. State Oil & Gas Lease No.	011122
7. Lease Name or Unit Agreement Name	
Central Vacuum Unit	
8. Well No.	2
9. Pool name or Wildcat	Vacuum Grayburg San Andres
10. Elevation (Show whether DF, RKB, RT, GR, etc.)	
3983 DF	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH PROPOSALS.)

1. Type of Well: OIL WELL ☒ GAS WELL ☐ OTHER ☐	2. Name of Operator Texaco E&P Inc.
3. Address of Operator P.O. Box 3109 Midland, Tx 79702	4. Well Location Unit Letter <u>B</u> : <u>330</u> Feet From The <u>North</u> Line and <u>2310</u> Feet From The <u>East</u> Line Section <u>30</u> Township <u>17S</u> Range <u>35E</u> NMPM Lea County
10. Elevation (Show whether DF, RKB, RT, GR, etc.) 3983 DF	

11. Check Appropriate Box to Indicate Nature of Notice, Report, or Other Data.	
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:
PERFORM REMEDIAL WORK ☐	REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐	ALTERING CASING ☐
PULL OR ALTER CASING ☐	COMMENCE DRILLING OPNS. ☐
OTHER: ☐	PLUG AND ABANDONMENT ☒
	CASING TEST AND CEMENT JOB ☐
	OTHER: ☐

12. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- 2-27-95 1. Notify OCD of intent to plug & abandon well.
2-28-95 2. MIRU Pool; TIH w/tub tag cmt. @ 4150. CIRc well w/25# per bbl/salt gel mud. POOH to 3900 Spot 25sx cmt. plug f/3900-3662. WOC & tag next day @ 3662'.
3-1-95 3. TOH to 3000' Spot 45sx cmt. plug f/3000-2538. WOC & tag 2538'.
3-1-95 4. TOH to 1800' Spot 45sx cmt. plug f/1800-1401. WOC & tag next day @ 1401'.
3-3-95 5. TOH to 400' Spot 40sx cmt. plug f/400-surface.
3-3-95 6. ND BOP & dig out cellar; cut off well head; cap well & install dry hole marker. clean location. RD Pool & move off location.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNATURE J. Calder TITLE P&A Supervisor DATE 3-3-95
TYPE OR PRINT NAME J. Calder TELEPHONE NO. _____

(This space for State Use)

APPROVED BY Terry M. Liel OIL & GAS INSPECTOR DATE _____
CONDITIONS OF APPROVAL IF ANY: _____E
SAD