			* 4		
STATE OF NEW MEXICO					
ENERGY AND MINERALS DEPARTMENT					Form C-103
NO. OF COPIES RECEIVED	OIL CONSERVATI	I ON DIVISION			RevI sed 10-1-78
DISTRIBUTION	POST OF FICE				1101, 300 10 1 10
SANTA FE	SANTA FE, NEW				
FILE	SARTA TE, INC.	HEXIOO OTSOT	I	5a. Indicate T	uno of Loaco
U.S.G.S				State X	Fee Fee
LAND OFFICE				5. State 011 &	Gas Lease No.
OPERATOR				SWD-0 033	·
SUNDRY NOTICES AND REPORTS ON WELLS				XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT				XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
RESERVOIR. USE "APPLICATION FOR PERMIT-" (FORM C-101) FOR SUCH PROPOSALS)				XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX	
1. OIL GAS				7. Unit Agreement Name	
WELL WELL	OTHER DISPOS	sal Well			
2. Name of Operator				8. Farm or Lease Name	
Read & Stevens, Inc.				Getty "BG" Stat e	
3. Address of Operator				9. Well No.	
Post Office Box 1518, Roswell, New Mexico 88202				1	
4. Location of Well				10. Field and Pool, or Wildcar	
UNIT LETTER K . 1980 FEET FROM THE South LINE AND 1980 FEET FROM				Quall Queen	
THE West LINE, SECTION		S RANGE	34E NMPM		«xxxxxxxxxxx
×××××××××××××××××××××××××××××××××××××××				12. County	XXXXXXXXXXXXXXXX
XXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXXX			Lea	XXXXXXXXXXXXXXXX	
	opriate Box To Indicate I		Report or Oth		
		- · · · · · · · · · · · · · · · · · · ·			
NOTICE OF INTENT	ION TO:	S	SUBSEQUENT REP	ORT OF:	
	<u> </u>				
PERFORM REMEDIAL WORK	PLUG AND ABANDON XX	REMEDIAL WORK		ALT ERING	CASING
TEMPORARILY ABANDON	CHANGE PLANS	COMMENCE DRILL	ING OPNS.	PLUG AN I	D ABAN DONMENT
PULL OR ALTER CASING		CASING TEST AND			—
OTHER		OTHER			ГТ
					
Describe Proposed or Completed Op	perations (Clearly state	all pertinent deta	alls, and give	pertinent date	es. Including esti-
mated date of starting any propos			, ,	P = (
market take as a second mag and, prosper					
1) Notify NMOCC @ 393-6161,	Hobbs, N.M., 24 hrs before	ore plugging.			
2) Set 8-3/8" pkr @ 2889", s			., .	•	
13.1 PPG, yelld 1.88 cu	ft/sx, compressive stren	g†h € 95° F, 72 hr	rs, 1555psi.	(Hole volume +2	2 5%)
 Circ the hole w/salt gel 	mud, 9.5 PPG.				
4) Spot 1001 plug 30pg Cin	ac HCH cm+ 10001 +a 190	Ol top alva			
4) Spot 100' plug, 30sx Clas	35 "G" CHIF, 1900' TO 180	oo,, rad biug.			
5) Set pkr @ 3751, squeeze v	w/100sx Class "C" cmt.	Leave top of cmt (@ 400¹.		
	•				
Set 10sx surface plug.					

SIGNED

APPROVED BY

7) Install dry hole marker, clean location, prepare for inspection.

DISTRICT I SUPERVISOR TITLE

ORIGINAL SIGNED BY JERRY SEXTON

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

TITLE Drilling and Production Manager DATE December 30, 1986

11987

RECEIVED

JAN 1 1987

OCO OFFICE

HOORS OFFICE

HOUSE TO SEE