

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease
State <input checked="" type="checkbox"/> Fee <input type="checkbox"/>

5. State Oil & Gas Lease No.

A-2614

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER- Plug & Abandon	7. Unit Agreement Name
2. Name of Operator Atlantic Richfield Company	8. Farm or Lease Name McDonald WN State
3. Address of Operator P. O. Box 1710, Hobbs, New Mexico 88240	9. Well No. 13
4. Location of Well UNIT LETTER P 990 FEET FROM THE South LINE AND 990 FEET FROM THE East LINE, SECTION 15 TOWNSHIP 22S RANGE 36E NMPM.	10. Field and Pool, or Wildcat Jalmat Gas
15. Elevation (Show whether DF, RT, GR, etc.) 3541' GR	12. County Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input checked="" type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>

SUBSEQUENT REPORT OF:

REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

TD 3616'. Presently completed open hole 3158-3616'.
12 1/4" 33.38# csg set @ 35' & cmt d w/25 sx to surface.
8-5/8" 24.7# csg set @ 1566' & cmt d w/450 sx & circ to surface.
5 1/2" 17# csg set @ 3158' & cmt d w/450 sx.

This well was swab tested & in two days swabbed 27 bbls water, turned into sales line, well will not flow. No remedial or other recompletion possibilities. Propose to plug & abandon in the following manner: Install BOP. POH w/completion assy. Run 5 1/2" 17# cmt retr & set @ 3100' & cmt w/100 sx Class H cmt. Spot heavy mud-laden fluid between all plugs. Cut 5 1/2" csg from free point & recover. Spot 40 sx cmt across 5 1/2" csg stub. Spot 40 sx cmt across 8-5/8" csg shoe. Spot 10 sx cmt plug @ surface. Erect regulation dry hole marker. Clean & level location.

THE COMMISSION MUST BE NOTIFIED 24 HOURS PRIOR TO THE BEGINNING OF PLUGGING OPERATIONS FOR THE CWS TO BE APPROVED.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED H. J. Berman TITLE Dist. Drlg. Supv. DATE 1/3/75

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: