

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103  
Supersedes Old  
C-102 and C-103  
Effective 1-1-65

5a. Indicate Type of Lease  
State  Fee

5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Imperial-American Management Co.	8. Farm or Lease Name Merry Christmas
3. Address of Operator 507 Midland Savings Bldg., Midland, Texas 79701	9. Well No. 1
4. Location of Well UNIT LETTER <u>L</u> <u>660</u> FEET FROM THE <u>West</u> LINE AND <u>1980</u> FEET FROM THE <u>South</u> LINE, SECTION <u>30</u> TOWNSHIP <u>21-S</u> RANGE <u>38-E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) GR 3414'	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data  
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input checked="" type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <input type="checkbox"/>	CASING TEST AND CEMENT JQB <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Plugged & Abandoned Well as follows:

1. Unable to recover Otis Permatrieve Packer @ 7090'. Left same in hole.
2. Set 30 sx cement plug 6900-7058'.
3. Set 30 sx cement plug 6450-6600'.
4. Shot off 7" csg @ 2400'. Pulled same.
5. Set 40 sx cmt plug 2600-2700'.
6. Set 40 sx cement plug 1520-1620'.
7. Set 45 sx cement plug 860-960' (1/2 in - 1/2 out surface csg.)
8. Set 10 sx cement plug 0-25'.
9. Installed marker and cleaned up location.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED David L. King TITLE Operations Supt. DATE 6-19-70

APPROVED BY John W. Ramsey TITLE Geologist DATE 6-21-70

CONDITIONS OF APPROVAL, IF ANY:

RECEIVED

JUN 23 1970

OIL CONSERVATION COMM.  
HOBBS, N. M.