

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.O.S.		
LAND OFFICE		
OPERATOR		

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-

5a. Indicate Type of Lease
State ☐ Fed ☒
5. State Oil & Gas Lease No.

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

OIL WELL ☒ GAS WELL ☐ OTHER ☐

7. Unit Agreement Name
Central Drinkard Unit

8. Farm or Lease Name

9. Well No.
413

10. Field and Pool, or Wildcat
Drinkard

Name of Operator

Gulf Oil Corporation

Address of Operator

P. O. Box 670, Hobbs, NM 88240

Location of Well

UNIT LETTER B, 910 FEET FROM THE North LINE AND 1857 FEET FROM
THE East LINE, SECTION 29 TOWNSHIP 21S RANGE 37E NMPM.

15. Elevation (Show whether DF, RT, GR, etc.)
3472' GL

12. County
Lea

Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK ☐
TEMPORARILY ABANDON ☐
PULL OR ALTER CASING ☐

PLUG AND ABANDON ☐
CHANGE PLANS ☐

REMEDIAL WORK ☐
COMMENCE DRILLING OPNS. ☐
CASING TEST AND CEMENT JOB ☐
OTHER ☐

ALTERING CASING ☐
PLUG AND ABANDONMENT ☐

OTHER Recondition Drinkard ☒

7. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

Acidize with 2000 gals 20% NEFE HCL acid. Swab and test well. POH with production equipment. Tag up plug back. Plug back to 6434' with frac sand; cap frac sand with 4' Calseal to 6430'. Tag up plug back. Perf 6420'-6422' with (2) 1/2" JHPF. Acidize with 1000 gals 20% NEFE slick HCL. Swab and test. Frac well.

I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED RDP the TITLE Area Engineer DATE 11-12-81

PROVED BY Orig. Signed by Jerry Sexton TITLE Dist. J. Supp. DATE 1981

CONDITIONS OF APPROVAL, IF ANY: