

OIL CONSERVATION DIVISION

P. O. BOX 2088
SANTA FE, NEW MEXICO 87501

Form C-103
Revised 10-1-78

NO. OF COPIES RECEIVED	
DISTRIBUTION	
SANTA FE	
FILE	
U.S.G.S.	
LAND OFFICE	
OPERATOR	

5a. Indicate Type of Lease
State Fee
5. State Oil & Gas Lease No.
E-2446

SUNDRY NOTICES AND REPORTS ON WELLS
(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT - " (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input type="checkbox"/> GAS WELL <input checked="" type="checkbox"/> OTHER <input type="checkbox"/>	7. Unit Agreement Name
2. Name of Operator Pogo Producing Company	8. Farm or Lease Name State C
3. Address of Operator P.O. Box 10340 Midland, Texas 79702	9. Well No. 3-Y
4. Location of Well UNIT LETTER <u>K</u> , <u>1980</u> FEET FROM THE <u>South</u> LINE AND <u>2310</u> FEET FROM THE <u>West</u> LINE, SECTION <u>20</u> TOWNSHIP <u>21-S</u> RANGE <u>35-E</u> NMPM.	10. Field and Pool, or Wildcat Undesignated
15. Elevation (Show whether DF, RT, GR, etc.) 3624.5 Ground	12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data
NOTICE OF INTENTION TO: SUBSEQUENT REPORT OF:

PERFORM REMEDIAL WORK <input type="checkbox"/>	PLUG AND ABANDON <input type="checkbox"/>	REMEDIAL WORK <input type="checkbox"/>	ALTERING CASING <input type="checkbox"/>
TEMPORARILY ABANDON <input type="checkbox"/>	CHANGE PLANS <input type="checkbox"/>	COMMENCE DRILLING OPNS. <input type="checkbox"/>	PLUG AND ABANDONMENT <input type="checkbox"/>
PULL OR ALTER CASING <input type="checkbox"/>	OTHER <u>Salvage Casing and P & A</u> <input checked="" type="checkbox"/>	CASING TEST AND CEMENT JOBS <input type="checkbox"/>	OTHER <input type="checkbox"/>

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

- Rig casing pullers. Remove wellhead. Run freepoint, cut 7 5/8" csg and recover. (TOC @ 9100').
- Run freepoint on 10 3/4" csg. Cut and pull casing. (TOC @ 2600' survey).
- RIH work string and spot following cement plugs:
 - 100' plug 10,790' to 10,690'.
 - 100' plug 50' above 7 5/8" stub & 50' in csg.
 - 100' plug 5715' to 5615'.
 - 100' plug 50' above 10 3/4" stub & 50' in csg.
 - 100' plug 1620' to 1520'.
 - 10 sxs @ surface.
- Cut off 13 3/8" csg, weld on plate & marker.
P & A procedure discussed with and approved by Jerry Sexton NMOC.D.

THE COMMISSIONER OF THE STATE OF NEW MEXICO HAS ORDERED THAT THE ABOVE MENTIONED OPERATIONS BE STOPPED IMMEDIATELY UNTIL SUCH TIME AS THE OPERATOR HAS OBTAINED THE NECESSARY PERMITS FROM THE COMMISSIONER.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

SIGNED [Signature] TITLE Division Operations Manager DATE 1/24/85

APPROVED BY JERRY SEXTON DISTRICT I SUPERVISOR TITLE _____ DATE JAN 28 1985

CONDITIONS OF APPROVAL, IF ANY: