

NO. OF COPIES RECEIVED		
DISTRIBUTION		
SANTA FE		
FILE		
U.S.G.S.		
LAND OFFICE		
OPERATOR		

NEW MEXICO OIL CONSERVATION COMMISSION

Form C-103
Supersedes Old
C-102 and C-103
Effective 1-1-65

5a. Indicate Type of Lease	
State <input type="checkbox"/>	Fee <input checked="" type="checkbox"/>
5. State Oil & Gas Lease No.	
7. Unit Agreement Name	
8. Farm or Lease Name	
9. Well No.	
10. Field and Pool, or Wildcat	
12. County	

SUNDRY NOTICES AND REPORTS ON WELLS

(DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT -" (FORM C-101) FOR SUCH PROPOSALS.)

1. OIL WELL <input checked="" type="checkbox"/> GAS WELL <input type="checkbox"/> OTHER <input type="checkbox"/>
2. Name of Operator Skelly Oil Company
3. Address of Operator P. O. Box 1351, Midland, Texas 79701
4. Location of Well UNIT LETTER K 1980 FEET FROM THE West LINE AND 2130 FEET FROM THE South LINE, SECTION 10 TOWNSHIP 22S RANGE 37E NMPM.
15. Elevation (Show whether DF, RT, GR, etc.) 3411' DF

7. Unit Agreement Name
8. Farm or Lease Name Baker "B"
9. Well No. 8
10. Field and Pool, or Wildcat Drinkard
12. County Lea

16. Check Appropriate Box To Indicate Nature of Notice, Report or Other Data

NOTICE OF INTENTION TO:

- PERFORM REMEDIAL WORK
- TEMPORARILY ABANDON
- PULL OR ALTER CASING
- PLUG AND ABANDON
- CHANGE PLANS

OTHER **Shut off lower Drinkard perforations and perforate in Upper Drinkard**

SUBSEQUENT REPORT OF:

- REMEDIAL WORK
- COMMENCE DRILLING OPNS.
- CASING TEST AND CEMENT JOB
- OTHER
- ALTERING CASING
- PLUG AND ABANDONMENT

17. Describe Proposed or Completed Operations (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work) SEE RULE 1103.

We propose to temporarily abandon the Lower Drinkard perforations 6475-6510', and perforate the Upper Drinkard at approximately 6353-6441' as follows:

- 1) Move in pulling unit. Pull tubing and rods.
- 2) Run Gamma Ray-Neutron Correlation Log.
- 3) Set cast iron bridge plug at approximately 6450'.
- 4) Perforate Upper Drinkard at approximately 6353-6441', as indicated by Gamma Ray-Neutron Log.
- 5) Run tubing and packer.
- 6) Treat Upper Drinkard perforations with 2000 gallons of acid.
- 7) Pull tubing and packer.
- 8) Run tubing and swab test Upper Drinkard perforations.
- 9) If well will not flow, run rods and pump.
- 10) Connect to flow line and return well to production.

18. I hereby certify that the information above is true and complete to the best of my knowledge and belief.

(Signed) **D. R. Crow**

SIGNED D.R.Crow TITLE Lead Clerk DATE April 30, 1973

APPROVED BY _____ TITLE _____ DATE _____

CONDITIONS OF APPROVAL, IF ANY: