## NEW MEXICO OIL CONSERVATION COMMISSION

Santa Fe, New Mexico

## MISCELLANEOUS NOTICES

Submit this notice in TRIPLICATE to the District Office, Oil Conservation Commission, before the work specified is to begin. A const will be returned to the sender on which will be given the approval, with any modifications considered advisable, or the rejection by the Commission or agent, of the plan submitted. The plan as approved should be followed, and work should not begin until approval is obtained. See additional instructions in the Rules and Regulations of the Commission.

		Indicate Nature o	n. f Notice by Check	ing Below	
Notice of Intention to Change Plans		Notice of Intenti Temporarily Abai		Notice of Intention to Drill Deeper	
Notice of Intention to Plug Well	Х	Notice of Intent	ion	Notice of Intention to Set Liner	
Notice of Intention to Squeeze		Notice of Intent to Acidize	rion	Notice of Intention to Shoot (Nitro)	
Notice of Intention to Gun Perforate		Notice of Intent (Other)	TION	Notice of Intention (Other)	
OIL CONSERVATIO SANTA FE, NEW ME		Hobbs,	New Nexico	) Ay 5 1955	
Gentlemen:					
				State "Y"	
Stanolind	Oil and C	as Company		Well No. 15 in H.	 it)
SE 4 NE		T. 24=5	, R. 38-E,I	мрм, Dollarhide	Poo
	n)				
	(FOLL) was	drilled to Tr	in the rules ) 38 <b>15 and</b>	and regulations) encountering no comme cial andon well as follows:	
Depth	Amount Cement		-		
		Cement		sack plug in bottom. Sho	ot
35181	25 sack		off 5½ ( casing a	easing at free point, pull and set 15 sack plug in stu	b
3518† 1500 <b>†</b>	25 sack	S	off $5\frac{1}{2}$ (casing a at approset at a	casing at free point, pull and set 15 sack plug in stu- exicately 1000' with 10 sac surface. Rell core to be f	b ks i.l <b>1-</b>
• •	,	ss	off 5½ casing a at approset at a ed with subseque	easing at free point, pull and set 15 sack plug in stu- eximately 1000' with 10 sac	b ks ill-
1590' Surface	15 sack	ss	off 52 casing a at approset at a pore set at a ed with subseque complet.	casing at free point, pull and set 15 sack plug in stuck at ely 1000' with 10 sack purface. Rell ore to be fourface. Rell ore to be fourface. Rell ore to be four material. Interport will be alled after on of work.  Original Signed by Company	b ks i.l <b>1-</b> A t⊕r
l 200 'Surface	15 sack	ss ss	off 5½ (casing a at approset at approset at a ed with subseque complet).  Stanol  By	casing at free point, pull and set 15 sack flug in stuck ately 1000' with 10 sack flug in stuck ately 1000' with 10 sack flug in the first section of the section of will be riled at the confidence of the section of t	b ks i.l <b>1-</b> A t⊕r
1,00° Surface	15 sack		off 5½ (casing a at approset at approset at a ed with subseque complet).  Stanol  By	casing at free point, pull and set 15 sack plug in stuck at ely 1000' with 10 sack purface. Rell ore to be fourface. Rell ore to be fourface. Rell ore to be four material. Interport will be alled after on of work.  Original Signed by Company	b ks i.l <b>1-</b> A t⊕r
Surface  Approved	15 sack		off 52 (casing a at approset at approset at a ed with subseque complet).  Stanol  By	casing at free point, pull and set 15 sack plug in stucted at 1000 with 10 sack purface. Well ore to be fourface. Well ore to be fourface. Well ore to be fourface. Well be alred at on of work.  Ind Dil and Cas Company or Operator Original Signed by Original Signed by Other Land Company or Operator Original Signed by Other Land Cas Company or Operator Original Signed by Other Land Cas Company or Operator Original Signed by Other Land Cas Company or Operator Original Signed by Other Land Cas Company or Operator Original Signed by Other Land Cas Company or Operator Original Signed by Other Cas Company or Operator Original Signed by Other Cas Company or Operator Op	b ks i.ll- A ter