

State of New Mexico  
Energy Minerals and Natural Resources  
Department Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
<https://www.emnrd.nm.gov/ocd/ocd-e-permitting/>

Form C-147  
Revised October 11, 2022

## Recycling Facility and/or Recycling Containment

**Type of Facility:** ☐ Recycling Facility ☐ Recycling Containment\*  
**Type of action:** ☐ Permit ☐ Registration  
☐ Modification ☒ Extension  
☐ Closure ☒ Other (explain) Cessation of Operations Request from 03-31-2025 - 09-30-2025

**\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.  
 Operator: OWL SWD Operating LLC (For multiple operators attach page with information) OGRID #: 308339  
 Address: 20 Greenway Plaza, Suite 500 Houston, TX 77046  
 Facility or well name (include API# if associated with a well): Javelina Facility AST  
 OCD Permit Number: 1RF-463 (For new facilities the permit number will be assigned by the district office)  
 U/L or Qtr/Qtr E1/2 pf NE1/4 Section 18 Township 26 South Range 35 East County: Lea County  
 Surface Owner: ☒ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.  
☒ **Recycling Facility:**  
 Location of recycling facility (if applicable): Latitude 32.048956 Longitude -103.401212 NAD83  
 Proposed Use: ☐ Drilling\* ☒ Completion\* ☐ Production\* ☐ Plugging\*  
*\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented*  
☐ Other, *requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.*  
☒ Fluid Storage  
☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type \_\_\_\_\_  
☐ Activity permitted under 19.15.36 NMAC explain type: \_\_\_\_\_ ☐ Other explain \_\_\_\_\_  
☐ For multiple or additional recycling containments, attach design and location information of each containment  
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: \_\_\_\_\_

3.  
☒ **Recycling Containment:**  
☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)  
 Center of Recycling Containment (if applicable): Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ NAD83  
☐ For multiple or additional recycling containments, attach design and location information of each containment  
☐ Lined ☐ Liner type: Thickness 60/40 mil ☐ LLDPE ☒ HDPE ☐ PVC ☐ Other With Leak Detection  
☐ String-Reinforced Round AST: 190' Diameter  
 Liner Seams: ☐ Welded ☐ Factory ☐ Other \_\_\_\_\_ Volume: 48,000 bbl Dimensions: L \_\_\_\_\_ x W \_\_\_\_\_ x D \_\_\_\_\_  
☐ Recycling Containment Closure Completion Date: \_\_\_\_\_

4.

**Bonding:**

- ☐ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☒ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ 58,000 (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify 6' Chain Link Dence

6.

**Signs:**

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

***Check the below box only if a variance is requested:***

☐ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

**Instructions:** The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

**General siting****Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No  
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No  
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

**Recycling Facility and/or Containment Checklist:**

**Instructions:** Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☐ Design Plan - based upon the appropriate requirements.
- ☐ Operating and Maintenance Plan - based upon the appropriate requirements.
- ☐ Closure Plan - based upon the appropriate requirements.
- ☐ Site Specific Groundwater Data -
- ☐ Siting Criteria Compliance Demonstrations –
- ☐ **Certify that notice of the C-147 (only) has been sent to the surface owner(s)**

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): David Grounds Title: VP Regulatory  
Signature: David Grounds Date: 04/14/2025  
e-mail address: David.Grounds@pilotwater.com Telephone: (817) 897-0135

11.

OCD Representative Signature: Victoria Venegas Approval Date: 04/17/2025

Title: Environmental Specialist OCD Permit Number: 1RF-463

- ☒ OCD Conditions \_\_\_\_\_
- ☒ Additional OCD Conditions on Attachment \_\_\_\_\_

State of New Mexico  
Energy Minerals and Natural Resources  
Department Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
<https://www.emnrd.nm.gov/ocd/ocd-e-permitting/>

Form C-147  
Revised October 11, 2022

## Recycling Facility and/or Recycling Containment

**Type of Facility:** ☐ Recycling Facility ☐ Recycling Containment\*

**Type of action:** ☐ Permit  
☐ Modification  
☐ Closure

☐ Registration

☒ Extension

☒ Other (explain) Cessation of Operations Request from 03-

**\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.

Operator: OWL SWD Operating LLC (For multiple operators attach page with information) OGRID #: 308339

Address: 20 Greenway Plaza, Suite 500 Houston, TX 77046

Facility or well name (include API# if associated with a well): Javelina Facility North Pit

OCD Permit Number: 1RF-463 (For new facilities the permit number will be assigned by the district office)

U/L or Qtr/Qtr E1/2 of NE1/4 Section 18 Township 26 South Range 35 East County: Lea County

Surface Owner: ☐ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.

☒ **Recycling Facility:**

Location of recycling facility (if applicable): Latitude 32.048477 Longitude -103.400286 NAD83

Proposed Use: ☐ Drilling\* ☒ Completion\* ☐ Production\* ☐ Plugging \*

*\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented*

☐ Other, *requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.*

☒ Fluid Storage

☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type \_\_\_\_\_

☐ Activity permitted under 19.15.36 NMAC explain type: \_\_\_\_\_ ☐ Other explain \_\_\_\_\_

☐ For multiple or additional recycling containments, attach design and location information of each containment

☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: \_\_\_\_\_

3.

☒ **Recycling Containment:**

☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)

Center of Recycling Containment (if applicable): Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ NAD83

☐ For multiple or additional recycling containments, attach design and location information of each containment

☒ Lined ☐ Liner type: Thickness 60/40 mil ☐ LLDPE ☒ HDPE ☐ PVC ☐ Other With Leak Detection

☐ String-Reinforced

Liner Seams: ☒ Welded ☐ Factory ☐ Other \_\_\_\_\_ Volume: 346,000 bbl Dimensions: L 320 x W 565 x D 18

☐ Recycling Containment Closure Completion Date: \_\_\_\_\_

4.

**Bonding:**

- ☐ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☒ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ 442,500 (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify 6' Chain Link Fence

6.

**Signs:**

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

***Check the below box only if a variance is requested:***

- ☐ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

**Instructions:** The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

**General siting****Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No  
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No  
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site

9.

**Recycling Facility and/or Containment Checklist:****Instructions:** Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☐ Design Plan - based upon the appropriate requirements.  
☐ Operating and Maintenance Plan - based upon the appropriate requirements.  
☐ Closure Plan - based upon the appropriate requirements.  
☐ Site Specific Groundwater Data -  
☐ Siting Criteria Compliance Demonstrations –  
☐ **Certify that notice of the C-147 (only) has been sent to the surface owner(s)**

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): David Grounds Title: VP RegulatorySignature: David Grounds Date: \_\_\_\_\_e-mail address: David.Grounds@pilotwater.com Telephone: (817) 897-0135

11.

OCD Representative Signature: Victoria Venegas Approval Date: 04/17/2025Title: Environmental Specialist OCD Permit Number: 1RF-463☒ OCD Conditions \_\_\_\_\_☒ Additional OCD Conditions on Attachment

State of New Mexico  
Energy Minerals and Natural Resources  
Department Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505  
<https://www.emnrd.nm.gov/ocd/ocd-e-permitting/>

Form C-147  
Revised October 11, 2022

## Recycling Facility and/or Recycling Containment

**Type of Facility:** ☐ Recycling Facility ☐ Recycling Containment\*  
**Type of action:** ☐ Permit ☐ Registration  
☐ Modification ☒ Extension  
☐ Closure ☒ Other (explain) Cessation of Operations Request from 03-31-2025 - 09-30-2025

**\* At the time C-147 is submitted to the division for a Recycling Containment, a copy shall be provided to the surface owner.**

Be advised that approval of this request does not relieve the operator of liability should operations result in pollution of surface water, ground water or the environment. Nor does approval relieve the operator of its responsibility to comply with any other applicable governmental authority's rules, regulations or ordinances.

1.  
 Operator: OWL SWD Operating LLC (For multiple operators attach page with information) OGRID #: 308339  
 Address: 20 Greenway Plaza, Suite 500 Houston, TX 77046  
 Facility or well name (include API# if associated with a well): Javelina Facility South Pit  
 OCD Permit Number: 1RF-463 (For new facilities the permit number will be assigned by the district office)  
 U/L or Qtr/Qtr E1/2 of NE1/4 Section 18 Township 26 South Range 35 East County: Lea County  
 Surface Owner: ☐ Federal ☐ State ☐ Private ☐ Tribal Trust or Indian Allotment

2.  
☒ **Recycling Facility:**  
 Location of recycling facility (if applicable): Latitude 32.046680 Longitude -103.400658 NAD83  
 Proposed Use: ☐ Drilling\* ☒ Completion\* ☐ Production\* ☐ Plugging \*  
*\*The re-use of produced water may NOT be used until fresh water zones are cased and cemented*  
☐ Other, *requires permit for other uses. Describe use, process, testing, volume of produced water and ensure there will be no adverse impact on groundwater or surface water.*  
☒ Fluid Storage  
☒ Above ground tanks ☒ Recycling containment ☐ Activity permitted under 19.15.17 NMAC explain type \_\_\_\_\_  
☐ Activity permitted under 19.15.36 NMAC explain type: \_\_\_\_\_ ☐ Other explain \_\_\_\_\_  
☐ For multiple or additional recycling containments, attach design and location information of each containment  
☐ **Closure Report (required within 60 days of closure completion):** ☐ Recycling Facility Closure Completion Date: \_\_\_\_\_

3.  
☒ **Recycling Containment:**  
☐ Annual Extension after initial 5 years (attach summary of monthly leak detection inspections for previous year)  
 Center of Recycling Containment (if applicable): Latitude \_\_\_\_\_ Longitude \_\_\_\_\_ NAD83  
☐ For multiple or additional recycling containments, attach design and location information of each containment  
☒ Lined ☐ Liner type: Thickness 60/40 mil ☐ LLDPE ☐ HDPE ☐ PVC ☐ Other With Leak Detection  
☐ String-Reinforced  
 Liner Seams: ☒ Welded ☐ Factory ☐ Other \_\_\_\_\_ Volume: 512,000 bbl Dimensions: L 500' x W 500' x D 18'  
☐ Recycling Containment Closure Completion Date: \_\_\_\_\_



4.

**Bonding:**

- ☐ Covered under bonding pursuant to 19.15.8 NMAC per 19.15.34.15(A)(2) NMAC (These containments are limited to only the wells owned or operated by the owners of the containment.)
- ☒ Bonding in accordance with 19.15.34.15(A)(1). Amount of bond \$ 654,000 (work on these facilities cannot commence until bonding amounts are approved)
- ☐ Attach closure cost estimate and documentation on how the closure cost was calculated.

5.

**Fencing:**

- ☐ Four foot height, four strands of barbed wire evenly spaced between one and four feet
- ☒ Alternate. Please specify 6' Chain Link Fence

6.

**Signs:**

- ☒ 12"x 24", 2" lettering, providing Operator's name, site location, and emergency telephone numbers
- ☐ Signed in compliance with 19.15.16.8 NMAC

7.

**Variances:**

Justifications and/or demonstrations that the proposed variance will afford reasonable protection against contamination of fresh water, human health, and the environment.

***Check the below box only if a variance is requested:***

- ☐ Variance(s): Requests must be submitted to the appropriate division district for consideration of approval. If a Variance is requested, include the variance information on a separate page and attach it to the C-147 as part of the application.

**If a Variance is requested, it must be approved prior to implementation.**

8.

**Siting Criteria for Recycling Containment**

**Instructions:** The applicant must provide attachments that demonstrate compliance for each siting criteria below as part of the application. Potential examples of the siting attachment source material are provided below under each criteria.

**General siting****Ground water is less than 50 feet below the bottom of the Recycling Containment.**

NM Office of the State Engineer - iWATERS database search; USGS; Data obtained from nearby wells

☐ Yes ☒ No  
☐ NA

Within incorporated municipal boundaries or within a defined municipal fresh water well field covered under a municipal ordinance adopted pursuant to NMSA 1978, Section 3-27-3, as amended.

☐ Yes ☒ No  
☐ NA

- Written confirmation or verification from the municipality; written approval obtained from the municipality

Within the area overlying a subsurface mine.

☐ Yes ☒ No

- Written confirmation or verification or map from the NM EMNRD-Mining and Minerals Division

Within an unstable area.

☐ Yes ☒ No

- Engineering measures incorporated into the design; NM Bureau of Geology & Mineral Resources; USGS; NM Geological Society; topographic map

Within a 100-year floodplain. FEMA map

☐ Yes ☒ No

Within 300 feet of a continuously flowing watercourse, or 200 feet of any other significant watercourse, or lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark).

☐ Yes ☒ No

- Topographic map; visual inspection (certification) of the proposed site

Within 1000 feet from a permanent residence, school, hospital, institution, or church in existence at the time of initial application.

☐ Yes ☒ No

- Visual inspection (certification) of the proposed site; aerial photo; satellite image

Within 500 horizontal feet of a spring or a fresh water well used for domestic or stock watering purposes, in existence at the time of initial application.

☐ Yes ☒ No

- NM Office of the State Engineer - iWATERS database search; visual inspection (certification) of the proposed site

Within 500 feet of a wetland.

☐ Yes ☒ No

- US Fish and Wildlife Wetland Identification map; topographic map; visual inspection (certification) of the proposed site



9.

**Recycling Facility and/or Containment Checklist:****Instructions:** Each of the following items must be attached to the application. Indicate, by a check mark in the box, that the documents are attached.

- ☐ Design Plan - based upon the appropriate requirements.  
☐ Operating and Maintenance Plan - based upon the appropriate requirements.  
☐ Closure Plan - based upon the appropriate requirements.  
☐ Site Specific Groundwater Data -  
☐ Siting Criteria Compliance Demonstrations –  
☐ **Certify that notice of the C-147 (only) has been sent to the surface owner(s)**

10.

**Operator Application Certification:**

I hereby certify that the information and attachments submitted with this application are true, accurate and complete to the best of my knowledge and belief.

Name (Print): David Grounds Title: VP Regulatory  
 Signature: David Grounds Date: 04/16/2025  
 e-mail address: David.Grounds@pilotwater.com Telephone: (817) 897-0135

11.

OCD Representative Signature: Victoria Venegas Approval Date: 04/17/2025

Title: Environmental Specialist OCD Permit Number: 1RF-463

- ☒ OCD Conditions \_\_\_\_\_  
☒ Additional OCD Conditions on Attachment



## New Mexico Recycling Facility Monthly Inspection

## Location

Submitted By

[Omar Portillo](#)*Location was not collected for this report.*

Surrogate

[Omar Portillo](#)

Started On January 8 2025, 2:41pm

Submitted On January 8 2025, 2:57pm (17 minutes)

Weather NaN°,

Version V1 (latest)

Updated January 8 2025, 2:57pm

Report No. 51478772

## New Mexico Recycling Facility Monthly Inspection

## GENERAL DETAILS

Date January 8th 2025 2:47 PM

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

## INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? Yes

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No

## EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

## SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	No
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	No
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes
Comments	Bird deterrent needs a new battery

## TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

## SUMMARY

# of Action Item(s)	1
---------------------	---

1

Inspector	<a href="#">Omar Portillo (Terminated)</a>
Signature	None

Generated Thursday, April 3rd 2025, 11:37am CDT.

powered by  KPA



## New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On November 5 2024, 12:29pm

Submitted On November 5 2024, 12:32pm (2 minutes)

Weather 61°, clear

Version V1 (latest)

Updated November 5 2024, 12:32pm

Report No. 48688541

## Location



## New Mexico Recycling Facility Monthly Inspection

### GENERAL DETAILS

Date November 5th 2024 12:29 PM

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

### INLET AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? Yes

How many inches? 2"

### EFFLUENT AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

### SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible?	Yes
Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


## TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

## SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



Generated Thursday, April 3rd 2025, 11:38am CDT.

powered by  KPA



## New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On September 30 2024, 10:36am

Submitted On September 30 2024, 10:38am (2 minutes)

Weather 70°, clear

Version V1 (latest)

Updated September 30 2024, 10:38am

Report No. 46932281

## Location



## New Mexico Recycling Facility Monthly Inspection

### GENERAL DETAILS

Date September 30th 2024 10:36 AM

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

### INLET AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? Yes

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No

### EFFLUENT AST

Is there fluid in the leak detection system? No

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

### SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible? Yes

Is pond level sensor working?	Yes
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


## TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

## SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Nevarez</a>

Signature



Generated Thursday, April 3rd 2025, 11:39am CDT.

powered by  KPA





## New Mexico Recycling Facility Monthly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On October 9 2024, 10:07am

Submitted On October 9 2024, 10:13am (6 minutes)

Weather 72°, clear

Version V1 (latest)

Updated October 9 2024, 10:13am

Report No. 47406712

## Location



## New Mexico Recycling Facility Monthly Inspection

### GENERAL DETAILS

Date October 9th 2024 10:07 AM

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

### INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? Yes

How many inches? 1"

### EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

### SOUTH POND

Is there fluid in the leak detection system? No

Are pond level markers visible?	Yes
Is pond level sensor working?	No
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


## TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

## SUMMARY

# of Action Item(s)	0
Inspector	None

Signature



Generated Thursday, April 3rd 2025, 11:39am CDT.

powered by  KPA



## New Mexico Recycling Facility Monthly Inspection

## Location

Submitted By

[Mario Lopez](#)

Location was not collected for this report.

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 9:33am

Submitted On April 10 2025, 9:35am (3 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 9:35am

Report No. 56747741

## New Mexico Recycling Facility Monthly Inspection

## GENERAL DETAILS

Date February 10th 2025 9:33 AM CST

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

## INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No

## EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

Comments Not in use

## SOUTH POND

Is there fluid in the leak detection system? Yes

Has the fluid been pumped out or is it scheduled?	Yes
Are pond level markers visible?	Yes
Is pond level sensor working?	N/A
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

**TREATMENT FACILITY**

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

**SUMMARY**

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>

Signature



Generated Monday, April 14th 2025, 12:11pm CDT.

powered by  KPA



## New Mexico Recycling Facility Monthly Inspection

## Location

Submitted By

[Mario Lopez](#)

Location was not collected for this report.

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 9:36am

Submitted On April 10 2025, 3:51pm (6 hours)

Weather NaN°,

Version V2 (latest)

Updated April 10 2025, 4:29pm

Report No. 56780234

## New Mexico Recycling Facility Monthly Inspection

### GENERAL DETAILS

Date March 22nd 2025 9:36 AM CDT

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

### INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No

### EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is there any evidence of cracking or subsidence of the pad around the AST? No

Comments Not in use





### SOUTH POND

Is there fluid in the leak detection system? Yes

Has the fluid been pumped out or is it scheduled?	Yes
Are pond level markers visible?	Yes
Is pond level sensor working?	N/A
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	No
Is pond aeration system functional?	Yes
Comments	missing life vest, will get replacement

## TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	Yes



Any evidence of erosion on the outside slope of the facility?	No
Comments	Liner sustained some wind damage and we've completed repairs

SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>

Signature







## New Mexico Recycling Facility Monthly Inspection

## Location

Submitted By

[Mario Lopez](#)

Location was not collected for this report.

Surrogate

[Mario Lopez](#)

Started On April 8 2025, 1:46pm

Submitted On April 9 2025, 9:11am (19 hours)

Weather NaN°,

Version V1 (latest)

Updated April 9 2025, 9:11am

Report No. 56673885

## New Mexico Recycling Facility Monthly Inspection

## GENERAL DETAILS

Date April 9th 2025 8:44 AM CDT

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

## INLET AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? No

Is bird netting in good condition? N/A

Is there any evidence of cracking or subsidence of the pad around the AST? No

Is there oil to be skimmed? No


## EFFLUENT AST

Is there fluid in the leak detection system? N/A

Any migratory birds or wildlife discovered in the AST? N/A


Is there any evidence of cracking or subsidence of the pad around the AST? N/A

## SOUTH POND



Is there fluid in the leak detection system?	Yes
Has the fluid been pumped out or is it scheduled?	N/A
Are pond level markers visible?	Yes
Is pond level sensor working?	N/A
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	No
Is pond aeration system functional?	Yes

## TREATMENT FACILITY




Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	Yes
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No

Any evidence of erosion on the outside slope of the facility?	N/A
Comments	We are working on getting quotes to fix berm around facility

SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>

Signature



Generated Monday, April 14th 2025, 12:15pm CDT.


powered by  KPA



New Mexico Recycling Facility Monthly Inspection


Location

Submitted By



[Mario Lopez](#)

Surrogate



[Mario Lopez](#)

Started On

April 10 2025, 9:30am

Submitted On

April 10 2025, 9:33am (2 minutes)

Weather

NaN°

Version

V1 (latest)

Updated

April 10 2025, 9:33am

Report No.

56747527

Location was not collected for this report.

New Mexico Recycling Facility Monthly Inspection

GENERAL DETAILS

Date

December 10th 2024 9:30 AM CST

Area

[New Mexico](#)

Recycle Facility

[JAVELINA RECYCLE FACILITY](#)

INLET AST

Is there fluid in the leak detection system?

N/A

Any migratory birds or wildlife discovered in the AST?

No

Is bird netting in good condition?

N/A

Is there any evidence of cracking or subsidence of the pad around the AST?

No

Is there oil to be skimmed?

No

EFFLUENT AST

Is there fluid in the leak detection system?

N/A

Any migratory birds or wildlife discovered in the AST?

No

Is there any evidence of cracking or subsidence of the pad around the AST?

N/A

Comments

Not in use

SOUTH POND

Is there fluid in the leak detection system?

Yes

Has the fluid been pumped out or is it scheduled?	Yes
Are pond level markers visible?	Yes
Is pond level sensor working?	N/A
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes

## TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

## SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>
Signature	

Generated Monday, April 14th 2025, 12:11pm CDT.

powered by  KPA



## New Mexico Recycling Facility Monthly Inspection

Submitted By

[Omar Portillo](#)

Surrogate

[Omar Portillo](#)

Started On January 28 2025, 1:35pm

Submitted On January 28 2025, 1:36pm (a minute)

Weather 44°, cloudy

Version V1 (latest)

Updated January 28 2025, 1:36pm

Report No. 52452906

## Location



## New Mexico Recycling Facility Monthly Inspection

### GENERAL DETAILS

Date	January 28th 2025 1:35 PM
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

### INLET AST

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	No
Is bird netting in good condition?	N/A
Is there any evidence of cracking or subsidence of the pad around the AST?	No
Is there oil to be skimmed?	No

### EFFLUENT AST

Is there fluid in the leak detection system?	N/A
Any migratory birds or wildlife discovered in the AST?	No
Is there any evidence of cracking or subsidence of the pad around the AST?	No

### SOUTH POND

Is there fluid in the leak detection system?	No
Are pond level markers visible?	Yes

Is pond level sensor working?	No
Is there any visible damage to the pond liner?	No
Any migratory birds or wildlife discovered in the pond?	No
Is bird deterrent working?	Yes
Is there any evidence of cracking or subsidence around the pond berm?	No
Is there any erosion on the outside of the berm?	No
Is life vest and related pond safety equipment in working condition?	Yes
Is pond aeration system functional?	Yes


## TREATMENT FACILITY

Is fencing and cattleguard in good condition?	Yes
Is there any evidence of spills or soil staining that have not been cleaned up?	No
Any migratory birds or wildlife discovered in the facility?	No
Are there any holes found in the containment liner?	No
Any evidence of erosion on the outside slope of the facility?	No

## SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Omar Portillo (Terminated)</a>

Signature



Generated Thursday, April 3rd 2025, 11:35am CDT.

powered by  KPA





## New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On September 23 2024, 11:00am

Submitted On September 23 2024, 11:04am (3 minutes)


Weather 63°, cloudy

Version V1 (latest)

Updated September 23 2024, 11:04am

Report No. 46594845

## Location



## New Mexico Recycling Facility Weekly Inspection

## GENERAL DETAILS

Date September 23rd 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

## WEEKLY INSPECTION

Read and record the fluid height of staff gauges 10'

Does the pond surface show visible oil? No

Visually inspect containments liner Checked good

Check leak detection system for any evidence of a loss of integrity of the primary liner None

## SUMMARY

# of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



## New Mexico Recycling Facility Weekly Inspection

## Location

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On October 16 2024, 11:13am


Submitted On October 16 2024, 11:14am (a minute)

Weather 56°, clear

Version V1 (latest)

Updated October 16 2024, 11:14am

Report No. 47730827



## New Mexico Recycling Facility Weekly Inspection

## GENERAL DETAILS

Date October 16th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

## WEEKLY INSPECTION

Read and record the fluid height of staff gauges 3'

Does the pond surface show visible oil? No

Visually inspect containments liner Yes checked good

Check leak detection system for any evidence of a loss of integrity of the primary liner Yes checked good

## SUMMARY

# of Action Item(s) 0

Inspector [Mario Nevarez](#)

Signature



## New Mexico Recycling Facility Weekly Inspection

Submitted By

[Mario Nevarez](#)

Surrogate

[Mario Nevarez](#)

Started On

November 18 2024, 11:24am

Submitted On

November 18 2024, 11:25am (a minute)

Weather

55°, wind

Version

V1 (latest)

Updated

November 18 2024, 11:25am

Report No.

49302427

## Location



## New Mexico Recycling Facility Weekly Inspection

### GENERAL DETAILS

Date

November 18th 2024

Area

[New Mexico](#)

Recycle Facility

[JAVELINA RECYCLE FACILITY](#)

### WEEKLY INSPECTION

Read and record the fluid height of staff gauges

Completed

Does the pond surface show visible oil?

No

Visually inspect containments liner

Completed

Check leak detection system for any evidence of a loss of integrity of the primary liner

Completed

### SUMMARY

# of Action Item(s)

0

Inspector

[Mario Nevarez](#)

Signature

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 6:29pm

Submitted On April 10 2025, 6:39pm (11 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 6:39pm

Report No. 56787721

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date January 6th 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner Working properly, no leaks

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:05pm CDT.

powered by KPA



## New Mexico Recycling Facility Weekly Inspection

## Location

Submitted By

[Mario Lopez](#)

Location was not collected for this report.

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 1:54pm

Submitted On April 11 2025, 1:56pm (2 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 1:56pm

Report No. 56845886

## New Mexico Recycling Facility Weekly Inspection

## GENERAL DETAILS

Date January 13th 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

## WEEKLY INSPECTION

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner All liners in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner leak detection working properly, no leaks

## SUMMARY

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

Generated Monday, April 14th 2025, 12:05pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 1:59pm

Submitted On April 11 2025, 2:00pm (57 seconds)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 2:00pm

Report No. 56846099

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date January 20th 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner All in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "ML", written over a horizontal line.

Generated Monday, April 14th 2025, 12:04pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 2:00pm

Submitted On April 11 2025, 2:01pm (a minute)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 2:01pm

Report No. 56846172

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date January 27th 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner all looks good

Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:04pm CDT.

powered by KPA



**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On

April 11 2025, 2:01pm

Submitted On

April 11 2025, 2:07pm (5 minutes)

Weather

NaN°,

Version

V1 (latest)

Updated

April 11 2025, 2:07pm

Report No.

56846490

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date

February 3rd 2025

Area

[New Mexico](#)

Recycle Facility

[JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges

6'

Does the pond surface show visible oil?

No

Visually inspect containments liner

All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner

working properly, no leaks

**SUMMARY**

# of Action Item(s)

0

Inspector

[Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "ML", written over a horizontal line.

Generated Monday, April 14th 2025, 12:03pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 2:07pm

Submitted On April 11 2025, 2:08pm (47 seconds)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 2:08pm

Report No. 56846761

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date February 10th 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6"

Does the pond surface show visible oil? No

Visually inspect containments liner all look good

Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:03pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 2:11pm

Submitted On April 11 2025, 2:12pm (a minute)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 2:12pm

Report No. 56847029

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date February 17th 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'6"

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:02pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 2:12pm

Submitted On April 11 2025, 2:40pm (27 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 2:40pm

Report No. 56848495

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date February 24th 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "ML", written over a horizontal line.

Generated Monday, April 14th 2025, 12:02pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 2:40pm

Submitted On April 11 2025, 2:46pm (7 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 2:47pm

Report No. 56848898

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date March 3rd 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "M Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:01pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 2:47pm

Submitted On April 11 2025, 2:59pm (12 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 2:59pm

Report No. 56849552

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date March 10th 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner all look good

Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)



Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:01pm CDT.

powered by KPA




New Mexico Recycling Facility Weekly Inspection		Location
Submitted By	 <a href="#">Mario Lopez</a>	Location was not collected for this report.
Surrogate	 <a href="#">Mario Lopez</a>	
Started On	April 11 2025, 3:04pm	
Submitted On	April 11 2025, 3:11pm (8 minutes)	
Weather	NaN°,	
Version	V1 (latest)	
Updated	April 11 2025, 3:11pm	
Report No.	56850070	

New Mexico Recycling Facility Weekly Inspection

GENERAL DETAILS	
Date	March 17th 2025
Area	<a href="#">New Mexico</a>
Recycle Facility	<a href="#">JAVELINA RECYCLE FACILITY</a>

WEEKLY INSPECTION	
Read and record the fluid height of staff gauges	6'
Does the pond surface show visible oil?	No
Visually inspect containments liner	Wind damage on some of the liners, will schedule liner crew to fix



Check leak detection system for any evidence of a loss of integrity of the primary liner	working properly no leaks detected
--	------------------------------------

SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>
Signature	

Generated Monday, April 14th 2025, 12:00pm CDT.

powered by  KPA





## New Mexico Recycling Facility Weekly Inspection

## Location

Submitted By

[Mario Lopez](#)

Location was not collected for this report.

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 3:11pm

Submitted On April 11 2025, 3:13pm (2 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 3:13pm

Report No. 56850166

## New Mexico Recycling Facility Weekly Inspection

## GENERAL DETAILS

Date March 24th 2025


Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

## WEEKLY INSPECTION

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner all containments/liners fixed



Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

## SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>
Signature	

Generated Monday, April 14th 2025, 11:59am CDT.

powered by  KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 11 2025, 3:13pm

Submitted On April 11 2025, 3:14pm (37 seconds)

Weather NaN°,

Version V1 (latest)

Updated April 11 2025, 3:14pm

Report No. 56850207

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date March 31st 2025

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner all look good

Check leak detection system for any evidence of a loss of integrity of the primary liner no leaks detected

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 11:57am CDT.

powered by KPA

# PILOT WATER SOLUTIONS™

## New Mexico Recycling Facility Weekly Inspection

Submitted By  [Mario Lopez](#)

Surrogate  [Mario Lopez](#)

Started On April 9 2025, 11:46am

Submitted On April 9 2025, 12:28pm (42 minutes)


Weather 78°, clear

Version V1 (latest)

Updated April 9 2025, 12:28pm

Report No. 56688832

## Location



## New Mexico Recycling Facility Weekly Inspection

### GENERAL DETAILS

Date April 9th 2025

Area [New Mexico](#)


Recycle Facility [FULFER RECYCLE FACILITY](#)

### WEEKLY INSPECTION

Read and record the fluid height of staff gauges 12ft

Does the pond surface show visible oil? No

Visually inspect containments liner Pump on site doesn't have containment, ground and fire extinguisher



Check leak detection system for any evidence of a loss of integrity of the primary liner Working

### SUMMARY

# of Action Item(s)	0
Inspector	<a href="#">Mario Lopez</a>
Signature	

Generated Monday, April 14th 2025, 12:14pm CDT.

powered by  KPA



## New Mexico Recycling Facility Weekly Inspection

## Location

Submitted By

[Mario Lopez](#)

Location was not collected for this report.

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 8:11am

Submitted On April 10 2025, 9:02am (an hour)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 9:02am

Report No. 56744897

## New Mexico Recycling Facility Weekly Inspection

## GENERAL DETAILS

Date September 1st 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

## WEEKLY INSPECTION

Read and record the fluid height of staff gauges 8'8"

Does the pond surface show visible oil? No

Visually inspect containments liner All containments look in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner working properly

## SUMMARY

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

Generated Monday, April 14th 2025, 12:14pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 9:02am

Submitted On April 10 2025, 9:09am (6 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 9:09am

Report No. 56745530

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date September 9th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 5'8"

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner Functioning properly

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "ML", written over a horizontal line.

Generated Monday, April 14th 2025, 12:14pm CDT.

powered by KPA



## New Mexico Recycling Facility Weekly Inspection

## Location

Submitted By

[Mario Lopez](#)

Location was not collected for this report.

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 9:09am

Submitted On April 10 2025, 9:11am (2 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 9:11am

Report No. 56745699

## New Mexico Recycling Facility Weekly Inspection

## GENERAL DETAILS

Date September 16th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)

## WEEKLY INSPECTION

Read and record the fluid height of staff gauges 9'

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner Functioning properly

## SUMMARY

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:13pm CDT.

powered by KPA



**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 9:11am

Submitted On April 10 2025, 9:18am (7 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 9:18am

Report No. 56746317

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date October 7th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 5'11"

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner Functioning Properly

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "M. Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:13pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 9:18am

Submitted On April 10 2025, 9:22am (4 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 9:22am

Report No. 56746720

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date October 27th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 5'6"

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner functioning properly

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "M Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:12pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 5:43pm

Submitted On April 10 2025, 5:45pm (2 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 5:45pm

Report No. 56785639

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date November 4th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 5'8"

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner working properly

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:10pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 5:45pm

Submitted On April 10 2025, 5:47pm (2 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 5:47pm

Report No. 56785720

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date November 11th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 5'6"

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner Working properly and no water coming out

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:09pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 5:48pm

Submitted On April 10 2025, 6:13pm (25 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 6:13pm

Report No. 56786819

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date December 2nd 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner working properly, no apparent leaks

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to read "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:09pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 6:13pm

Submitted On April 10 2025, 6:19pm (6 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 6:19pm

Report No. 56787068

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date December 9th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner working properly and no signs of leaks

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:08pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 6:19pm

Submitted On April 10 2025, 6:21pm (a minute)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 6:21pm

Report No. 56787136

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date December 16th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner working properly, no apparent leaks

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Mario Lopez", written over a horizontal line.

Generated Monday, April 14th 2025, 12:08pm CDT.

powered by KPA

**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 6:21pm

Submitted On April 10 2025, 6:23pm (2 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 6:23pm

Report No. 56787191

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date December 22nd 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'

Does the pond surface show visible oil? No

Visually inspect containments liner All look good

Check leak detection system for any evidence of a loss of integrity of the primary liner working properly, no leaks

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "Hf", written over a horizontal line.

Generated Monday, April 14th 2025, 12:06pm CDT.

powered by KPA



**New Mexico Recycling Facility Weekly Inspection****Location**

Submitted By

[Mario Lopez](#)*Location was not collected for this report.*

Surrogate

[Mario Lopez](#)

Started On April 10 2025, 6:27pm

Submitted On April 10 2025, 6:29pm (2 minutes)

Weather NaN°,

Version V1 (latest)

Updated April 10 2025, 6:29pm

Report No. 56787381

**New Mexico Recycling Facility Weekly Inspection****GENERAL DETAILS**

Date December 29th 2024

Area [New Mexico](#)Recycle Facility [JAVELINA RECYCLE FACILITY](#)**WEEKLY INSPECTION**

Read and record the fluid height of staff gauges 6'6"

Does the pond surface show visible oil? No

Visually inspect containments liner Liners in good condition

Check leak detection system for any evidence of a loss of integrity of the primary liner detection system working properly, no leaks

**SUMMARY**

# of Action Item(s) 0

Inspector [Mario Lopez](#)

Signature

A handwritten signature in blue ink, appearing to be "ML", written over a horizontal line.

Generated Monday, April 14th 2025, 12:06pm CDT.

powered by KPA

**Venegas, Victoria, EMNRD**

---

**From:** Venegas, Victoria, EMNRD  
**Sent:** Thursday, April 17, 2025 9:39 AM  
**To:** David Grounds; Shelly Cowden  
**Subject:** 1RF-463 - JAVELINA FACILITY [fVV2108855989]  
**Attachments:** C-147 1RF-463 JAVELINA FACILITY [fVV2108855989].pdf

**1RF-463 - JAVELINA FACILITY [fVV2108855989]**

Good morning, Mr. Ground.

The Oil Conservation Division has reviewed the cessation of operations extension request for 1RF-463 - JAVELINA FACILITY [fVV2108855989], received from [308339] OWL SWD OPERATING, LLC on 04/16/2024, Application ID 452865. The request for an extension of the cessation of operations is approved with the following conditions for approval:

- 1RF-463 - JAVELINA FACILITY [fVV2108855989] registration/permit expires on March 23, 2026.
- 1RF-463 - JAVELINA FACILITY [fVV2108855989] extension of the cessation of operations is approved from 03/31/2025 to 09/30/2025. However, if after this 6-month period, the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, and the operator would be directed to remove all fluids and proceed with the closure requirements.
- [308339] OWL SWD OPERATING, LLC will maintain a liquid level in the containment that is at least equal to the weight of the liner plus 20%. [308339] OWL SWD OPERATING, LLC may maintain a higher liquid level if they choose.
- [308339] OWL SWD OPERATING, LLC will provide written notice to the OCD, at least 72 hours, but no more than one week, prior to the recommencement of operations. Recommencement of recycling operations means that the operator plans to resume moving fluids through the containment and discharging fluids from the containment.
  - At the resumption of recycling operations, [308339] OWL SWD OPERATING, LLC is required to perform an incremental fluid level test for containment liquid levels above the minimum liquid level.
  - [308339] OWL SWD OPERATING, LLC will fill the containment. [308339] OWL SWD OPERATING, LLC will pause filling operations at every 10% of total fluid capacity above the minimum level.
  - [308339] OWL SWD OPERATING, LLC will maintain the liquid level for each 10% volume increase for 24 hours and inspect and operate the leak detection system at the end of the 24-hour period.
  - If there are no liquids present in the leak detection system, [308339] OWL SWD OPERATING, LLC may proceed to fill the next 10% volume and repeat the process until the containment full design capacity minus the 3-feet of freeboard is reached.
  - If liquids are present, [308339] OWL SWD OPERATING, LLC should immediately cease the incremental fill test and perform a liner inspection. [308339] OWL SWD OPERATING, LLC should provide written notice of the fluid detection and liner inspection findings to the OCD using a C-147 (long form) with the "Other" box checked and "Notice of fluid detection" written as the explanation of "Other."
  - [308339] OWL SWD OPERATING, LLC must submit copies of the detailed containment inspection records for the prior three (3) months and a report detailing the incremental fluid level test process and results to OCD using a C-147 (long form) with the "Other" box checked. "Recommencement of Operations - Incremental Fluid Level Test" should be written as the explanation of "Other." Form C-147 must be completed and include information in sections 1 General Information, 2 Recycling Facility, 3 Recycling Containment, 4 Bonding, and 10 Operator Application Certification. Section 9 Recycling Facility and/or Containment Checklist may also need to be partially completed. Operators should verify that the resumption of operations notification does not result in any changes to the recycling containment operating and maintenance plan or the closure plan. If the recommencement of

operations affects the operating and maintenance plan or closure plan, operators should check those boxes in section 9 and provide updated plans or plan addendums as attachments to the C-147.

- [308339] OWL SWD OPERATING, LLC will continue to operate, maintain, and close the 1RF-463 - JAVELINA FACILITY [fVV2108855989] in compliance with 19.15.34 NMAC, to include but not limited detailed inspection records, removal of trash/oil from containment, and monthly C-148 reporting (even if there is zero activity).
- A minimum of 3-feet freeboard must always be maintained in the recycling containment during operations.
- [308339] OWL SWD OPERATING, LLC shall inspect the recycling containment and associated leak detection systems weekly while it contains fluids. [308339] OWL SWD OPERATING, LLC shall maintain a current log of such inspections and make the logs available for review by the division upon request as per 19.15.34.13.A.

Please let me know if you have any additional questions.

Best regards,

**Victoria Venegas** • Environmental Specialist Advanced  
EMNRD - Oil Conservation Division  
506 W. Texas Ave. Artesia, NM 88210  
575.909.0269 | [Victoria.Venegas@emnrd.nm.gov](mailto:Victoria.Venegas@emnrd.nm.gov)



March 31, 2025

Victoria Venegas  
EMNRD – Oil Conservation Division  
506 W. Texas Ave.  
Artesia, NM 88210

RE:     OWL SWD Operating, LLC  
          Javelina 1RF-463  
          Cessation of Operations Extension Request  
          OGRID No. 308339

OWL SWD Operating, LLC respectfully requests *Cessation of Operations Extension Request* from 03/31/2025 to 9/30/2025.

Operations has slowed down due to customer needs in the region. The localized drilling and frac schedule have shifted and OWL SWD Operating does have commitments for the recycling facility to start back up in the next several months.

Attached are the inspection reports for leak detection and inspection logs for the last 6 months.

Should you have any questions or require additional information, please contact David Grounds at 817-897-0135 or via email at [david.grounds@pilotwater.com](mailto:david.grounds@pilotwater.com).

Sincerely,

*David Grounds*

David Grounds  
Vice President, Regulatory Compliance

Sante Fe Main Office  
Phone: (505) 476-3441

General Information  
Phone: (505) 629-6116

Online Phone Directory  
<https://www.emnrd.nm.gov/ocd/contact-us>

State of New Mexico  
Energy, Minerals and Natural Resources  
Oil Conservation Division  
1220 S. St Francis Dr.  
Santa Fe, NM 87505

CONDITIONS

Action 452865

CONDITIONS

Operator:  OWL SWD OPERATING, LLC 20 Greenway Plaza Houston, TX 77046	OGRID:  308339
	Action Number:  452865
	Action Type:  [C-147] Water Recycle Long (C-147L)

CONDITIONS

Created By	Condition	Condition Date
vvenegas	• 1RF-463 - JAVELINA FACILITY [FVV2108855989] extension of the cessation of operations is approved from 03/31/2025 to 09/30/2025. However, if after this 6-month period, the containment was not utilized at a minimum of 20% fluid capacity, no additional extensions would be granted, and the operator would be directed to remove all fluids and proceed with the closure requirements.	4/17/2025