

Atchafalaya Measurement Inc
416 East Main Street, Artesia NM 88210 575-746-3481

Sample Information

	Sample Information
Sample Name	OXY__Burton Flats CTB Production__GC2-73019-12
Station Number	14071P
Lease Name	Burton Flats CTB Production
Analysis For	OXY USA
Producer	OXY USA
Field Name	Burton Flats
County/State	N/A
Frequency/Spot Sample	Spot
Sampling Method	Fill Empty
Sample Deg F	97
Atmos Deg F	79
Flow Rate	153.142
Line PSIG	48
Date Sampled/Time Sampled	7-23-19
Cylinder Number	N/A
Cylinder Clean Date	N/A
Sampled By	Derek Sauder
Analysis By	Pat Silvas
Verified/Calibrated Date	7-29-19
Report Date	2019-07-30 10:46:10

Component Results

Component Name	Ret. Time	Peak Area	Norm%	GPM (Dry) (Gal. / 1000 cu.ft.)	
Nitrogen	23.100	30269.9	2.1819	0.000	
H2S	0.000	0.0	0.0000	0.000	
Methane	23.860	787502.9	75.1296	0.000	
Carbon Dioxide	27.900	5825.9	0.3597	0.000	
Ethane	36.960	202456.6	11.6915	3.121	
Propane	77.160	133263.6	5.8157	1.600	
i-Butane	29.820	64807.6	0.7713	0.252	
n-Butane	32.080	165504.2	1.9549	0.615	
i-Pentane	39.120	49926.9	0.5126	0.187	
n-Pentane	41.900	54913.2	0.5487	0.199	
C6's	50.750	43911.0	0.3860	0.158	
C7's	67.000	54984.0	0.4654	0.214	
C8's	84.000	18044.0	0.1628	0.083	
C9's	102.000	4888.0	0.0159	0.009	
C10 Plus	146.000	1090.0	0.0040	0.002	
Total:			100.0000	6.441	

Results Summary

Result	Dry	Sat. (Base)	
Total Raw Mole% (Dry)	103.9585		
Pressure Base (psia)	14.650		
Temperature Base	60.00		
Gross Heating Value (BTU / Ideal cu.ft.)	1294.9	1272.2	
Gross Heating Value (BTU / Real cu.ft.)	1300.1	1277.9	
Relative Density (G), Ideal	0.7687	0.7661	
Relative Density (G), Real	0.7715	0.7692	
Compressibility (Z) Factor	0.9960	0.9956	

UPSET FLARING EVENT SPECIFIC JUSTIFICATIONS FORM**Facility:** Burton Flats CTB**Flare Date:** 11/13/2021**Duration of event:** 3 Hours 10 Minutes**MCF Flared:** 182**Start Time:** 10:20 AM**End Time:** 01:30 PM**Cause:** Compressor Malfunction > Low Oil**Method of Flared Gas Measurement:** Gas Flare Meter

Comments: This upset event was not caused by any wells associated with the facility. This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. Oxy engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program.

1. Reason why this event was beyond Operator's control:

In this case, the facility's gas compressor automatically shut down on a low oil malfunction alarm. A malfunction alarm and automatic shutdown of the compressor unit can be caused by any number of things, such as fuel quality change, temperature changes, psi changes, oil issues, plugs and valves failing, etc. As it pertains to this event, the sudden and reasonably unforeseeable malfunction occurred due to the unit had an issue with the oil level volume. This unit recently underwent a preventative maintenance overview by the compression owner, USA Compression and no issues were found during its inspection and maintenance work. Notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable, and very unexpected, which can cause compressor unit malfunctions to occur without warning or advance notice. With the gas compressor down, there was no gas takeaway, and thus field psi increased until set psi levels were reached which triggered flaring, as a safety measure for operations, facility equipment, and personnel. This gas compressor unit was working as designed and operated normally prior to the sudden and without warning detonation malfunction of the compressor unit. This incident was completely out of OXY's control to prevent from happening yet OXY made every effort to control and minimize emissions as much as possible during this event by working safely and diligently during this event.

2. Steps Taken to limit duration and magnitude of venting or flaring:

It is OXY's policy to route all stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, as the part of the overall process or steps to take to limit duration and magnitude of flaring. Oxy personnel are in the field 24/7 and can physically see when we are flaring which in turn are communicated to additional Oxy field personnel. Internal OXY procedures ensure that upon gas compressor unit and/or multiple unit shutdown alarms, increased sensor pressure alarms, etc., field production technician personnel are promptly notified, and are instructed to assess the issue as soon as possible in order to take prompt corrective action and minimize emissions. Oxy production technicians must assess whether the issue or circumstance is due to damage and repair is needed, or whether there are other reasons for its cause.

In this case, the facility's gas compressor automatically shut down on a low oil malfunction alarm. A malfunction alarm and automatic shutdown of the compressor unit can be caused by any number of things, such as fuel quality change, temperature changes, psi changes, oil issues, plugs and valves failing, etc. As it pertains to this event, the sudden and reasonably unforeseeable malfunction occurred due to the unit had an issue with the oil level volume. The field Oxy production tech, who received the facility compressor alarm notifications, drove to the facility, as this is an unmanned facility, and upon arrival, immediately began to inspect the gas compressor. After inspecting the unit, the field production tech noticed that the oil level was low and immediately contacted the compressor owner, USA Compression, who owns the compressor, to have a mechanic be sent out to the facility to troubleshoot the gas compressor unit. A USA Compression mechanic went out and made necessary equipment fluid refills and adjustments before re-inspecting the unit. Once the USA Compression mechanic had performed his necessary work, the gas compressor unit was restarted and returned to normal working operations. The production tech and the USA Compression mechanic stayed on-site for a short period of time to monitor the gas compressor unit to ensure that no further incidents occurred. OXY made every effort to control and minimize emissions as much as possible during this event by working safely and diligently to resolve the issues.

3. Corrective Actions taken to eliminate the cause and reoccurrence of venting or flaring:

Oxy is limited in the corrective actions to eliminate this type of cause and potential reoccurrence of flaring as notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable and unexpected which can cause compressor unit malfunctions to occur without warning or advance notice. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. The only actions that Oxy can take and handle that is within its control, is to keep continue with its compression equipment preventative maintenance program for this unit.

District I

1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II

811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

QUESTIONS

Action 64181

QUESTIONS

Operator: OXY USA WTP LIMITED PARTNERSHIP P.O. Box 4294 Houston, TX 772104294	OGRID: 192463
	Action Number: 64181
	Action Type: [C-129] Venting and/or Flaring (C-129)

QUESTIONS**Prerequisites**

Any messages presented in this section, will prevent submission of this application. Please resolve these issues before continuing with the rest of the questions.

Incident Well	Not answered.
Incident Facility	[fAPP2126552654] BURTON FLATS FED CTB

Determination of Reporting Requirements

Answer all questions that apply. The Reason(s) statements are calculated based on your answers and may provide additional guidance.

Was or is this venting and/or flaring caused by an emergency or malfunction	Yes
Did or will this venting and/or flaring last eight hours or more cumulatively within any 24-hour period from a single event	No
Is this considered a submission for a venting and/or flaring event	Yes, minor venting and/or flaring of natural gas.
An operator shall file a form C-141 instead of a form C-129 for a release that, includes liquid during venting and/or flaring that is or may be a major or minor release under 19.15.29.7 NMAC.	
Was there or will there be at least 50 MCF of natural gas vented and/or flared during this event	Yes
Did this venting and/or flaring result in the release of ANY liquids (not fully and/or completely flared) that reached (or has a chance of reaching) the ground, a surface, a watercourse, or otherwise, with reasonable probability, endanger public health, the environment or fresh water	No
Was the venting and/or flaring within an incorporated municipal boundary or withing 300 feet from an occupied permanent residence, school, hospital, institution or church in existence	No

Equipment Involved

Primary Equipment Involved	Other (Specify)
Additional details for Equipment Involved. Please specify	Emergency Flare > Compressor Malfunction > Low Oil

Representative Compositional Analysis of Vented or Flared Natural Gas

Please provide the mole percent for the percentage questions in this group.

Methane (CH4) percentage	75
Nitrogen (N2) percentage, if greater than one percent	2
Hydrogen Sulfide (H2S) PPM, rounded up	0
Carbon Dioxide (CO2) percentage, if greater than one percent	0
Oxygen (O2) percentage, if greater than one percent	0

If you are venting and/or flaring because of Pipeline Specification, please provide the required specifications for each gas.

Methane (CH4) percentage quality requirement	Not answered.
Nitrogen (N2) percentage quality requirement	Not answered.
Hydrogen Sulfide (H2S) PPM quality requirement	Not answered.
Carbon Dioxide (CO2) percentage quality requirement	Not answered.
Oxygen (O2) percentage quality requirement	Not answered.

Date(s) and Time(s)

Date venting and/or flaring was discovered or commenced	11/13/2021
Time venting and/or flaring was discovered or commenced	10:20 AM
Time venting and/or flaring was terminated	01:30 PM
Cumulative hours during this event	3

Measured or Estimated Volume of Vented or Flared Natural Gas

Natural Gas Vented (Mcf) Details	Not answered.
----------------------------------	---------------

Natural Gas Flared (Mcf) Details	Cause: Other Other (Specify) Natural Gas Flared Released: 182 Mcf Recovered: 0 Mcf Lost: 182 Mcf]
Other Released Details	Not answered.
Additional details for Measured or Estimated Volume(s). Please specify	Gas Flare Meter
Is this a gas only submission (i.e. only significant Mcf values reported)	Yes, according to supplied volumes this appears to be a "gas only" report.

Venting or Flaring Resulting from Downstream Activity	
Was or is this venting and/or flaring a result of downstream activity	No
Was notification of downstream activity received by you or your operator	Not answered.
Downstream OGRID that should have notified you or your operator	Not answered.
Date notified of downstream activity requiring this venting and/or flaring	Not answered.
Time notified of downstream activity requiring this venting and/or flaring	Not answered.

Steps and Actions to Prevent Waste	
For this event, the operator could not have reasonably anticipated the current event and it was beyond the operator's control.	True
Please explain reason for why this event was beyond your operator's control	This emissions event was caused by the unforeseen, unexpected, sudden, and unavoidable breakdown of equipment or process that was beyond the owner/operator's control, and did not stem from activity that could have been foreseen and avoided, and could not have been avoided by good design, operation, and preventative maintenance practices. Oxy engages in respectable and good facility operation practices while also maintaining its continuous facility equipment preventative maintenance program. In this case, the facility's gas compressor automatically shut down on a low oil malfunction alarm. A malfunction alarm and automatic shutdown of the compressor unit can be caused by any number of things, such as fuel quality change, temperature changes, psi changes, oil issues, plugs and valves failing, etc. As it pertains to this event, the sudden and reasonably unforeseeable malfunction occurred due to the unit had an issue with the oil level volume. This unit recently underwent a preventative maintenance overview by the compression owner, USA Compression and no issues were found during its inspection and maintenance work. Notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable, and very unexpected, which can cause compressor unit malfunctions to occur without warning or advance notice.
Steps taken to limit the duration and magnitude of venting and/or flaring	It is OXY's policy to route all stranded gas to a flare during an unforeseen and unavoidable emergency or malfunction, as the part of the overall process or steps to take to limit duration and magnitude of flaring. Oxy personnel are in the field 24/7 and can physically see when we are flaring which in turn are communicated to additional Oxy field personnel. Internal OXY procedures ensure that upon gas compressor unit and/or multiple unit shutdown alarms, increased sensor pressure alarms, etc., field production technician personnel are promptly notified, and are instructed to assess the issue as soon as possible in order to take prompt corrective action and minimize emissions. Oxy production technicians must assess whether the issue or circumstance is due to damage and repair is needed, or whether there are other reasons for its cause.
Corrective actions taken to eliminate the cause and reoccurrence of venting and/or flaring	Oxy is limited in the corrective actions to eliminate this type of cause and potential reoccurrence of flaring as notwithstanding proper gas compressor design and operation, various forms of mechanical or technical issues can be sudden, reasonably unforeseeable and unexpected which can cause compressor unit malfunctions to occur without warning or advance notice. Oxy continually strives to maintain and operate its facility equipment in a manner consistent with good practices for minimizing emissions and reducing the number of emission events. Oxy has a strong and positive compression equipment preventative maintenance program in place. The only actions that Oxy can take and handle that is within its control, is to keep continue with its compression equipment preventative maintenance program for this unit

District I
1625 N. French Dr., Hobbs, NM 88240
Phone:(575) 393-6161 Fax:(575) 393-0720

District II
811 S. First St., Artesia, NM 88210
Phone:(575) 748-1283 Fax:(575) 748-9720

District III
1000 Rio Brazos Rd., Aztec, NM 87410
Phone:(505) 334-6178 Fax:(505) 334-6170

District IV
1220 S. St Francis Dr., Santa Fe, NM 87505
Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico
Energy, Minerals and Natural Resources
Oil Conservation Division
1220 S. St Francis Dr.
Santa Fe, NM 87505

CONDITIONS

Action 64181

CONDITIONS

Operator: OXY USA WTP LIMITED PARTNERSHIP P.O. Box 4294 Houston, TX 772104294	OGRID: 192463
	Action Number: 64181
	Action Type: [C-129] Venting and/or Flaring (C-129)

CONDITIONS

Created By	Condition	Condition Date
marialuna2	If the information provided in this report requires an amendment, submit a [C-129] Amend Venting and/or Flaring Incident (C-129A), utilizing your incident number from this event.	11/30/2021