## SITE REMEDIATION AND CLOSURE REPORT

## **REPORTABLE RELEASE**

## **Spur Energy Partners**

Holiday #1H Battery GPS: Latitude 32.8023071 Longitude -104.2290268 Eddy County, NM Incident ID No. NAPP2119561140



Paragon Environmental LLC 225 Billy Walker Rd Hobbs, NM 88240 903-522-0833

## **General Information**

This report was prepared by Paragon Environmental LLC (Paragon) in response to the release for Spur Energy Partners (Spur) at the **Holiday #1H Battery** (Holiday).

Site Coordinates: Latitude: 32.8023071 Longitude: -104.2290268

Unit: UL D, Section 01, Township 20S, Range 25E

Date of Spill: 07/10/2021

**Type of Spill:** Crude Oil **Produced Water** Condensate Other (Specify):

**<u>Comments:</u>** Reportable release. Released: 32 bbls of Produced Water Recovered: 32 bbls of Produced Water

## Incident ID: NAPP2119561140

## Depth to Groundwater

According to the New Mexico State of Engineers Office, the nearest water data is less than 1/2 miles away and is 121 feet below grade surface (BGS). See Appendix A for details.

## Soil Survey

Per the New Mexico Bureau of Geology and Mineral Resources, the geology is in the Piedmont alluvial deposits (Holocene to lower Pleistocene)-Includes deposits of higher gradient tributaries bordering major stream valleys, alluvial veneers of the piedmont slope, and alluvial fans. May locally include uppermost Pliocene deposits (QP). According to the United States Department of Agriculture Natural Resources Conservation Service soil survey, the soil in this area is comprised of the Reeves-Gypsum land complex, with 0 to 3 percent slopes. The drainage courses in this area are well-drained. There is a **high** potential for karst geology to be present in the area of the Holiday (Appendix B).

## **Release Description and Assessment**

This release was caused by corrosion developing a hole in a four-inch water line. The release was contained in the falcon-lined containment. A vacuum truck was dispatched to aid in the recovery of the fluids and placed the recovered fluids back into the water tank. The line was repaired and put back into service.

## Site Assessment and Soil Sampling Results

On February 9, 2022, Paragon sent an Environmental Technician to the site to conduct a Liner inspection and to obtain soil samples. The results of this sampling event are in the following data table and all the laboratory results can be found in Appendix E.

NMOCD Table 1 Closure Criteria 19.15.29 NMAC (High Karst Area)								
Sample Da	te 2-9-22	Closure Criteria <u>&lt;</u> 50 mg/kg	Closure Criteria <u>≤</u> 10 mg/kg				Closure Criteria 100 mg/kg	Closure Criteria <u>6</u> 00 mg/kg
Sample ID	Depth (BGS)	BTEX	Benzene	GRO	DRO	MRO	Total TPH	CHLORIDES
N. COMP.	0	ND	ND	ND	ND	ND	ND	16
E. COMP.	0	ND	ND	ND	ND	ND	ND	144
			ND	ND	ND	ND	ND	32
S. COMP.	0	ND	ND	ND	ND	ND	ND	52
S. COMP. W. COMP.	0	ND ND	ND ND	ND	ND	ND	ND	32

2-9-22 Soil Sample Results

ND- Analyte Not Detected

The liner was cleaned prior to the inspection. The 48-hour notification was given to the state on 2-7-22, see Appendix F. During the inspection, there were no obvious rips or tears in the liner to make me believe that the liner needs any repair or has lost the integrity to contain any spilled fluids. The liner report can also be found in Appendix F.

## Remediation Activity Summary

Based on the Liner Inspection and the composite sample results being below closure criteria no remediation is needed for this incident.

## **Closure Request**

After careful review, Paragon respectfully requests that the incident, NAPP2119561140, be closed. Spur has complied with the applicable closure requirements.

Should you have any questions or need additional information, please feel free to contact Wayne Brunt at 903-522-0833 or wayne@paragonenvironmental.net.

Respectfully,

Wayne Brunt Environmental Professional Paragon Environmental LLC

## **Attachments**

Figures:

- 1- Site Map
- 2- TOPO Map
- 3- Karst Map
- 4- Location Map

Appendices:

- Appendix A- Referenced Water Data
- Appendix B- Soil Survey & FEMA Flood Map
- Appendix C- C-141
- Appendix D- Photographic Documentation
- Appendix E- Laboratory Results
- Appendix F- Liner Inspection Notification and Form



Figures:

1-Site Map 2- TOPO Map 3- Karst Map 4- Location Map







## Received by OCD: 5/20/2022 12:27:18 PM Spur Energy Partners

Page 9 of 39

Avalon

Carlsbad Nor

Dayton

Holiday #1

Seven Rivers

285

285

524

8 mi

Holiday #1H Battery API# 30-015-39769 Eddy County, NM Location Map



Appendix A Referenced Water Data:

New Mexico State of Engineers Office



# New Mexico Office of the State Engineer Water Column/Average Depth to Water

(A CLW##### in the POD suffix indicates the POD has been replaced	(R=POD has beer replaced,	1											
& no longer serves a water right file.)	O=orphaned, C=the file is closed)			-			V 2=NE est to la	3=SW 4=SI rgest) (N	E) VAD83 UTM in n	neters)	(In f	eet)	
	POD							<i>6 / (</i>		,	X		
POD Number	Sub- Code basin	County	_	Q ( 16 4		Tws	Rng	х	Y	DistanceDe	othWellDep		/ater Jumn
<u>RA 10898 POD1</u>	RA	ED		1 3			25E	552198	3607248*	874	810	121	689
<u>RA 05458</u>	RA	ED		3 3	01	208	25E	552101	3606747*	1358	500	95	405
									Avera	ge Depth to Wa	ter:	108 fee	t
										Minimum De	epth:	95 fee	t
										Maximum De	pth:	121 fee	t
Record Count: 2													
<u>U</u> TMNAD <u>83</u> Radius	<u>Search_(in_meters)</u>	:											
<b>Easting (X):</b> 552	2011.538	Nortl	hing	( <b>Y</b> ):	360	8102.50	52		<b>Radius:</b> 1500				
*UTM location was derived	l from PLSS - see Hel	р											
*UTM location was derived The data is furnished by the I the accuracy, completeness, r	NMOSE/ISC and is acc	cepted by th							that the OSE/ISC 1	nake no warrantie	es, expressed o	r implied, con	cerni

4/12/22 11:51 AM

WATER COLUMN/ AVERAGE DEPTH TO WATER

Page 11 of 39

Received by OCD: 5/20/2022 12:27:18 PM



# New Mexico Office of the State Engineer **Point of Diversion Summary**

		(qua	rters are	e 1=N	W 2=1	NE 3=S	W 4=SE)			
		(quarters are smallest to largest)				t)	(NAD83 U	JTM in meters)		
POD	Number	Q6	4 Q16	Q4	Sec	Tws	Rng	Х	Y Y	
RA	10898 POD1	2	1	3	01	20S	25E	552198	3607248* 🧉	
ense:	331	Drille	er Con	npan	y:		-	C DBA STE	WART BROTH	ERS DRILLING
ne:						CO	•			
Date:	02/17/2006	Drill	Finish	Dat	e:	0	3/08/20	06 <b>P</b>	lug Date:	
ate:	03/27/2006	PCW	Rcv I	)ate:				S	ource:	Artesian
e:		Pipe	Discha	rge	Size:			E	stimated Yield:	1000 GPM
e:	8.63	Dept	h Well	:		8	10 feet	Γ	Depth Water:	121 feet
Wate	er Bearing Stratifi	ications:		Та	op l	Botton	Desc	ription		
				46	50	802	2 Lime	stone/Dolo	mite/Chalk	
	Casing Per	forations:		То	op l	Botton	l			
				54	42	802	2			
	RA ense: ne: Date: nte: :	ne: Date: 02/17/2006 nte: 03/27/2006 :: e: 8.63 Water Bearing Stratifi	POD Number       Q64         RA 10898 POD1       2         ense:       331       Drille         ne:       Date:       02/17/2006       Drill         nte:       03/27/2006       PCW         ::       Pipe 1	POD NumberQ64Q16RA 10898 POD121ense:331Driller Conense:02/17/2006Drill FinishDate:02/17/2006PCW Rcv Iense:03/27/2006PCW Rcv Iense:8.63Depth WellWater Bearing Stratifications:	POD NumberQ64Q16Q4RA 10898 POD1213ense:331Driller CompaniesDate:02/17/2006Drill Finish DateDate:03/27/2006PCW Rcv Datesense:8.63Depth Well:Water Bearing Stratifications:ToCasing Perforations:To	POD Number RA 10898 POD1Q64Q16Q4Sec21301ense:331Driller Company: ne:Date:02/17/2006Drill Finish Date: PCW Rcv Date:ense:03/27/2006PCW Rcv Date: Pipe Discharge Size:ense:8.63Depth Well:Water Bearing Stratifications:Top1460	POD Number RA 10898 POD1Q64 Q16 Q4SecTwsRA 10898 POD121301208ense:331Driller Company:SB0 CODate:02/17/2006Drill Finish Date:03Date:03/27/2006PCW Rcv Date:03ense:Pipe Discharge Size:8ense:8.63Depth Well:8Water Bearing Stratifications:TopBottomCasing Perforations:TopBottom	POD Number RA 10898 POD1Q64 Q16 Q4SecTwsRng2130120S25Eense:331 ne:Driller Company:SBQ2, LLO CO.Date:02/17/2006Drill Finish Date:03/08/200ite:03/27/2006PCW Rcv Date:03/08/200ense:8.63Depth Well:810 feetWater Bearing Stratifications:TopBottomDesc 460Kasing Perforations:TopBottomDescCasing Perforations:TopBottomDesc	POD Number       Q64       Q16       Q4       Sec       Tws       Rng       X         RA       10898       POD1       2       1       3       01       208       25E       552198         ense:       331       Driller Company:       SBQ2, LLC DBA STE CO.         ne:       02/17/2006       Drill Finish Date:       03/08/2006       P         ne:       03/27/2006       PCW Rcv Date:       03/08/2006       P         se:       03/27/2006       PCW Rcv Date:       S       S         se:       8.63       Depth Well:       810       feet       D         Water Bearing Stratifications:       Top       Bottom       Description         460       802       Limestone/Dolo	POD Number       Q64 Q16 Q4 Sec       Tws       Rng       X       Y         RA 10898 POD1       2       1       3       01       20S       25E       552198       3607248*       Image: Company: Compa

## \*UTM location was derived from PLSS - see Help

The data is furnished by the NMOSE/ISC and is accepted by the recipient with the expressed understanding that the OSE/ISC make no warranties, expressed or implied, concerning the accuracy, completeness, reliability, usability, or suitability for any particular purpose of the data.

4/12/22 11:52 AM

POINT OF DIVERSION SUMMARY

Page 12 of 39



Appendix B Soil Survey:

U.S.D.A. FEMA Flood Map

## Eddy Area, New Mexico

## RG—Reeves-Gypsum land complex, 0 to 3 percent slopes

## Map Unit Setting

National map unit symbol: 1w5f Elevation: 1,250 to 5,000 feet Mean annual precipitation: 10 to 25 inches Mean annual air temperature: 57 to 70 degrees F Frost-free period: 190 to 235 days Farmland classification: Not prime farmland

## **Map Unit Composition**

Reeves and similar soils: 55 percent Gypsum land: 30 percent Minor components: 15 percent Estimates are based on observations, descriptions, and transects of the mapunit.

## **Description of Reeves**

## Setting

Landform: Ridges, plains, hills Landform position (two-dimensional): Shoulder, backslope, footslope, toeslope Landform position (three-dimensional): Side slope, crest, nose slope, head slope Down-slope shape: Convex Across-slope shape: Linear Parent material: Residuum weathered from gypsum

## **Typical profile**

H1 - 0 to 8 inches: loam
H2 - 8 to 32 inches: clay loam
H3 - 32 to 60 inches: gypsiferous material

## **Properties and qualities**

Slope: 0 to 1 percent
Depth to restrictive feature: More than 80 inches
Drainage class: Well drained
Runoff class: High
Capacity of the most limiting layer to transmit water (Ksat): Very low to moderately low (0.00 to 0.06 in/hr)
Depth to water table: More than 80 inches
Frequency of flooding: None
Frequency of ponding: None
Calcium carbonate, maximum content: 25 percent
Gypsum, maximum content: 80 percent
Maximum salinity: Very slightly saline to moderately saline (2.0 to 8.0 mmhos/cm)
Sodium adsorption ratio, maximum: 4.0
Available water supply, 0 to 60 inches: Low (about 4.3 inches)

Map Unit Description: Reeves-Gypsum land complex, 0 to 3 percent slopes---Eddy Area, New Mexico

## Interpretive groups

Land capability classification (irrigated): 3s Land capability classification (nonirrigated): 7s Hydrologic Soil Group: B Ecological site: R042XC007NM - Loamy Hydric soil rating: No

## **Description of Gypsum Land**

## Setting

Landform: Ridges, plains, hills Landform position (two-dimensional): Shoulder, backslope, footslope, toeslope Landform position (three-dimensional): Side slope, crest, nose slope, head slope Down-slope shape: Convex Across-slope shape: Linear Parent material: Residuum weathered from gypsum

## Interpretive groups

Land capability classification (irrigated): None specified Land capability classification (nonirrigated): 8s Hydric soil rating: No

## **Minor Components**

## Largo

Percent of map unit: 5 percent Ecological site: R042XC007NM - Loamy Hydric soil rating: No

## Cottonwood

Percent of map unit: 5 percent Ecological site: R042XC033NM - Salty Bottomland Hydric soil rating: No

## Reagan

Percent of map unit: 5 percent Ecological site: R042XC007NM - Loamy Hydric soil rating: No

## **Data Source Information**

Soil Survey Area: Eddy Area, New Mexico Survey Area Data: Version 17, Sep 12, 2021



# Received by OCD: 5/20/2022 12:27:18 PM National Flood Hazard Layer FIRMette



## Legend

regulatory purposes.

Page 16 of 39



Releasea to Imaging: 8/29/2022 9.96:11 PM 1,500 2.000

Basemap: USGS National Map: Orthoimagery: Data refreshed October, 2020



Appendix C:

C-141

District I 1625 N. French Dr., Hobbs, NM 88240 District II 811 S. First St., Artesia, NM 88210 District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505 State of New Mexico Energy Minerals and Natural Resources Department

Oil Conservation Division 1220 South St. Francis Dr. Santa Fe, NM 87505 Form C-141 Revised August 24, 2018 Submit to appropriate OCD District office

)

Page 18 bf 39

Incident ID	
District RP	
Facility ID	
Application ID	

## **Release Notification**

## **Responsible Party**

Responsible Party	OGRID
Contact Name	Contact Telephone
Contact email	Incident # (assigned by OCD)
Contact mailing address	

## **Location of Release Source**

Longitude

Latitude	

Site Name	Site Type
Date Release Discovered	API# (if applicable)

(NAD 83 in decimal degrees to 5 decimal places)

Unit Letter	Section	Township	Range	County

Surface Owner: State Federal Tribal Private (Name: \_

## Nature and Volume of Release

Material(s) Released (Select all that apply and attach calculations or specific justification for the volumes provided below)

Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (bbls)	Volume Recovered (bbls)
Is the concentration of dissolved chloride in the produced water >10,000 mg/l?	Yes No
Volume Released (bbls)	Volume Recovered (bbls)
Volume Released (Mcf)	Volume Recovered (Mcf)
Volume/Weight Released (provide units)	Volume/Weight Recovered (provide units)
	-
	Volume Released (bbls)         Is the concentration of dissolved chloride in the produced water >10,000 mg/l?         Volume Released (bbls)         Volume Released (Mcf)

Page 2

Incident ID	
District RP	
Facility ID	
Application ID	

Was this a major	If YES, for what reason(s) does the responsible party consider this a major release?
release as defined by	
19.15.29.7(A) NMAC?	
<b>``</b>	
🗌 Yes 🗌 No	
If YES, was immediate n	otice given to the OCD? By whom? To whom? When and by what means (phone, email, etc)?

## **Initial Response**

The responsible party must undertake the following actions immediately unless they could create a safety hazard that would result in injury

The source of the release has been stopped.

The impacted area has been secured to protect human health and the environment.

Released materials have been contained via the use of berms or dikes, absorbent pads, or other containment devices.

All free liquids and recoverable materials have been removed and managed appropriately.

If all the actions described above have not been undertaken, explain why:

Per 19.15.29.8 B. (4) NMAC the responsible party may commence remediation immediately after discovery of a release. If remediation has begun, please attach a narrative of actions to date. If remedial efforts have been successfully completed or if the release occurred within a lined containment area (see 19.15.29.11(A)(5)(a) NMAC), please attach all information needed for closure evaluation.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Printed Name:	Title:
Signature: Valors Red	Date:
email:	Telephone:
OCD Only	
Received by: Ramona Marcus	Date: <u>10/4/2021</u>

-

NAPP2119561140

Spill Volume (Bbls) Calculator					
Inputs in blue, Outputs in red					
Length(Ft)	Width(Ft)	Depth(In)			
24.000	45.000	2.000			
Cubic Feet	Impacted	<u>180.000</u>			
Barr	els	<u>32.06</u>			
Soil T	Lined Containment				
Bbls Assuming 100% Saturation		<u>32.06</u>			
Saturation	Fluid pre	esent with shovel/backhoe			
Estimateo Relea		32.10000			

Released to Imaging: 8/29/2022 3:56:11 PM

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

## **State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Spur Energy Partners LLC	53870
	Action Type:
	[C-141] Release Corrective Action (C-141)

#### CONDITIONS

Created By Condition		Condition Date
rmarcus	None	10/4/2021

CONDITIONS

Page 21 4639

Action 53870

m 0.1.11	C		
Form C-141	State of New Mexico	Incident ID	NAPP2119561140
Page 3	Oil Conservation Division	District RP	
		Engility ID	

Application ID

## Site Assessment/Characterization

This information must be provided to the appropriate district office no later than 90 days after the release discovery date.

What is the shallowest depth to groundwater beneath the area affected by the release?	121 (ft bgs)
Did this release impact groundwater or surface water?	🗌 Yes 🛛 No
Are the lateral extents of the release within 300 feet of a continuously flowing watercourse or any other significant watercourse?	🗌 Yes 🛛 No
Are the lateral extents of the release within 200 feet of any lakebed, sinkhole, or playa lake (measured from the ordinary high-water mark)?	🗌 Yes 🛛 No
Are the lateral extents of the release within 300 feet of an occupied permanent residence, school, hospital, institution, or church?	Yes 🛛 No
Are the lateral extents of the release within 500 horizontal feet of a spring or a private domestic fresh water well used by less than five households for domestic or stock watering purposes?	🗌 Yes 🛛 No
Are the lateral extents of the release within 1000 feet of any other fresh water well or spring?	🗌 Yes 🛛 No
Are the lateral extents of the release within incorporated municipal boundaries or within a defined municipal fresh water well field?	🗌 Yes 🛛 No
Are the lateral extents of the release within 300 feet of a wetland?	🗌 Yes 🛛 No
Are the lateral extents of the release overlying a subsurface mine?	🗌 Yes 🛛 No
Are the lateral extents of the release overlying an unstable area such as karst geology?	🗌 Yes 🛛 No
Are the lateral extents of the release within a 100-year floodplain?	🗌 Yes 🛛 No
Did the release impact areas not on an exploration, development, production, or storage site?	🗌 Yes 🛛 No

Attach a comprehensive report (electronic submittals in .pdf format are preferred) demonstrating the lateral and vertical extents of soil contamination associated with the release have been determined. Refer to 19.15.29.11 NMAC for specifics.

Characterization Report Checklist: Each of the following items must be included in the report.

Scaled site map showing impacted area, surface features, subsurface features, delineation points, and monitoring wells.

- Field data
- Data table of soil contaminant concentration data
- Depth to water determination
- Determination of water sources and significant watercourses within 1/2-mile of the lateral extents of the release
- Boring or excavation logs
- Photographs including date and GIS information
- Topographic/Aerial maps
- Laboratory data including chain of custody

If the site characterization report does not include completed efforts at remediation of the release, the report must include a proposed remediation plan. That plan must include the estimated volume of material to be remediated, the proposed remediation technique, proposed sampling plan and methods, anticipated timelines for beginning and completing the remediation. The closure criteria for a release are contained in Table 1 of 19.15.29.12 NMAC, however, use of the table is modified by site- and release-specific parameters.

Received by OCD: 5/20/2022 12:27:18 PM

Form C-141	State of New Mexico		Incident ID	NAPP2119561140
Page 4	Oil Conservation Division		District RP	
			Facility ID	
			Application ID	
regulations all operators are public health or the environ failed to adequately investig addition, OCD acceptance of and/or regulations. Printed Name: Braidy M Signature: <b>Braidy</b> email: <u>bmoulder@spure</u>	y Mouldes	tifications and perform co OCD does not relieve the reat to groundwater, surfa	prrective actions for rele e operator of liability sh ce water, human health iance with any other fe- nager	eases which may endanger ould their operations have or the environment. In
OCD Only Received by:		Date:		

Released to Imaging: 8/29/2022 3:56:11 PM

Form C-141 Page 5 State of New Mexico Oil Conservation Division

Incident ID	NAPP2119561140	
District RP		
Facility ID		
Application ID		

## Closure

The responsible party must attach information demonstrating they have complied with all applicable closure requirements and any conditions or directives of the OCD. This demonstration should be in the form of a comprehensive report (electronic submittals in .pdf format are preferred) including a scaled site map, sampling diagrams, relevant field notes, photographs of any excavation prior to backfilling, laboratory data including chain of custody documents of final sampling, and a narrative of the remedial activities. Refer to 19.15.29.12 NMAC.

Closure Report Attachment Checklist: Each of the following items must be included in the closure report.

A scaled site and sampling diagram as described in 19.15.29.11 NMAC

Photographs of the remediated site prior to backfill or photos of the liner integrity if applicable (Note: appropriate OCD District office must be notified 2 days prior to liner inspection)

Laboratory analyses of final sampling (Note: appropriate ODC District office must be notified 2 days prior to final sampling)

Description of remediation activities

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to OCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the OCD does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to groundwater, surface water, human health or the environment. In addition, OCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations. The responsible party acknowledges they must substantially restore, reclaim, and re-vegetate the impacted surface area to the conditions that existed prior to the release or their final land use in accordance with 19.15.29.13 NMAC including notification to the OCD when reclamation and re-vegetation are complete.

Printed Name: Braidy Moulder	Title: HSE Manager
Signature: Braidy Moulder	Date: 4-12-22
email: <u>bmoulder@spurepllc.com</u>	Telephone: 713-264-2517
OCD Only	
Received by:	Date:
Closure approval by the OCD does not relieve the responsible party of liab remediate contamination that poses a threat to groundwater, surface water, party of compliance with any other federal, state, or local laws and/or regu	human health, or the environment nor does not relieve the responsible
Closure Approved by:	Date:08/29/2022
Printed Name: Jennifer Nobui	Title: Environmental Specialist A



Appendix D:

Photographic Documentation



## **Photographic Documentation**

## Liner Inspection Composite Samples From Around The Containment









## **Cleaned & Completed**











Appendix E:

Laboratory Results



February 15, 2022

CASON SPURLOCK PARAGON ENVIROMENTAL 5002 CARRAIGE RD HOBBS, NM 88242

**RE: HOLIDAY 1 BATTERY** 

Enclosed are the results of analyses for samples received by the laboratory on 02/11/22 10:05.

Cardinal Laboratories is accredited through Texas NELAP under certificate number T104704398-21-14. Accreditation applies to drinking water, non-potable water and solid and chemical materials. All accredited analytes are denoted by an asterisk (\*). For a complete list of accredited analytes and matrices visit the TCEQ website at <a href="https://www.tceq.texas.gov/field/ga/lab\_accred\_certif.html">www.tceq.texas.gov/field/ga/lab\_accred\_certif.html</a>.

Cardinal Laboratories is accreditated through the State of Colorado Department of Public Health and Environment for:

Method EPA 552.2	Haloacetic Acids (HAA-5)
Method EPA 524.2	Total Trihalomethanes (TTHM)
Method EPA 524.4	Regulated VOCs (V1, V2, V3)

Accreditation applies to public drinking water matrices.

This report meets NELAP requirements and is made up of a cover page, analytical results, and a copy of the original chain-of-custody. If you have any questions concerning this report, please feel free to contact me.

Sincerely,

Celey D. Keine

Celey D. Keene Lab Director/Quality Manager



PARAGON ENVIROMENTAL
CASON SPURLOCK
5002 CARRAIGE RD
HOBBS NM, 88242
Fax To:

Received:	02/11/2022	Sampling Date:	02/09/2022
Reported:	02/15/2022	Sampling Type:	Soil
Project Name:	HOLIDAY 1 BATTERY	Sampling Condition:	** (See Notes)
Project Number:	SPUR	Sample Received By:	Tamara Oldaker
Project Location:	SPUR - EDDY CO NM		

#### Sample ID: NORTH COMP (H220542-01)

BTEX 8021B	mg/	′kg	Analyze	d By: JH					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	02/12/2022	ND	2.11	105	2.00	2.41	
Toluene*	<0.050	0.050	02/12/2022	ND	2.08	104	2.00	2.95	
Ethylbenzene*	<0.050	0.050	02/12/2022	ND	2.08	104	2.00	2.87	
Total Xylenes*	<0.150	0.150	02/12/2022	ND	6.50	108	6.00	2.74	
Total BTEX	<0.300	0.300	02/12/2022	ND					
Surrogate: 4-Bromofluorobenzene (PID	108 9	% 69.9-14	0						
Chloride, SM4500Cl-B	mg/kg		Analyzed By: GM						
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	16.0	16.0	02/14/2022	ND	416	104	400	3.77	
TPH 8015M	mg/kg		Analyzed By: CK						
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10*	<10.0	10.0	02/14/2022	ND	192	96.0	200	3.13	
DRO >C10-C28*	<10.0	10.0	02/14/2022	ND	197	98.6	200	3.00	
EXT DRO >C28-C36	<10.0	10.0	02/14/2022	ND					
Surrogate: 1-Chlorooctane	113 9	66.9-13	6						
Surrogate: 1-Chlorooctadecane	128 9	% 59.5-14	2						

#### Cardinal Laboratories

#### \*=Accredited Analyte

Celeg D. Keine

Celey D. Keene, Lab Director/Quality Manager



PARAGON ENVIROMENTAL	
CASON SPURLOCK	
5002 CARRAIGE RD	
HOBBS NM, 88242	
Fax To:	

Received:	02/11/2022	Sampling Date:	02/09/2022
Reported:	02/15/2022	Sampling Type:	Soil
Project Name:	HOLIDAY 1 BATTERY	Sampling Condition:	** (See Notes)
Project Number:	SPUR	Sample Received By:	Tamara Oldaker
Project Location:	SPUR - EDDY CO NM		

#### Sample ID: EAST COMP (H220542-02)

BTEX 8021B	mg/	/kg	Analyze	d By: JH					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	02/12/2022	ND	2.11	105	2.00	2.41	
Toluene*	<0.050	0.050	02/12/2022	ND	2.08	104	2.00	2.95	
Ethylbenzene*	<0.050	0.050	02/12/2022	ND	2.08	104	2.00	2.87	
Total Xylenes*	<0.150	0.150	02/12/2022	ND	6.50	108	6.00	2.74	
Total BTEX	<0.300	0.300	02/12/2022	ND					
Surrogate: 4-Bromofluorobenzene (PID	106 9	% 69.9-14	0						
Chloride, SM4500Cl-B	mg/	/kg	Analyze	d By: GM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	144	16.0	02/14/2022	ND	416	104	400	3.77	
TPH 8015M	mg/	/kg	Analyze	d By: CK					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10*	<10.0	10.0	02/14/2022	ND	192	96.0	200	3.13	
DRO >C10-C28*	<10.0	10.0	02/14/2022	ND	197	98.6	200	3.00	
EXT DRO >C28-C36	<10.0	10.0	02/14/2022	ND					
Surrogate: 1-Chlorooctane	105 9	% 66.9-13	6						
Surrogate: 1-Chlorooctadecane	117 9	% 59.5-14							

#### Cardinal Laboratories

#### \*=Accredited Analyte

Celez D. Keine

Celey D. Keene, Lab Director/Quality Manager



PARAGON ENVIROMENTAL	
CASON SPURLOCK	
5002 CARRAIGE RD	
HOBBS NM, 88242	
Fax To:	

Received:	02/11/2022	Sampling Date:	02/09/2022
Reported:	02/15/2022	Sampling Type:	Soil
Project Name:	HOLIDAY 1 BATTERY	Sampling Condition:	** (See Notes)
Project Number:	SPUR	Sample Received By:	Tamara Oldaker
Project Location:	SPUR - EDDY CO NM		

#### Sample ID: SOUTH COMP (H220542-03)

BTEX 8021B	mg/	/kg	Analyze	d By: JH					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	02/12/2022	ND	2.11	105	2.00	2.41	
Toluene*	<0.050	0.050	02/12/2022	ND	2.08	104	2.00	2.95	
Ethylbenzene*	<0.050	0.050	02/12/2022	ND	2.08	104	2.00	2.87	
Total Xylenes*	<0.150	0.150	02/12/2022	ND	6.50	108	6.00	2.74	
Total BTEX	<0.300	0.300	02/12/2022	ND					
Surrogate: 4-Bromofluorobenzene (PID	106 9	% 69.9-14	0						
Chloride, SM4500Cl-B	mg/	/kg	Analyze	d By: GM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	32.0	16.0	02/14/2022	ND	416	104	400	3.77	
TPH 8015M	mg/	/kg	Analyze	d By: CK					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10*	<10.0	10.0	02/14/2022	ND	192	96.0	200	3.13	
DRO >C10-C28*	<10.0	10.0	02/14/2022	ND	197	98.6	200	3.00	
EXT DRO >C28-C36	<10.0	10.0	02/14/2022	ND					
Surrogate: 1-Chlorooctane	106 9	% 66.9-13	6						
Surrogate: 1-Chlorooctadecane	120 9	% 59.5-14	2						

#### Cardinal Laboratories

#### \*=Accredited Analyte

Celeg D. Keine

Celey D. Keene, Lab Director/Quality Manager



PARAGON ENVIROMENTAL	
CASON SPURLOCK	
5002 CARRAIGE RD	
HOBBS NM, 88242	
Fax To:	

Received:	02/11/2022	Sampling Date:	02/09/2022
Reported:	02/15/2022	Sampling Type:	Soil
Project Name:	HOLIDAY 1 BATTERY	Sampling Condition:	** (See Notes)
Project Number:	SPUR	Sample Received By:	Tamara Oldaker
Project Location:	SPUR - EDDY CO NM		

#### Sample ID: WEST COMP (H220542-04)

BTEX 8021B	mg/	′kg	Analyze	d By: JH					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Benzene*	<0.050	0.050	02/12/2022	ND	2.11	105	2.00	2.41	
Toluene*	<0.050	0.050	02/12/2022	ND	2.08	104	2.00	2.95	
Ethylbenzene*	<0.050	0.050	02/12/2022	ND	2.08	104	2.00	2.87	
Total Xylenes*	<0.150	0.150	02/12/2022	ND	6.50	108	6.00	2.74	
Total BTEX	<0.300	0.300	02/12/2022	ND					
Surrogate: 4-Bromofluorobenzene (PID	108 9	% 69.9-14	0						
Chloride, SM4500Cl-B	mg/	′kg	Analyze	d By: GM					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
Chloride	32.0	16.0	02/14/2022	ND	416	104	400	3.77	
TPH 8015M	mg/	′kg	Analyze	d By: CK					
Analyte	Result	Reporting Limit	Analyzed	Method Blank	BS	% Recovery	True Value QC	RPD	Qualifier
GRO C6-C10*	<10.0	10.0	02/14/2022	ND	192	96.0	200	3.13	
DRO >C10-C28*	<10.0	10.0	02/14/2022	ND	197	98.6	200	3.00	
EXT DRO >C28-C36	<10.0	10.0	02/14/2022	ND					
Surrogate: 1-Chlorooctane	116 9	% 66.9-13	6						
Surrogate: 1-Chlorooctadecane	133 9	% 59.5-14	2						

#### Cardinal Laboratories

#### \*=Accredited Analyte

Celez D. Keine

Celey D. Keene, Lab Director/Quality Manager



## **Notes and Definitions**

ND	Analyte NOT DETECTED at or above the reporting limit
RPD	Relative Percent Difference
**	Samples not received at proper temperature of 6°C or below.
***	Insufficient time to reach temperature.
-	Chloride by SM4500Cl-B does not require samples be received at or below 6°C

Samples reported on an as received basis (wet) unless otherwise noted on report

#### Cardinal Laboratories

#### \*=Accredited Analyte

Celeg D. Keine

Celey D. Keene, Lab Director/Quality Manager

# (575) 393-2326 FAX (575) 393-2476 101 East Marland, Hobbs, NM 88240

Company Name:	Company Name: Paradon Environmental		BILLTO				
Project Manager:	Project Manager: Cason Spurlock		P.O. #:		_	ANALISIS REQUEST	_
Address: 5002	Address: 5002 Carriage Rd		Company: Sour				
city: Hobbs	State: NM	zip: 88242	Total	Neel			
Phone #: 575-631-6977	т		SS:				
Project #:	Project Owner:		City:				
Project Name:	Spur		State: Zip:				
Project Location:	Hohday 1 Battery		Phone #:				
Sampler Name:	5	-	Fax #:				
FOR LAB USE ONLY		P. MATRIX	PRESERV. SAMPLING				
Lab I.D. Haqusyz	Sample I.D.	(G)RAB OR (C)OM # CONTAINERS GROUNDWATER WASTEWATER SOIL OIL SLUDGE	OTHER : ACID/BASE: ICE / COOL OTHER : DATE	TIME BTEK	TPH-Ext Chlorides		
-	North Comp.	1	5	1000	<		
2	East Comp.	9	•	1	-		
. (J	South Comp.	0	<	1030			
£	WESt Comp.	() () () () () () () () () () () () () (	x t	1045			
analyses. All claims including th service. In no event shall Cardin affiliates or successors arising ou	analyses. All claims including to use of compligance and any other cause whateneous via any user in unit ansary wireture used in contract or fort, shall be formed to the amount pad by the cleant of the special service. In no event shall be cardinal be liable for incidental or consequential damages, including without limitation, business interruptions, loss of use, or loss of profits incurred by client, its subsidiaries, affiliates or successors arising out of or related to the performance of services hereunder by Cardinal, regardless of whether such claim is based upon any of the above stated reasons or otherwise.	co-cover entries y or any camin anishing writering used in contract or (ord, shall be limited to the annual is whittsoever shall be deemed writer and the limited in writing and receive by Cardinal within 30 days at lai damages, including without limitation, business interruptions, loss of use, or less of porfits incurred to the share of the share share of the share of the share of the share of the share share of the share of the share share of the share share of the share of the share of the share of the share share of the share share of the share of the share of the share share of the share of the share share of the share of the share share share of the share share share of the share s	rr rort, snall be limited to the amount pail received by Cardinal within 30 days after ss of use, or loss of profits incurred by c based upon any of the above stated real	d by the client for the ir completion of the applicable client, its subsidiaries, asons or otherwise.			
Relinquished By:	Belling Timp Date: Date:	Received By:	Suladya	Phone Result:	□ Yes □ No	Add'l Phone #: Add'l Fax #:	
Delivered Rv: 1	Time:						
Delivered By: (Circle One)	29.12	CO, SC Sample Condition	IN CHECKED BY:				

Received by OCD: 5/20/2022 12:27:18 PM

Sampler - UPS - Bus - Other:

20.

0 # Ù 00 J

+

Cardinal cannot accept verbal changes. Please fax written changes to (575) 393-2326

0 600

Cool Intact Yes Pres Sample Condition

(Initials)

CHAIN-OF-CUSTODY AND ANALYSIS REQUEST

## Page 35 of 39

**CARDINAL** Laboratories



Appendix F:

Liner Inspection and Email Notification



Paragon Environmental LLC

## **Liner Inspection Form**

Company Name:	Spur Energy Partners		
Site:	Holiday #1H Battery		
Lat/Long:	32.8023071, -104.2290268		
NMOCD Incident ID & Incident Date:	NAPP2119561140		
2-Day Notification Sent:	2-7-22		
Inspection Date:	2-9-22		
Liner Type:	Earthen w/liner	Earthen no liner	Polystar
(	Steel w/poly liner	Steel w/spray epoxy	No Liner

Other:

Visualization	Yes	No	Comments
Is there a tear in the liner?		х	
Are there holes in the liner?		х	
Is the liner retaining any fluids?		Х	
Does the liner have integrity to contain a leak?	х		

Comments: \_\_\_\_\_

Inspector Name: Travis Collins

Inspector Signature: Travis Collins



Cason Spurlock <cason@paragonenvironmental.net>

## Holiday #1 Battery

1 message

Cason <cason@paragonenvironmental.net>

Mon, Feb 7, 2022 at 5:57 AM To: mike.bratcher@state.nm.us, robert.hamlet@state.nm.us, chad.hensley@state.nm.us, Braidy Moulder <br/>
<br/>
spureplic.com>, Dakota Neel <dneel@spureplic.com>

Gentleman,

On behalf of Spur Energy, Paragon will be conducting a liner inspection at the referenced location. This inspection will be conducted in reference to incidents NAPP2119633013, NAPP2119561140, and NRM2026056833. We will be conducting this inspection on 2-9-22 at approximately 9 am. If you have any questions or care to join you can reach out and let me know.

Paragon Environmental 225 Billy Walker Rd Hobbs, NM 88240

District I 1625 N. French Dr., Hobbs, NM 88240 Phone:(575) 393-6161 Fax:(575) 393-0720 District II

811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III

1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

District IV 1220 S. St Francis Dr., Santa Fe, NM 87505 Phone: (505) 476-3470 Fax: (505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Operator:	OGRID:
Spur Energy Partners LLC	328947
9655 Katy Freeway	Action Number:
Houston, TX 77024	109078
	Action Type:
	[C-141] Release Corrective Action (C-141)
	·

#### CONDITIONS

Created By		Condition Date
jnobui	Closure Approved.	8/29/2022

Page 39 of 39

Action 109078