

	New Mexico Form C-103			
	and Natural Resources Revised July 18, 2013			
1625 N. French Dr., Hobbs, NM 88240 District II – (575) 748-1283	WELL API NO. 30-025-21675			
811 S. First St., Artesia, NM 88210 OIL CONSERV	5 Indicate Type of Lease			
1000 Rio Brazos Rd Aztec NM 87/10	St. Francis Dr. STATE X FEE STATE X FEE			
<u>District IV</u> – (505) 476-3460 Santa Fe 1220 S. St. Francis Dr., Santa Fe, NM	e, NM 87505 6. State Oil & Gas Lease No.			
87505				
SUNDRY NOTICES AND REPORTS OF ONE OF THE SUNDRY NOTICES AND REPORTS OF THE	E			
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FOR				
PROPOSALS.) 1. Type of Well: Oil Well X Gas Well Other	8. Well Number 023			
2. Name of Operator	9. OGRID Number			
MORNINGSTAR OPERATING LLC				
3. Address of Operator	10. Pool name or Wildcat			
400 W 7TH ST, FORT WORTH, TX 4. Well Location	76102 VACUUM; GLORIETA			
Unit Letter F : 2310 feet from the	N line and 1860 feet from the W line			
Section 25 Township 1				
	nether DR, RKB, RT, GR, etc.)			
4010 G	BL			
12 Charle Assurantiate Daniel In	L'acta Natara of Nation Domait or Other Date			
12. Check Appropriate Box to In	dicate Nature of Notice, Report or Other Data			
NOTICE OF INTENTION TO:	SUBSEQUENT REPORT OF:			
PERFORM REMEDIAL WORK PLUG AND ABANDON				
TEMPORARILY ABANDON ☐ CHANGE PLANS PULL OR ALTER CASING ☐ MULTIPLE COMPL	☐ COMMENCE DRILLING OPNS.☐ P AND A ☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐☐			
DOWNHOLE COMMINGLE	CASING/CEMENT JOB			
CLOSED-LOOP SYSTEM				
OTHER:	OTHER:			
13. Describe proposed or completed operations. (Clearly state all pertinent details, and give pertinent dates, including estimated date of starting any proposed work). SEE RULE 19.15.7.14 NMAC. For Multiple Completions: Attach wellbore diagram of				
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion.	.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v	.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the value of the start of the value of t	.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v	.14 NMAC. For Multiple Completions: Attach wellbore diagram of			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on	.14 NMAC. For Multiple Completions: Attach wellbore diagram of well:			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi.	.14 NMAC. For Multiple Completions: Attach wellbore diagram of well:			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi. 6) Circulate hole with pkr fluid.	top. Condition of Approval: notify			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi.	14 NMAC. For Multiple Completions: Attach wellbore diagram of well: top. Condition of Approval: notify OCD Hobbs office 24 hours			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi. 6) Circulate hole with pkr fluid. 7) Notify OCD of intent to run MIT and proceed as	14 NMAC. For Multiple Completions: Attach wellbore diagram of well: top. Condition of Approval: notify OCD Hobbs office 24 hours			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi. 6) Circulate hole with pkr fluid. 7) Notify OCD of intent to run MIT and proceed as	top. Condition of Approval: notify			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi. 6) Circulate hole with pkr fluid. 7) Notify OCD of intent to run MIT and proceed as 8) RDMO.	14 NMAC. For Multiple Completions: Attach wellbore diagram of vell: top. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi. 6) Circulate hole with pkr fluid. 7) Notify OCD of intent to run MIT and proceed as 8) RDMO.	14 NMAC. For Multiple Completions: Attach wellbore diagram of well: top. Condition of Approval: notify OCD Hobbs office 24 hours			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi. 6) Circulate hole with pkr fluid. 7) Notify OCD of intent to run MIT and proceed as 8) RDMO.	14 NMAC. For Multiple Completions: Attach wellbore diagram of vell: top. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi. 6) Circulate hole with pkr fluid. 7) Notify OCD of intent to run MIT and proceed as 8) RDMO.	114 NMAC. For Multiple Completions: Attach wellbore diagram of vell: top. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Release Date:			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the version of the start of	114 NMAC. For Multiple Completions: Attach wellbore diagram of vell: top. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Release Date:			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the version of the start of	114 NMAC. For Multiple Completions: Attach wellbore diagram of well: top. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Release Date: te to the best of my knowledge and belief.			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the version of the start of	114 NMAC. For Multiple Completions: Attach wellbore diagram of vell: top. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Release Date:			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi. 6) Circulate hole with pkr fluid. 7) Notify OCD of intent to run MIT and proceed as 8) RDMO. Spud Date: Rig F Signature Connic Blaylock TITE Type or print name Connic Blaylock E-materials.	114 NMAC. For Multiple Completions: Attach wellbore diagram of well: top. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Release Date: te to the best of my knowledge and belief.			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the version of the start of	114 NMAC. For Multiple Completions: Attach wellbore diagram of well: top. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Release Date: te to the best of my knowledge and belief. LE_Regulatory Analyst DATE_03/15/2023			
of starting any proposed work). SEE RULE 19.15.7. proposed completion or recompletion. MorningStar Operating requests approval to TA the v 1) MIRU. 2) POOH w/tubing and pump. 3) RIH w/bit and scraper. POOH. 4) Set 7" CIBP @ 5680'. Dump bail 35' cement on 5) Pressure test plug and casing to 550 psi. 6) Circulate hole with pkr fluid. 7) Notify OCD of intent to run MIT and proceed as 8) RDMO. Spud Date: Rig F Signature Connic Blaylock TITE Type or print name Connic Blaylock E-materials.	Attach wellbore diagram of vell: top. Condition of Approval: notify OCD Hobbs office 24 hours prior of running MIT Test & Chart Release Date: te to the best of my knowledge and belief. LE_Regulatory Analyst DATE_03/15/2023 ail address: _cblaylock@txoenergy.com PHONE: _817-334-7882			

VGWU #23H API No. 30-025-21675



VGWU #23H - PROPOSED API No. 30-025-21675



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 197454

CONDITIONS

Operator:	OGRID:
MorningStar Operating LLC	330132
400 W 7th St	Action Number:
Fort Worth, TX 76102	197454
	Action Type:
	[C-103] NOI Temporary Abandonment (C-103I)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Run TA status MIT/BHT test	3/15/2023