U.S. Department of the Interior BUREAU OF LAND MANAGEMENT

Sundry Print Report

Well Name: ROSS DRAW 30W

FEDERAL COM

Well Location: T26S / R30E / SEC 30 /

SESW /

County or Parish/State: EDDY /

NM

Well Number: 2

Type of Well: CONVENTIONAL GAS

WELL

Allottee or Tribe Name:

Lease Number: NMNM17225A

Unit or CA Name: 2 ROSS DRAW 30W

Unit or CA Number:

FED COM

NMNM106863

**US Well Number:** 3001531722

Well Status: Producing Gas Well

Operator: XTO ENERGY

INCORPORATED

Accepted for record – NMOCD gc 5/4/2023

## **Notice of Intent**

Sundry ID: 2706718

Type of Submission: Notice of Intent

Type of Action: Plug and Abandonment

Date Sundry Submitted: 12/09/2022

Time Sundry Submitted: 02:58

Date proposed operation will begin: 01/23/2023

Procedure Description: XTO Energy Inc respectfully submits a NOI to PA sundry for the above well

## **Surface Disturbance**

Is any additional surface disturbance proposed?: No

## **NOI Attachments**

## **Procedure Description**

Ross\_Draw\_30W\_Fed\_Com\_2\_Procedure\_opt\_20221209145800.pdf

Ross\_Draw\_30W\_Fed\_Com\_2\_Proposed\_WBD\_20221209145619.pdf

Ross\_Draw\_30W\_Fed\_Com\_2\_DHWP\_opt\_20221209145553.pdf

Received by OCD: 4/21/14/2022: 4:59544RAW 30W

FEDERAL COM

Well Location: T26S / R30E / SEC 30 / SESW /

County or Parish/State: EDDY /

Page 2 of 15

Type of Well: CONVENTIONAL GAS Well Number: 2

Allottee or Tribe Name:

Lease Number: NMNM17225A

Unit or CA Name: 2 ROSS DRAW 30W FED COM

Unit or CA Number: NMNM106863

**US Well Number:** 3001531722

Well Status: Producing Gas Well

**Operator: XTO ENERGY INCORPORATED** 

## **Conditions of Approval**

## Specialist Review

ROSS DRAW 30W FED COM 2 2706718 COA AND PROCEDURE 20230106104538.pdf

## **Operator**

I certify that the foregoing is true and correct. Title 18 U.S.C. Section 1001 and Title 43 U.S.C. Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction. Electronic submission of Sundry Notices through this system satisfies regulations requiring a

Operator Electronic Signature: CASSIE EVANS Signed on: DEC 09, 2022 02:56 PM

Name: XTO ENERGY INCORPORATED

Title: Regulatory Analyst

Street Address: 6401 Holiday Hill Road, Bldg 5 State: TX City: Midland

Phone: (432) 218-3671

Email address: CASSIE.EVANS@EXXONMOBIL.COM

## **Field**

Representative Name:

Street Address:

City: State: Zip:

Phone:

Email address:

## **BLM Point of Contact**

**BLM POC Name: KEITH P IMMATTY BLM POC Title: ENGINEER** 

**BLM POC Phone:** 5759884722 BLM POC Email Address: KIMMATTY@BLM.GOV

Disposition: Approved Disposition Date: 01/06/2023

Signature: KEITH IMMATTY

Page 2 of 2

## PLUG AND ABANDON WELLBORE ROSS DRAW 30W FEDERAL COM 002 EDDY COUNTY, NEW MEXICO Class II

MASIP	MAOP	MAWP	Surface Csg Yield
1,000 psi	1,000 psi	3,000 psi	1,980 psi

**SUMMARY:** Plug and abandon wellbore according to BLM regulations.

- 1) MIRU plugging company. Set open top steel pit for plugging.
- 2) ND WH and NU 3K manual BOP. Function test BOP.
- 3) POOH 2-3/8" tubing string.
- 4) MIRU WLU, RIH GR sized for 3-1/2" 9.30# liner to 12175', RIH CIBP and set at 12150'. Notify BLM. Pressure test CIBP to 500 psig for 30 min.
- 5) Spot 40 SKS Class H from 12150' to 11345' (T/Perf, 5-1/2" shoe). WOC, tag and notify BLM.
- 6) MIRU WLU, perforate at 10146'.
- 7) Squeeze <del>50</del> SKS Class H from 10146' to 9996' (T/Wolfcamp). **60 9945'**
- 8) MIRU WLU, perforate at 7000'.
- 9) Squeeze 50 SKS Class C from 7000' to 6810' (T/Bone Spring).

60 6790'

- 10) MIRU WLU, perforate at 5000'.
- 11) Squeeze 25 SKS Class C from 5000' to 4900' (3000' requirement).
- 12) MIRU WLU, perforate at 3175'.
- 13) Squeeze 40 SKS Class C from 3175' to 3016' (T/Delaware, 8-5/8" shoe). WOC, tag and notify BLM.
- 14) BOS: 2290-2167'. 30sx Class C. Perf and sqz.
- 15) TOS: 1325-1212', 30sx Class C. Perf and Sqz
- 16) MIRU WLU, perforate at 985'.
- 17) Squeeze 40 SKS Class C from 985' to 835' (11-3/4" shoe). WOC, tag and notify BLM.
- 18) MIRU WLU, perforate at 500'.
- 19) Circulate Class C to surface (Est. 115 SKS).


500' surface plug for high cave karst area

- 19) Set P&A marker.
- 20) Pull fluid from steel tank and haul to disposal. Release steel tank.


Digitally signed by KEITH IMMATTY
Date: 2023.01.06
10:31:59 -07'00'

## Downhole Well Profile - with Schematic

Well Name: ROSS DRAW 30W FEDERAL COM 002



# Ross Draw 30W Federal Com 002 - Proposed WBD



T/Bone Spring 6910'

8-5/8" shoe 3125'

T/Delaware 3116'

11-3/4" shoe 935'

T/Wolfcamp 10096'

5-1/2" TOC 11100'

T/Perf 12220'

TOL 11135'

Sundry ID 2706718

Sundry ID 2706718						
Plug Type	Тор	Bottom	Length	Tag	Sacks	Notes
				circulated		
Surface Plug	0.00	500.00	500.00	to surface	115.00	Perf and sqz
				WOC and		
Shoe Plug	875.65	985.00	109.35		40.00	Perf and sqz
				WOC and		
Top of Salt @ 1275	1212.25	1325.00	112.75	Tag	30.00	Perf and sqz
				WOC and		
Base of Salt @ 2240	2167.60	2290.00	122.40	Tag	30.00	Perf and sqz
				WOC and		
Delaware @ 3116	3034.84	3166.00	131.16	_	40.00	Same as below plug
				WOC and		
Shoe Plug	3043.75	3175.00	131.25	Tag		Perf and sqz
Spacer	4900.00	5000.00			25.00	Perf and sqz
				WOC and		
Bonesprings @ 6910	6790.90	6960.00	169.10		60.00	Perf and sqz
				WOC and		
Wolfcamp @ 10096	9945.04	10146.00	200.96	Tag	60.00	Perf and sqz
				WOC and		Covered by below
Shoe Plug	11280.55	11495.00	214.45		40.00	
				Verify		Leak test 500psi,
CIBP Plug	12115.00	12150.00	35.00	depth	40.00	30mins

No more than 2000' is to be allowed between plugs in open hole, and no more than 3000' between plugs in cased hole.

Class H >7500'

Class C<7500'

Fluid used to mix the cement in R111P shall be saturated with the salts common to the section penetrated, and in suitable proportions, but not more than 3% calcium chloride by weight of cement will be considered the desired mixture whenever possible.

Critical, High Cave Karst: Cave Karst depth to surface

R111P: Solid plug in all annuli - 50' from bottom of salt to surface.

Class C: 1.32 ft^3/sx Class H: 1.06 ft^3/sx

Onshore Order 2.III.G Drilling Abandonment Requirements: "All formations bearing usable-quality water, oil, gas, or geothermal resources, and/or a prospectively valuable deposit of minerals shall be protected.

Cave Karst/Potash Cement	High	KARST DEPTH/TOS to surface	500.00
Shoe @	935.00	)	
Shoe @	3125.00		
Shoe @	11445.00	)	
Shoe @	12500.00	)	
Perforatons Top @	12220.00	Perforations 12250	.00

CIBP @ 12150.00

## BUREAU OF LAND MANAGEMENT Carlsbad Field Office 620 East Greene Street Carlsbad, New Mexico 88220 575-234-5972

## Permanent Abandonment of Federal Wells Conditions of Approval

Failure to comply with the following Conditions of Approval may result in a Notice of Incidents of Noncompliance (INC) in accordance with 43 CFR 3163.1.

1. Plugging operations shall commence within <u>ninety (90)</u> days from the approval date of this Notice of Intent to Abandon.

If you are unable to plug the well by the 90<sup>th</sup> day provide this office, prior to the 90<sup>th</sup> day, with the reason for not meeting the deadline and a date when we can expect the well to be plugged. Failure to do so will result in enforcement action.

The rig used for the plugging procedure cannot be released and moved off without the prior approval of the authorized officer. Failure to do so may result in enforcement action.

- 2. <u>Notification:</u> Contact the appropriate BLM office at least 24 hours prior to the commencing of any plugging operations. For wells in Chaves and Roosevelt County, call 575-627-0272; Eddy County, call 575-361-2822; Lea County, call 575-689-5981.
- 3. <u>Blowout Preventers</u>: A blowout preventer (BOP), as appropriate, shall be installed before commencing any plugging operation. The BOP must be installed and maintained as per API and manufacturer recommendations. The minimum BOP requirement is a 2M system for a well not deeper than 9,090 feet; a 3M system for a well not deeper than 13,636 feet; and a 5M system for a well not deeper than 22,727 feet.
- 4. <u>Mud Requirement:</u> Mud shall be placed between all plugs. Minimum consistency of plugging mud shall be obtained by mixing at the rate of 25 sacks (50 pounds each) of gel per 100 barrels of **brine** water. Minimum nine (9) pounds per gallon.
- 5. <u>Cement Requirement</u>: Sufficient cement shall be used to bring any required plug to the specified depth and length. Any given cement volumes on the proposed plugging procedure are merely estimates and are not final. Unless specific approval is received, no plug except the surface plug shall be less than 25 sacks of cement. Any plug that requires a tag will have a minimum WOC time of 4 hours.

In lieu of a cement plug across perforations in a cased hole (not for any other plugs), a bridge plug set within 50 feet to 100 feet above the perforations shall be capped with 25 sacks of cement. If a bailer is used to cap this plug, 35 feet of cement shall be sufficient. **Before pumping or bailing cement on top of CIBP, tag will be required to verify depth. Based on depth, a tag of the cement may be deemed necessary.** 

Unless otherwise specified in the approved procedure, the cement plug shall consist of either Neat Class "C", for up to 7,500 feet of depth or Neat Class "H", for deeper than 7,500 feet plugs.

6. <u>Dry Hole Marker</u>: All casing shall be cut-off at the base of the cellar or 3 feet below final restored ground level (whichever is deeper). The BLM is to be notified a minimum of 4 hours prior to the wellhead being cut off to verify that cement is to surface in the casing and all annuluses. Wellhead cut off shall commence within ten (10) calendar days of the well being plugged. If the cut off cannot be done by the 10<sup>th</sup> day, the BLM is to be contacted with justification to receive an extension for completing the cut off.

The well bore shall then be capped with a 4-inch pipe, 10-feet in length, 4 feet above ground and embedded in cement, unless otherwise noted in COA (requirements will be attached). The following information shall be permanently inscribed on the dry hole marker: well name and number, name of the operator, lease serial number, surveyed location (quarter-quarter section, section, township and range or other authorized survey designation acceptable to the authorized officer such as metes and bounds). A weep hole shall be left if a metal plate is welded in place.

- 7. <u>Subsequent Plugging Reporting:</u> Within 30 days after plugging work is completed, file one original and three copies of the Subsequent Report of Abandonment, Form 3160-5 to BLM. The report should give in detail the manner in which the plugging work was carried out, the extent (by depths) of cement plugs placed, and the size and location (by depths) of casing left in the well. **Show date well was plugged.**
- 8. <u>Trash:</u> All trash, junk and other waste material shall be contained in trash cages or bins to prevent scattering and will be removed and deposited in an approved sanitary landfill. Burial on site is not permitted.

Following the submission and approval of the Subsequent Report of Abandonment, surface restoration will be required. See attached reclamation objectives.



## **United States Department of the Interior**

## BUREAU OF LAND MANAGEMENT

Carlsbad Field Office 620 E. Greene St. Carlsbad, New Mexico 88220-6292 www.blm.gov/nm



In Reply Refer To: 1310

## **Reclamation Objectives and Procedures**

**Reclamation Objective:** Oil and gas development is one of many uses of the public lands and resources. While development may have a short- or long-term effect on the land, successful reclamation can ensure the effect is not permanent. During the life of the development, all disturbed areas not needed for active support of production operations should undergo "interim" reclamation in order to minimize the environmental impacts of development on other resources and uses. At final abandonment, well locations, production facilities, and access roads must undergo "final" reclamation so that the character and productivity of the land and water are restored.

The long-term objective of final reclamation is to set the course for eventual ecosystem restoration, including the restoration of the natural vegetation community, hydrology, and wildlife habitats. In most cases this means returning the land to a condition approximating or equal to that which existed prior to the disturbance. The final goal of reclamation is to restore the character of the land and water to its predisturbance condition. The operator is generally not responsible for achieving full ecological restoration of the site. Instead, the operator must achieve the short-term stability, visual, hydrological, and productivity objectives of the surface management agency and take steps necessary to ensure that long-term objectives will be reached through natural processes.

To achieve these objectives, remove any/all contaminants, scrap/trash, equipment, pipelines and powerlines (Contact service companies, allowing plenty of time to have the risers and power lines and poles removed prior to reclamation, don't wait till the last day and try to get them to remove infrastructure). Strip and remove caliche, contour the location to blend with the surrounding landscape, re-distribute the native soils, provide erosion control as needed, rip (across the slope and seed as specified in the original APD COA. This will apply to well pads, facilities, and access roads. Barricade access road at the starting point. If reserve pits have not reclaimed due to salts or other contaminants, submit a plan for approval, as to how you propose to provide adequate restoration of the pit area.

- 1. The Application for Permit to Drill or Reenter (APD, Form 3160-3), Surface Use Plan of Operations must include adequate measures for stabilization and reclamation of disturbed lands. Oil and Gas operators must plan for reclamation, both interim and final, up front in the APD process as per Onshore Oil and Gas Order No. 1.
- 2. For wells and/or access roads not having an approved plan, or an inadequate plan for surface reclamation (either interim or final reclamation), the operator must submit a proposal describing the procedures for reclamation. For interim reclamation, the appropriate time for submittal would be when filing the Well Completion or Recompletion Report and Log (Form 3160-4). For final reclamation, the appropriate time for submittal would be when filing the Notice of Intent, or the Subsequent Report of Abandonment, Sundry Notices and Reports on Wells (Form 3160-5). Interim reclamation is to be completed within 6 months of well completion, and final reclamation is to be completed within 6 months of well abandonment.
- 3. The operator must file a Subsequent Report Plug and Abandonment (Form 3160-5) following the plugging of a well.
- 4. Previous instruction had you waiting for a BLM specialist to inspect the location and provide you with reclamation requirements. If you have an approved Surface Use Plan of Operation and/or an approved Sundry Notice, you are free to proceed with reclamation as per approved APD. If you

have issues or concerns, contact a BLM specialist to assist you. It would be in your interest to have a BLM specialist look at the location and access road prior to the removal of reclamation equipment to ensure that it meets BLM objectives. Upon conclusion submit a Form 3160-5, Subsequent Report of Reclamation. This will prompt a specialist to inspect the location to verify work was completed as per approved plans.

- 5. The approved Subsequent Report of Reclamation will be your notice that the native soils, contour and seedbed have been reestablished. If the BLM objectives have not been met the operator will be notified and corrective actions may be required.
- 6. It is the responsibility of the operator to monitor these locations and/or access roads until such time as the operator feels that the BLM objective has been met. If after two growing seasons the location and/or access roads are not showing the potential for successful revegetation, additional actions may be needed. When you feel the BLM objectives have been met submit a Final Abandonment Notice (FAN), Form 3160-5, stating that all reclamation requirements have been achieved and the location and/or access road is ready for a final abandonment inspection.
- 7. At this time the BLM specialist will inspect the location and/or access road. If the native soils and contour have been restored, and the revegetation is successful, the FAN will be approved, releasing the operator of any further liability of the location and/or access road. If the location and/or access road have not achieved the objective, you will be notified as to additional work needed or additional time being needed to achieve the objective.

If there are any questions, please feel free to contact any of the following specialists:

Jim Amos Supervisory Petroleum Engineering Tech/Environmental Protection Specialist 575-234-5909 (Office), 575-361-2648 (Cell)

Arthur Arias Environmental Protection Specialist 575-234-6230

Crisha Morgan Environmental Protection Specialist 575-234-5987

Jose Martinez-Colon Environmental Protection Specialist 575-234-5951

Mark Mattozzi Environmental Protection Specialist 575-234-5713


Robert Duenas Environmental Protection Specialist 575-234-2229

Trishia Bad Bear, Hobbs Field Station Natural Resource Specialist 575-393-3612 Received by OCD: 4/21/2023 4:59:44 AM



## Downhole Well Profile - with Schematic Well Name: ROSS DRAW 30W FEDERAL COM 002

SAP Cost Center ID Permit Number State/Province County 3001531722 Eddy 3001531722 1137621001 New Mexico Surface Location Spud Date Original KB Elevation (ft) Ground Elevation (ft) KB-Ground Distance (ft) Surface Casing Flange Elevation (ft) T26S-R30E-S30 6/22/2001 00:00 2.914.00



		2,8	914.00						
Wellbores				·					
Wellbore Name		Parent Well	lbore		I \	Wellbore API/L	JWI		
Original Hole		Original							
Start Depth (ftKB)				Profile Type					
0.0				Vertical					
Section Des		Hole Sz (ir		Ac	t Top (ftKB)	0.0	Act Btm (ftKB)		
Surface		14 3/4		0.0				935.0	
ntermediate		11 935.0				3,125.0			
ntermediate			7 7/8			3,125.0		11,445.0	
Production			5 5/8			11,445.0			12,500.0
Casing Strings									
Csg Des	Set Depth (		OI	) (in)	٧	Vt/Len (lb/ft)			Grade
Surface		935.0		11 3/4			42.00		
ntermediate 1		3,125.0		8 5/8			32.00	J-55	
Intermediate 2		11,445.0		5 1/2			17.00	S-95	
Liner-Production		12,500.0		3 1/2			9.30	L-80	
Cement									
Des		7	Гуре	Start Da	ite	Тор	(ftKB)		Btm (ftKB)
Surface Casing Cement		Casing		6/25/2001				0.0	935.0
ntermediate 1 Casing Ce	ement	Casing		6/29/2001		0.		0.0	3,125.0
ntermediate 2 Casing Ce	ement	Casing		7/12/2001			11,100.0		11,445.0
Liner Cement		_		7/20/2001			11,135.0 12,		12,500.0
Tubing Strings									
Tubing Outrings Tubing Description		Run Date				Set Depth (ftKE	3)		
Tubing - Production		8/19/200	)1			11,445.0	-,		
Item Des	OD (in)	Wt (Ib		de Jts	Len	, ,	Top (		Btm (ftKB)
	2 ′	3/8	4.70 L-80		11	,445.00		0.0	11,445.0
Tubing									
	2.								
	Top (ftKl	В)	Btm	(ftKB)			Linked	Zone	
Perforations  Date		B) 12,220.0	Btm	(ftKB) 12,250.0			Linked	Zone	
Tubing  Perforations  Date  7/31/2001  Stimulation Intervals			Btm	,			Linked	Zone	
Perforations  Date 7/31/2001		12,220.0	m (ftKB) 12,250.0	12,250.0	min)	MIR (bb		Zone	Proppant Total (lb)

Page 1/1 Report Printed: 12/1/2022

District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

**State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division** 1220 S. St Francis Dr. **Santa Fe, NM 87505** 

CONDITIONS

Action 209551

## **CONDITIONS**

Operator:	OGRID:
XTO ENERGY, INC	5380
6401 Holiday Hill Road	Action Number:
Midland, TX 79707	209551
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

## CONDITIONS

Created By		Condition Date
gcordero	None	5/4/2023