
Office	ate of New Mexico	Form C-1031
<u>District I</u> – (575) 393-6161 Energy, Minerals and Natural Resources 1625 N. French Dr., Hobbs, NM 88240		Revised July 18, 2013 WELL API NO.
District II – (575) 748-1283 811 S. First St., Artesia, NM 88210 OIL CON	ISERVATION DIVISION	30-025-31388
	South St. Francis Dr.	5. Indicate Type of Lease
1000 Rio Brazos Rd., Aztec, NM 87410		STATE FEE 6. State Oil & Gas Lease No.
<u>District IV</u> – (505) 476-3460 1220 S. St. Francis Dr., Santa Fe, NM 87505	anta 1 0, 14141 0 7 3 0 3	6. State Off & Gas Lease No.
SUNDRY NOTICES AND REPORTS ON WELLS (DO NOT USE THIS FORM FOR PROPOSALS TO DRILL OR TO DEEPEN OR PLUG BACK TO A		7. Lease Name or Unit Agreement Name
DIFFERENT RESERVOIR. USE "APPLICATION FOR PERMIT" (FORM C-101) FOR SUCH		Arrowhead Grayburg Unit
PROPOSALS.) 1. Type of Well: Oil Well Gas Well Other		8. Well Number 212
2. Name of Operator		9. OGRID Number 330679
Empire Petroleum Corporation		7. OGIGE TURBET 330079
3. Address of Operator		10. Pool name or Wildcat
2200 S. Utica Place, Suite 150, Tulsa, Oklahoma 74114		Arrowhead; Grayburg
4. Well Location		
Unit Letter M : 630 feet f	from the <u>South</u> line and _	660 feet from the West line
Section 7 Town	ship 22S Range 37E	NMPM Lea County
11. Elevation (S	Show whether DR, RKB, RT, GR, etc.	•
3437' GR		
12. Check Appropriate Bo	x to Indicate Nature of Notice,	Report or Other Data
NOTICE OF INTENTION TO	S. CLID	CECUENT DEPORT OF
NOTICE OF INTENTION TO PERFORM REMEDIAL WORK ☑ PLUG AND ABA		SEQUENT REPORT OF: K
TEMPORARILY ABANDON CHANGE PLAN		_
		-
-	WIPL CASING/CEMEN	I JOB
DOWNHOLE COMMINGLE		
OLOGED LOOP OVOTEM		
CLOSED-LOOP SYSTEM OTHER:		П
OTHER:	OTHER:	d give pertinent dates, including estimated date
OTHER: 13. Describe proposed or completed operations.	(Clearly state all pertinent details, and	
OTHER:	(Clearly state all pertinent details, and	
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE	(Clearly state all pertinent details, and	
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion.	(Clearly state all pertinent details, and	
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig	(Clearly state all pertinent details, and	
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Con	mpletions: Attach a wellbore diagram of
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Con	mpletions: Attach a wellbore diagram of
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Con	mpletions: Attach a wellbore diagram of Condition of Approval: notify
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of the conduction o	mpletions: Attach a wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of the conduction o	mpletions: Attach a wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of the conduction o	mpletions: Attach a wellbore diagram of Condition of Approval: notify
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of the conduction o	mpletions: Attach a wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of the conduction o	mpletions: Attach a wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of the conduction o	mpletions: Attach a wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of the conduction o	mpletions: Attach a wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO. 11. RTI.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of the conduction o	mpletions: Attach a wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO. 11. RTI.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of Section 2	mpletions: Attach a wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO. 11. RTI.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction of Section 2	mpletions: Attach a wellbore diagram of Condition of Approval: notify OCD Hobbs office 24 hours
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO. 11. RTI.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Cond set @ 3415'.	Condition of Approval: notify OCD Hobbs office 24 hours for of running MIT Test & Chart
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO. 11. RTI.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conducted Set @ 3415'. DCD. Rig Release Date:	Condition of Approval: notify OCD Hobbs office 24 hours for of running MIT Test & Chart e and belief.
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction & State & S	Condition of Approval: notify OCD Hobbs office 24 hours for of running MIT Test & Chart e and belief. DATE 10/10/2023
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO. 11. RTI. Spud Date:	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conduction & State & S	Condition of Approval: notify OCD Hobbs office 24 hours for of running MIT Test & Chart e and belief. DATE 10/10/2023
OTHER: 13. Describe proposed or completed operations. of starting any proposed work). SEE RULE proposed completion or recompletion. 1. MIRU workover rig 2. Unset packer and scan tubing OOH. 3. RIH with RBP and set @ 3453'. 4. Pressure test casing. 5. Remediate any casing integrity issues. 6. RIH with redressed packer and tubing an 7. Circulate packer fluid down the backside 8. Notify NMOCD of MIT. 9. Perform MIT and submit results to NMC 10. RDMO. 11. RTI.	(Clearly state all pertinent details, and 19.15.7.14 NMAC. For Multiple Conducted Set @ 3415'. DCD. Rig Release Date:	Condition of Approval: notify OCD Hobbs office 24 hours for of running MIT Test & Chart e and belief. DATE 10/10/2023

Current and Proposed WBD



District I
1625 N. French Dr., Hobbs, NM 88240
Phone: (575) 393-6161 Fax: (575) 393-0720

District II 811 S. First St., Artesia, NM 88210 Phone:(575) 748-1283 Fax:(575) 748-9720

District III 1000 Rio Brazos Rd., Aztec, NM 87410 Phone:(505) 334-6178 Fax:(505) 334-6170

1220 S. St Francis Dr., Santa Fe, NM 87505 Phone:(505) 476-3470 Fax:(505) 476-3462

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. **Santa Fe, NM 87505**

CONDITIONS

Action 274290

CONDITIONS

Operator:	OGRID:
Empire New Mexico LLC	330679
2200 S. Utica Place	Action Number:
Tulsa, OK 74114	274290
	Action Type:
	[C-103] NOI Workover (C-103G)

CONDITIONS

Created By	Condition	Condition Date
kfortner	Run PWOT MIT/BHT	10/13/2023