Received by QCD 34/2/2025 10:17:48 A. Phone: (505) 476-3441 General Information Phone: (505) 629-6116	M State of New Mexi Energy, Minerals and Natura	Resources	Form Cost Revised July 18, 2 LL API NO. 30-005-00887	
Online Phone Directory Visit: https://www.emnrd.nm.gov/ocd/contact-us/	OIL CONSERVATION D 1220 South St. Franci Santa Fe, NM 875	s Dr.	ndicate Type of Lease STATE FEE state Oil & Gas Lease No.	
(DO NOT USE THIS FORM FOR PROPOS DIFFERENT RESERVOIR. USE "APPLIC	CES AND REPORTS ON WELLS SALS TO DRILL OR TO DEEPEN OR PLUG CATION FOR PERMIT" (FORM C-101) FOR	BACK TO A ROC	ease Name or Unit Agreement Nam CK QUEEN UNIT	e
PROPOSALS.) 1. Type of Well: Oil Well	Gas Well Other	8. V	Vell Number #33	
2. Name of Operator GREAT WES		9. 0	OGRID Number	
3. Address of Operator PO BOX 10	659, MIDLAND, TX 79702		Pool name or Wildcat PROCK; QUEEN	
4. Well Location P Unit Letter : 660	feet from the SOUTH	line and 660	feet from the EAST line	
27 Section		Range	NMPM CHAVES Cour	ntu.
27 Section	11. Elevation (Show whether DR, F		NMFM CHAVES Cour	ity
	4,424'GL			
12. Check Ap	ppropriate Box to Indicate Natur	e of Notice, Repor	t or Other Data	
	PLUG AND ABANDON FOR CHANGE PLANS COMPL COMPLETE COMPL COMPLETE COMPL COMPLETE COMPL COMPLETE COMPLICATION COMPLETE COMPLICATION COMPLETE COMPLETE COMPLICATION COMPL	EMEDIAL WORK COMMENCE DRILLING ASING/CEMENT JOB OTHER: nent details, and give p	pertinent dates, including estimated of	
proposed completion or recon MIRU Unit 1. If necessary, kill well and	ND wellhead. NU BOP	or Multiple Completion	ns: Attach wellbore diagram of	
2. Release packer and POOH3. Fill hole to surface with from the control of the				
4. RIH w/ wireline and tag ar				
5. RU and run GR / CCL / C				
6. Perform MIT on 4"				
7. RDMO unit				
8. Prepare and submit remain	ning Plug and Abandonment proceed	dure		
Spud Date: APRIL 9, 1955	Rig Release Date:	APRIL 21, 1955		
·	<u>_</u>		<u></u>	
I hereby certify that the information al	is two and samplets to the best			
Thorough corting that the information at	bove is true and complete to the best of	f my knowledge and b	elief.	
SIGNATURE SIGNATURE			elief. EUM ENGINEER DATE 9-9-2025	
900/102	TITLE CONTRACT	CONSULTING PETROLE		

Form 3160-5 (October 2024)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED

	OMB No. 1004-0220
	Expires: October 31, 202
5 Lease Serial No.	

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an abandoned well. Use Form 3160-3 (APD) for such proposals.

NM-04365	
If Indian Allottee or Tribe Name	

				7. If Unit of CA/Agreement, Name and/or No.
	TRIPLICATE - Other instr	uctions on page 2		7. If Office of CATAgreement, Ivanic and/of Ivo.
1. Type of Well				
Oil Well Gas V	holomed			8. Well Name and No. ROCK QUEEN UNIT #33
2. Name of Operator GREAT WESTE	RN DRILLING COMPAN	Y, LLC.		9. API Well No. 30-005-00890
3a. Address 700 W. LOUISIANA, MI	DLAND, TEXAS 79702	3b. Phone No. (include area code)		10. Field and Pool or Exploratory Area
,	,,	(432) 682-5241		CAPROCK; QUEEN
4. Location of Well (Footage, Sec., T.,F	.,M., or Survey Description,			11. Country or Parish, State
990' FSL & 1650' FEL, UNIT LETTER O, SEC. 27, T13S, R31E, NMPM.		CHAVES COUNTY, TEXAS		
12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE O	F NOTI	CE, REPORT OR OTHER DATA
TYPE OF SUBMISSION		TYPE	OF ACT	TION
Notice of Intent	Acidize	Deepen	Produ	uction (Start/Resume) Water Shut-Off
Trouce of ment	Alter Casing	Hydraulic Fracturing	Recla	mation Well Integrity
Subsequent Report	Casing Repair	New Construction	Reco	mplete Other
subsequent report	Change Plans	✓ Plug and Abandon	Temp	porarily Abandon
Final Abandonment Notice	Convert to Injection	Plug Back	Wate	r Disposal
the proposal is to deepen directiona the Bond under which the work wil	lly or recomplete horizontal	ly, give subsurface locations and mea e Bond No. on file with BLM/BIA. R	sured an Required	ate of any proposed work and approximate duration thereof. If d true vertical depths of all pertinent markers and zones. Attach subsequent reports must be filed within 30 days following new interval, a Form 3160-4 must be filed once testing has been

- completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)
 - 1) MIRU unit.
 - 2) If necessary, kill well and ND well head, NU BOPE.
 - 3) Release packer and POOH w/ tubing and packer.
 - RIH w/ wireline to tag, and confirm, TD.
 - 5) RIH w/ bailer and dump 2 sx "C" cement at TD sufficient for TOC above 3019'.
 - 6) WOC and fill hole to surface with fresh water.
 - 7) RIH w/ wireline and tag TOC to confirm PBTD.
 - 8) RU and run GR/CCL/CBL well log.
 - 9) Perform MIT on 5-1/2" casing.
 - 10) RDMO unit.

11) Prepare and submit remaining Plug and Abandonment procedure.

Work to be performed within 60 days along with submitting plugging sundry


14. I hereby certify that the foregoing is true and correct. Name (<i>Printed/Typed</i>) BILLY W. HARRIS	CONTRACT CONSULTING PETROLEUM ENGINEER
Signature Work our I	Date 08/14/2025
THE SPACE FOR FEDE	RAL OR STATE OFICE USE
Approved by	Petroleum Engineer Date 08/19/2025
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.	Office RFO
THE LOTTING OF A LOST AND LOTTING A LOST AND LOTTING OF A LOST AND LOTTING OF A LOST AND LOTTING A LOST AND LOTTING AND LOTT	

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

ROCK QUEEN UNIT #33

ELEVATIONS
KB= 4423'
DF= 4421'
GL= 4414'



Others: originally **FEDERAL HINKLE #4**, later **ROCK QUEEN UNIT #27-**SEC: 27 O, T13S, R31E, 1650' FEL & 990' FSL
Chaves County, New Mexico

__" Conductor set @ __'.

" Hole to 326'.

8-5/8" 24# 8rd ___csg (__jts) set @ 302'. Cmtd w/ 200 sx on 11/__/1955.

TOC 8-5/8" @ _____ (returned __ bbls).

" Hole 0'-3019' by rotary tools.
" Hole to 3019'-3029' by cable tool.

FEDERAL LSE: NM04385 API: 30-005-00890 AFE: (internal GWDC) SPUD: 11/19/1955 COMPL: 12/01/1955

FORMATION	TOPS, KB
Red Beds	300'
Anhydrite+Shale	1450'
Salt+Anhydrite	1510'
Shale+Anhydrite	2150'
Sand+Shale	2280'
Sd, Sh, Lime Strgrs	2410'
Sand	3020
T/Queen	3020'
TD rotary tools	3027'
TD cable tools	3029'

TOC 5-1/2" @ ____' by ____ on __/__/___.

5-1/2" AS1-X nickel-plated pkr w/ 1.5 "F" profile nipple (Globe Energy's) set @ 2933'-2940' in 10k tension on 2-3/8", 4.7#, 8rd, EUE, J55, regular IPC tbg, ____' (92 jts). Set on 06/07/2013.

5-1/2" TIGHT SPOT/ CSG LEAK OPERATIONS - Mar 2011 & Jun 2013

03/02/2011: 5-1/2" plastic-coated AD-1 tension RBP unable to pass 2792'.

03/03/2011: 4-3/4" csg swedge, 3-3/4" bmpr sub, 3-3/4" hydr jars on 2-7/8" tbg wrk thru 2792' w/ up/dwn 30k-40k over string wt - unable to swedge out.

03/04/2011: 4-3/4" tapered mill, DC's on 2-7/8" tbg ream/wrk thru 2972' area. Slight bmp w/ 5-1/2" pkr run pass-thru, POOH 20k over string wt @2792'; Reran twice w/o drag or add'l pull wt. Pkr set @2975', +500# tst held ok. POOH, rplace pkr rubber, RIH w/ AD-1 pkr set @ 2975', 520# 30-min tst held ok.

03/07/2011: Ran req'd MIT @ 520# for 30-min w/ no press loss (BLM not witnessed) - charts sent to BLM & NM OCD.

04/10/2012: Annual MIT req'd - tstd 540# for 31 min - good tst, NM OCD witnessed charts to BLM & NM OCD.

06/13/2013: Rls pkr, move up & set @ 2777 (had 4k overpull) tst tbg/csg annulus to 560# -leaked to 530# in 30 min. Rls, PU, set @ 2935'; Tst 5-1/2" csg 0' - 2940' w/ 520#, leaked to 510# in 30 min. 06/07/2013: Set Pkr @ 2933'-2940'; tst tbg/csg annulus @ 570# for 15 min. w/ no # loss. NU Larkin head.

06/10/2013: Took 31 min. MIT @ 590# ending @580# NM OCD witness w/ chart copy to BLM.

5-1/2" 14# 8rd__<mark>_, ___cs</mark>g (___jts) set @ 3026' KB. Cmtd w/ 100 sx "__" on 11/__/1955 (returned__bbls cmt to surface).

Pulled 10K tension on pkr. Installed 2" full-opening Al-Br tbg valve.

TD rotary tools @ 3019' on 11/__/1955.

TD cable tools @ 3029' on 11/__/1955.

TD = 3034' (appears in BLM Sundry report approved 03/31/2011).

BHT =No Record Found.

NOTE: Yellow Highlighted Diagram Text denotes non-updated, missing, unverified, or unknown data.

ROCK QUEEN UNIT #33

ELEVATIONS
KB= 4423'
DF= 4421'
GL= 4414'



Others: originally **FEDERAL HINKLE #4**, later **ROCK QUEEN UNIT #27-**SEC: 27 O, T13S, R31E, 1650' FEL & 990' FSL
Chaves County, New Mexico

__" Conductor set @ __'.

" Hole to 326'.

8-5/8" 24# 8rd ___csg (__jts) set @ 302'. Cmtd w/ 200 sx on 11/__/1955.

TOC 8-5/8" @ _____ (returned __ bbls).

" Hole 0'-3019' by rotary tools.
" Hole to 3019'-3029' by cable tool.

FEDERAL LSE: NM04385 API: 30-005-00890 AFE: (internal GWDC) SPUD: 11/19/1955 COMPL: 12/01/1955

FORMATION	TOPS, KB
Red Beds	300'
Anhydrite+Shale	1450'
Salt+Anhydrite	1510'
Shale+Anhydrite	2150'
Sand+Shale	2280'
Sd, Sh, Lime Strgrs	2410'
Sand	3020
T/Queen	3020'
TD rotary tools	3027'
TD cable tools	3029'

TOC 5-1/2" @ ____' by ____ on __/__/___.

5-1/2" AS1-X nickel-plated pkr w/ 1.5 "F" profile nipple (Globe Energy's) set @ 2933'-2940' in 10k tension on 2-3/8", 4.7#, 8rd, EUE, J55, regular IPC tbg, _____' (92 jts). Set on 06/07/2013.

5-1/2" TIGHT SPOT/ CSG LEAK OPERATIONS - Mar 2011 & Jun 2013

03/02/2011: 5-1/2" plastic-coated AD-1 tension RBP unable to pass 2792'.

03/03/2011: 4-3/4" csg swedge, 3-3/4" bmpr sub, 3-3/4" hydr jars on 2-7/8" tbg wrk thru 2792' w/ up/dwn 30k-40k over string wt - unable to swedge out.

03/04/2011: 4-3/4" tapered mill, DC's on 2-7/8" tbg ream/wrk thru 2972' area. Slight bmp w/ 5-1/2" pkr run pass-thru, POOH 20k over string wt @2792'; Reran twice w/o drag or add'l pull wt. Pkr set @2975', +500# tst held ok. POOH, rplace pkr rubber, RIH w/ AD-1 pkr set @ 2975', 520# 30-min tst held ok.

03/07/2011: Ran req'd MIT @ 520# for 30-min w/ no press loss (BLM not witnessed) - charts sent to BLM & NM OCD.

04/10/2012: Annual MIT req'd - tstd 540# for 31 min - good tst, NM OCD witnessed charts to BLM & NM OCD.

06/13/2013: Rls pkr, move up & set @ 2777 (had 4k overpull) tst tbg/csg annulus to 560# -leaked to 530# in 30 min. Rls, PU, set @ 2935'; Tst 5-1/2" csg 0' - 2940' w/ 520#, leaked to 510# in 30 min. 06/07/2013: Set Pkr @ 2933'-2940'; tst tbg/csg annulus @ 570# for 15 min. w/ no # loss. NU Larkin head. Pulled 10K tension on pkr. Installed 2" full-opening Al-Br tbg valve.

06/10/2013: Took 31 min. MIT @ 590# ending @580# NM OCD witness w/ chart copy to BLM.

5-1/2" 14# 8rd__<mark>_, ___cs</mark>g (___jts) set @ 3026' KB. Cmtd w/ 100 sx "__" on 11/__/1955 (returned__bbls cmt to surface).

TD rotary tools @ 3019' on 11/__/1955.

TD cable tools @ 3029' on 11/__/1955.

TD = 3034' (appears in BLM Sundry report approved 03/31/2011).

BHT =No Record Found.

NOTE: Yellow Highlighted Diagram Text denotes non-updated, missing, unverified, or unknown data.

Form 3160-5 (October 2024)

UNITED STATES DEPARTMENT OF THE INTERIOR **BUREAU OF LAND MANAGEMENT**

FORM APPROVED

Expires: October 31, 20
5 Lease Serial No.

SUNDRY NOTICES AND REPORTS ON WELLS Do not use this form for proposals to drill or to re-enter an

5. Lease Serial No. NM-04365	7 - 6	-
6. If Indian, Allottee or Tribe Name		

abandoned wen.	JSE FUITI 3 100-3 (A	PD) ioi sucii proposais	•			50000000000000000000000000000000000000
SUBMIT IN	TRIPLICATE - Other instr	uctions on page 2		7. If Unit of CA/Agreer	ment, Name and/or No.	-
1. Type of Well						
Oil Well Gas W				8. Well Name and No.	ROCK QUEEN UNIT #3	33
2. Name of Operator GREAT WESTE	RN DRILLING COMPAN	Y, LLC.		9. API Well No. 30-005	5-00890	
3a. Address 700 W. LOUISIANA, MI	DLAND TEXAS 79702	3b. Phone No. (include area code	:)	10. Field and Pool or E	xploratory Area	_
7.00 11. 200.00 11. 1, 11.	DE/1110, 12/010 70/02	(432) 682-5241		CAPROCK; QUEEN	1 -	
4. Location of Well (Footage, Sec., T.,R	.,M., or Survey Description,			11. Country or Parish, S	State	
990' FSL & 1650' FEL, UNIT LETT	ER O, SEC. 27, T13S, R	31E, NMPM.		CHAVES COUNTY	, TEXAS	
12. CHE	CK THE APPROPRIATE B	OX(ES) TO INDICATE NATURE	OF NOTI	ICE, REPORT OR OTHI	ER DATA	
TYPE OF SUBMISSION		TYI	PE OF AC	TION		
Notice of Intent	Acidize	Deepen	Prod	luction (Start/Resume)	Water Shut-Off	
Trouce of Intent	Alter Casing	Hydraulic Fracturing	Recl	amation	Well Integrity	
Subsequent Report	Casing Repair	New Construction	Reco	omplete	Other	
succequent report	Change Plans	✓ Plug and Abandon	Tem	porarily Abandon		
Final Abandonment Notice	Convert to Injection	Plug Back	Wate	er Disposal		
 Describe Proposed or Completed O the proposal is to deepen directional 	peration: Clearly state all pe lly or recomplete horizontal	ertinent details, including estimated ly, give subsurface locations and m	starting d	ate of any proposed work	k and approximate duration all pertinent markers and	on thereof. If I zones. Attach

- the Bond under which the work will be perfonned or provide the Bond No. on file with BLM/BIA. Required subsequent reports must be filed within 30 days following completion of the involved operations. If the operation results in a multiple completion or recompletion in a new interval, a Form 3160-4 must be filed once testing has been completed. Final Abandonment Notices must be filed only after all requirements, including reclamation, have been completed and the operator has detennined that the site is ready for final inspection.)
 - 1) MIRU unit.
 - 2) If necessary, kill well and ND well head, NU BOPE.
 - 3) Release packer and POOH w/ tubing and packer.
 - RIH w/ wireline to tag, and confirm, TD.
 - 5) RIH w/ bailer and dump 2 sx "C" cement at TD sufficient for TOC above 3019'.
 - 6) WOC and fill hole to surface with fresh water.
 - 7) RIH w/ wireline and tag TOC to confirm PBTD.
 - 8) RU and run GR/CCL/CBL well log.
 - 9) Perform MIT on 5-1/2" casing. 10) RDMO unit.

11) Prepare and submit remaining Plug and Abandonment procedure.

Work to be performed within 60 days along with submitting plugging sundry

14. I hereby certify that the foregoing is true and correct. Name (Printed/Typed)	CONTRACT CONCULTING DETROLEUM ENGINEER			
BILLY W. HARRIS	CONTRACT CONSULTING PETROLEUM ENGINEER Title			
Signature Workan I	Date 08/14/2025			
THE SPACE FOR FEDE	RAL OR STATE OFICE USE			
Approved by				
	Petroleum Engineer 08/19/2025			
Conditions of approval, if any, are attached. Approval of this notice does not warrant of certify that the applicant holds legal or equitable title to those rights in the subject leas which would entitle the applicant to conduct operations thereon.				

Title 18 U.S.C Section 1001 and Title 43 U.S.C Section 1212, make it a crime for any person knowingly and willfully to make to any department or agency of the United States any false, fictitious or fraudulent statements or representations as to any matter within its jurisdiction.

(Instructions on page 2)

Sante Fe Main Office Phone: (505) 476-3441

General Information Phone: (505) 629-6116

Online Phone Directory https://www.emnrd.nm.gov/ocd/contact-us

State of New Mexico Energy, Minerals and Natural Resources Oil Conservation Division 1220 S. St Francis Dr. Santa Fe, NM 87505

CONDITIONS

Action 504245

CONDITIONS

Operator:	OGRID:
GREAT WESTERN DRILLING CO	9338
P.O. Box 1659	Action Number:
Midland, TX 79701	504245
	Action Type:
	[C-103] NOI Plug & Abandon (C-103F)

CONDITIONS

Created By		Condition Date
loren.diede	Notify the OCD inspection supervisor via email 24 hours prior to beginning Plug & Abandon (P&A) operations.	9/10/2025
loren.diede	Submit the CBL tif file to NMOCD for upload into the Well Log File.	9/10/2025