

Bratcher, Mike, EMNRD

From: Fred Holmes [fred@etechenv.com]
Sent: Wednesday, September 21, 2011 12:46 PM
To: Bratcher, Mike, EMNRD; tgregsto@blm.gov
Cc: 'Daniel Frick'; 'Ron Ragland'; 'Joe Hernandez'
Subject: LINN Energy - JL Keel B #61 Flowline Release - Initial C-141
Attachments: LINN Energy - JL Keel B #61 Flowline Release - Initial C-141 092111.pdf; JL Keel 61 Release Assessment Map 091911.pdf; JL Keel B 61 Photo Log 091911.pdf; LINN ENergy - J.L. Keel 61 FL Corrective Action Plan - Short Form 092111.pdf

Mike & Terry:

Please find attached the initial C-141 for the JL Keel B # 61 Flowline Release. Also attached is the site map, photo log, and corrective action plan. Please let me know if you have any questions.

Regards,

Fred Holmes

Etech Environmental & Safety Solutions, Inc.

P.O. Box 8469

Midland, Texas 79708-8469

Phone: 432-563-2200

Fax: 432-563-2213

E-mail: fred@etechenv.com

CONFIDENTIAL

This e-mail message, including any attachments, is intended solely for the individual(s) named above. It contains confidential and/or proprietary information. If you are not the intended recipient, please do not read, copy or distribute it or any information it contains. Please immediately notify the sender by return mail and delete it.



Corrective Action Report – Short Form

(To Accompany C-141)

Date: 09/21/11

Lease Name: J.L. Keel Well #61

Type of Contamination: ☒ Hydrocarbon ☒ Produced Water ☐ Other (Specify):

Cause of Release: Over-pressure of line from scale buildup causing line to rupture

1.0 Site Information

General Setting and Area of Impact (Check All that Apply):

☐ Pad Only ☐ Road Only ☒ Off-Site Areas Impacted: ☐ Flat ☒ Sloped ☐ Drainage Features Impacted

Estimated Depth of Contamination: .5 - 1 Feet, Vertical

Estimated Area of Contamination: 2600 Square Feet

Site Delineated: ☐ No ☒ Yes Method: ☒ Visual (probe/shovel) ☐ Sampling & Analysis (Attach Analysis)

2.0 Corrective Actions to Be Taken

Remedial Action Goals: ☒ Hydrocarbons <5,000 mg/kg ☒ Chlorides <1,000 mg/kg

Other (Specify):

Estimated Start Date: 10/10/11

Estimated Completion Date: 10/17/11

2.1 Remedial Actions (Check All That Apply):

☒ Dig & Haul Disposal Site: ☐ CRI ☒ Lea Land ☐ Sundown ☐ Other (Specify):

☐ Blending ☐ Biological Degradation ☐ Irrigation ☐ Calcium Amendment & Irrigation

☐ Cap & Cover Cap Material: ☐ Clay ☐ Caliche ☐ Native Soil

☐ Liner: Mil Thickness: , Installation Depth: Feet

☐ Other (Specify):

2.2 Clearance Confirmation Sampling to be Performed: ☒ Yes ☐ No

3.0 Restoration Activities (Check All That Apply)

☒ Installation of Top Soil ft. ☒ Contour to Grade


☐ Erosion Control: ☐ Water Bars ☐ Rip/Rap ☐ Other (Specify):

☐ Seeding: ☐ Natural ☐ BLM Seed Mix #2 ☐ BLM Seed Mix #3 ☐ BLM Seed Mix #4

☒ Other: 50/50 Mix of BLM 2 & 4.

Other Notes or Actions:

Spill area resides in a potential historical spill site present prior to acquisition of the lease. This area will be investigated and remediated if required at the time this release is remediated. Also, spill is in a pipeline ROW operated by Yates. Line is marked as a "Water Line". Photos and site map attached.



Scale 1:1,200



0 40 80 120 160 200
1" = 100.0 ft Data Zoom 17-0

J.L. Keel B #61 Flowline Release Assessment Map



MN (7 8° E)

Data use subject to license.

© DeLorme. XMap® 7.

www.delorme.com



Photo No: 1.	
Direction Taken: Down	
Description: Lease sign	

Photo No: 2.	
Direction Taken: Northeast	
Description: View of spill area from road side. Not pipeline ROW Marker in left foreground.	

