


District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
1301 W. Grand Avenue, Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S St Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources  
Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505



Form C-141  
Revised March 17, 1999

Submit 2 Copies to appropriate  
District Office in accordance  
with Rule 116 on back  
side of form

**Release Notification and Corrective Action**

nJMW1229349116

**OPERATOR**

☒ Initial Report ☐ Final Report

Name of Company Devon Energy 6137	Contact Tracy Kidd
Address P. O. Box 250 Artesia, NM 88211	Telephone No. 575-513-0628
Facility Name Cotton Draw Unit 153H	Facility Type Oil Well

Surface Owner	Mineral Owner	Lease No.
---------------	---------------	-----------

APT# 30-015-38535

**LOCATION OF RELEASE**

Unit Letter B	Section 3	Township 25S	Range 31E	Feet from the 200	North/South Line North	Feet from the 1980	East/West Line East	County Eddy
------------------	--------------	-----------------	--------------	----------------------	---------------------------	-----------------------	------------------------	----------------

**NATURE OF RELEASE**

Type of Release Produced Water	Volume of Release 15 BBLS	Volume Recovered 15 BBLS
Source of Release Tank Overflow	Date and Hour of Occurrence 10/6/12, 3:00 AM	Date and Hour of Discovery 10/6/12, 3:00AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Jim Amos, OCD & Mike Bratcher, BLM	
By Whom? Gracie Bustamante	Date and Hour 10/08/12, OCD 3:45PM BLM 3:34PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*

N/A

Describe Cause of Problem and Remedial Action Taken.\*

At the Cotton Draw Unit 153 Battery, the scada pack battery lost connection after blowing a fuse that was caused by the cold weather, resulted in a 15 barrel spill of produced water.

Describe Area Affected and Cleanup Action Taken.\*

At the Cotton Draw Unit 153 Battery, the scada pack battery lost connection after blowing a fuse that was caused by the cold weather, resulted in a 15 barrel spill of produced water. After the battery failed the water transfer pump turned off which allowed the water tanks to fill up and overflow. By the time the night rider arrived the produced water was spilling over into the lined containment. The night rider immediately contacted the pumper who then contacted a wash crew and vacuum truck. They washed and cleaned the containment, recovering 15 barrels of produced water.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCd rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCd marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCd acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: Gracie Bustamante		OIL CONSERVATION DIVISION	
Printed Name: Gracie Bustamante		Approved by District Supervisor: Signed By <u>Mike Bratcher</u>	
Title: Field Adm. Support		Approval Date: <b>OCT 19 2012</b>	Expiration Date:
Date: 10/8/12 Phone: (575) 746-5561		Conditions of Approval:	Attached <input type="checkbox"/>

\* Attach Additional Sheets If Necessary

Remediation per OCD Rules &  
Guidelines. **SUBMIT REMEDIATION**

**PROPOSAL NOT LATER THAN:**

Nov. 19, 2012

2RP-1329