

District I
1625 N. French Dr., Hobbs, NM 88240
District II
1301 W. Grand Avenue, Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised October 10, 2003

Submit 2 Copies to appropriate
District Office in accordance
with Rule 116 on back
side of form

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company COG Operating LLC	Contact Pat Ellis
Address 550 W. Texas, Suite 1300 Midland, Texas 79701	Telephone No. (432) 230-0077
Facility Name Schley Federal Tank Battery	Facility Type Tank Battery

Surface Owner Federal	Mineral Owner	Lease No. NM-29281
------------------------------	---------------	---------------------------

LOCATION OF RELEASE

Unit Letter K	Section 29	Township 17-S	Range 29-E	Feet from the 1650	North/South Line South	Feet from the 2310	East/West Line West	County Eddy
-------------------------	----------------------	-------------------------	----------------------	------------------------------	----------------------------------	------------------------------	-------------------------------	-----------------------

Latitude N 32.80277° Longitude W 104.09825°

NATURE OF RELEASE



Type of Release: Produced Water	Volume of Release 40 bbls	Volume Recovered 35 bbls
Source of Release Water Tank	Date and Hour of Occurrence 10/23/2010	Date and Hour of Discovery 10/23/10 8:00 a.m.
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher - OCD	
By Whom? Josh Russo	Date and Hour 10/25/10	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse. N/A	

If a Watercourse was Impacted, Describe Fully.*
N/A

Describe Cause of Problem and Remedial Action Taken.*
Water Tank overflowed due to electrical problem with the water transfer pump. The electrical problem has been corrected and the water transfer pump is back in service.

Describe Area Affected and Cleanup Action Taken.*
Tetra Tech inspected site and collected samples to define spills extent. Soil with elevated chloride concentrations was removed and hauled away to Controlled Recovery, Inc., Hobbs, NM. Site was then brought up to surface grade with clean backfill material. Tetra Tech prepared closure report and submitted to NMOCD for review.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature: 	OIL CONSERVATION DIVISION	
Printed Name: Ike Tavarez (Agent for COG)	Approved by District Supervisor 	
Title: Project Manager	Approval Date: DEC 17 2012	Expiration Date: N/A
E-mail Address: ike.tavarez@tetrattech.com	Conditions of Approval: N/A	Attached <input type="checkbox"/>
Date: 1-25-12	Phone: (432) 682-4559	

* Attach Additional Sheets If Necessary

2RP-471