<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II
1301 W. Grand Avenue, Artesia, NM 88210
District III 1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

Date: 10-3-12

* Attach Additional Sheets If Necessary

State of New Mexico **Energy Minerals and Natural Resources**

Oil Conservation Division 1220 South St. Francis Dr. Santa Ea NIM 87505

Revised October 10, 2003 Submit 2 Copies to appropriate District Office in accordance

Form C-141

with Rule 116 on back side of form

Saina Fe, INM 87303													
Release Notification and Corrective Action													
nJM/1229039489							OPERATOR			al Report	\boxtimes	Final Report	
							Contact CAMPBELL, RODNEY						
							Telephone No. (575) 628-4167						
Facility Name INDIAN BASIN GAS PLANT I						Facility Type GAS PROCESSING FACILITY							
Surface Owner Mineral Owner II						NDIAN BASIN			Lease No.				
LOCATION OF RELEASE													
									West Line County				
G 23 21-S 23-E							Eddy						
Latitude 32°27'52.502" Longitude 104°34'28.004"													
NATURE OF RELEASE													
Type of Release Gas Volume of Release 166.2 MCF Volume Recovered 0													
Source of Release							Date and Hour of Occurrence			Date and Hour of Discovery			
Residue Flare							10/2/2012 4:35:00 PM			10/2/2012 4:35:00 PM			
Was Immediate Notice Given? ☐ Yes ☐ No ☒ Not Required						If YES, To Whom? N/A							
By Whom? N/A						Date and Hour N/A							
Was a Watercourse Reached?							If YES, Volume Impacting the Watercourse.						
☐ Yes ☒ No						N/A			See the second s				
If a Watercourse was Impacted, Describe Fully.*										· · · · · · · · · · · · · · · · · · ·	A COLOR	, 	
N/A									l n	CT 012	042	ł	
OCT 04 2012												ı	
									NMOCD ARTESIA				
Describe Cau	ise of Probl	em and Reme	dial Actio	n Taken.*	,						-O#		
Cause:													
			INUTES I	DUE TO HIGH O	XYGE	N CONTENT	•					•	
Remedial Ac			ATHERIN	JG LINE FOR EX	CESS	IVE O2 DUE	TO THE SHOR	T DHR	ATION OF	THE FLAR	E EVE	ENT THE	
OPERATIONS SAMPLED INLET GATHERING LINE FOR EXCESSIVE O2. DUE TO THE SHORT DURATION OF THE FLARE EVENT THE SOURCE OF O2 COULDN'T BE DETERMINED.													
	Describe Area Affected and Cleanup Action Taken.*												
N/A													
				is true and comp									
				nd/or file certain re ce of a C-141 repo									
should their o	or the chyl	nave failed to	adequately	investigate and re	nt by u emedia	te contaminat	on that pose a thr	eport o	round wate	r surface w	iaioi oi ater hii	, naonny man health	
	should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other												
federal, state,	or local la	ws and/or regi	ılations.		· .		.	•					
OIL CONSERVATION DIVISION													
Signature: Rafa							Accepted for record						
							Approved by District Supervisor:						
Printed Name: RODNEY CAMPBELL							·· · · · · · · · · · · · · · · · · · ·						
Title: HES Specialist A							Approva Ocate: 1 7 2013			Expiration Date:			
•							Conditions of Approval:			Attached			