<u>District I</u> 1625 N. French Dr., Hobbs, NM 88240 District II

811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410 District IV 1220 S. St. Francis Dr., Santa Fe, NM 87505

## State of New Mexico Jan Division State of New Mexico Jan Division Submit 1 Copy to appropriate District Office in accordance with 19.15.29 NMAC. State of New Mexico RECEIVED

1220 South St. Francis PMMOCD ARTESIA Santa Fe, NM 87505

TUI		_	Keit	ease Nounc	auon	and Co	orrective A	cuon					
n MW	1409	28,55	518			<b>OPERA</b>	ГOR			al Report		Final Report	
Name of Co	mpany: B	(	Contact: Tony Savoie										
Address: 52	2 W. Merr		Telephone No. 575-887-7329										
Facility Nar	ne: PLU-3	j	Facility Type: Exploration and Production										
Surface Owner: U.S.A.) \ \ \ Mineral Owner:							: U.S.A. API No.30-015-41185						
Burrace OW	10.0.0.7		/ 5			7111110	.50 015 41	103					
		ate or				OF RE	·						
Unit Letter D	Section 18	Township 25S	1   5			n/South Line Feet from the 418		East/West Line West		County: Eddy			
Latitude N 32.136122 Longitude W 103.824399													
NATURE OF RELEASE													
Type of Release: Crude oil and produced water Volume of Release: 29 bbls crude Volume Recovered:20 bbls crude oil and													
							oil and 6 bbls produced water 5 bbls produced water						
Source of Release							Date and Hour of Occurrence:  1/5/14 at 7:00 a.m.  Date and Hour of Discovery: 1/5/14 at 7:00 a.m.						
Was Immediate Notice Given?  ☐ Yes ☐ No ☐ Not Required							If YES, To Whom? Delayed report to Mike Bratcher NMOCD BLM on 1/5/14 at 12:30 p.m.						
By Whom? Tony Savoie						Date and Hour 1/7/14 at 11:36 a.m.							
Was a Watercourse Reached?  ☐ Yes ☒ No							If YES, Volume Impacting the Watercourse.						
If a Watercourse was Impacted, Describe Fully.*							<del></del>						
11 a watercourse was impacted, Describe Fully.													
Describe Cause of Problem and Remedial Action Taken.*													
The valves or	the proces	s valves were	misaligne	ed and the flare scr	ubber d	ump failed to	o operate properly	. The sy	stem over j	pressured an	d fluid	went out the	
flare line ven	t. The syste	m was restore	d to norm	al operations.									
Describe Are	a Affected a	and Cleanup A	Action Tal	cen.*									
Approximate	ly <b>247,86</b> 0 :	sq.ft. of pastu	re area wa	s lightly misted by									
				ted by the release,									
				ontained some of the with soap, water an				luid was	s recovered	from the be	rmed ar	rea. The	
The spill will be remediated in accordance to the NMOCD and BLM recommended guidelines.  I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and													
				is true and compl nd/or file certain re									
				ce of a C-141 report									
should their o	perations h	ave failed to a	dequately	investigate and re	mediate	contaminat	ion that pose a thr	eat to gr	ound water	r, surface wa	ter, hur	nan health	
				otance of a C-141 r	eport de	oes not reliev	e the operator of	responsi	ibility for c	ompliance w	ith any	other	
federal, state, or local laws and/or regulations.													
							OIL CONSERVATION DIVISION						
Signature: Sauce										11			
Drint d Name Town Same							Approved by Environmental Specialist: Signed By Mile Brances						
Title: Waste Management and Remediation Specialist							AN 28 2014	<b>)</b>	Expiration	Date:			
						Conditions of Approval:			Attached				
Date: \//4/14 Phone: 432-556-8730 Remediation per OCD Rule & Guidelines, & like approval by BLM. SUBMIT REMEDIATION													
Attach Addi		ets If Necess			ике ар	phroval by B	LIVI. <u>SUBMIT RE</u> I	MEDIA	<u> TION</u>	288	71	7 11	





## New Mexico Office of the State Engineer Water Column/Average Depth to Water

For PLU-387 H

No records found.

Basin/County Search:

Basin: Carlsbad

County: Eddy

Subbasin: Carlsbad

PLSS Search:

Section(s): 7, 12, 13, 18

Township: 25S

Range: 31E