

District I
1625 N. French Dr., Hobbs, NM 88240
District II
811 S. First St., Artesia, NM 88210
District III
1000 Rio Brazos Road, Aztec, NM 87410
District IV
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico
Energy Minerals and Natural Resources

Oil Conservation Division
1220 South St. Francis Dr.
Santa Fe, NM 87505

Form C-141
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in
accordance with 19.15.29 NMAC.

Release Notification and Corrective Action

OPERATOR

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name: Turner B #81	Facility Type: Oil Production

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-26389
-----------------------	-----------------------	----------------------

LOCATION OF RELEASE

Unit Letter J	Section 29	Township 17S	Range 31E	Feet from the 2545	North/South Line South	Feet from the 2615	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	-------------

Latitude 32.8053082596052 Longitude -103.891817672312

NATURE OF RELEASE



Type of Release: Oil	Volume of Release .5bbls/.5bbls	Volume Recovered 0
Source of Release: pipeline	Date and Hour of Occurrence 08/23/2012 12:15 pm	Date and Hour of Discovery 08/23/12 12:20pm
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? BLM Terry Gregston, Mike Bratcher NMOCD	
By Whom? Joe Hernandez	Date and Hour: 12/23/12 12:20 PM	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.* NA	NMOCD ARTESIA MAY 06 2014
---	-------------------------------------

Describe Cause of Problem and Remedial Action Taken.* 1/2 inch nipple between the valve and elbow on the flow line was leaking due to corrosion on the fittings that leaked around the well head. The fittings were replace.	RECEIVED
---	-----------------

Describe Area Affected and Cleanup Action Taken.* The spill traversed approximately 15 ft. Northwest of the location, impacting an area of 30 feet long by 1ft wide. Linn energy retained DFSI for the remediation of this site. All impacted soil was removed to an NMOCD approved facility. The impacted pasture area was remediated and re-seeded according to BLM guidelines.
--

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

Signature:		OIL CONSERVATION DIVISION	
Printed Name: Brian Wall		Approved by Environmental Specialist: 	
Title: Construction Foreman II		Approval Date: 5/7/14	Expiration Date: NA
E-mail Address: bwall@linenergy.com		Conditions of Approval: 	
Date: 04/28/2014 Phone: 806-367-0645		Attached <input type="checkbox"/>	

* Attach Additional Sheets If Necessary