

District I  
1625 N. French Dr., Hobbs, NM 88240  
District II  
811 S. First St., Artesia, NM 88210  
District III  
1000 Rio Brazos Road, Aztec, NM 87410  
District IV  
1220 S. St. Francis Dr., Santa Fe, NM 87505

State of New Mexico  
Energy Minerals and Natural Resources

Oil Conservation Division  
1220 South St. Francis Dr.  
Santa Fe, NM 87505

Form C-141  
Revised August 8, 2011

Submit 1 Copy to appropriate District Office in  
accordance with 19.15.29 NMAC.

**Release Notification and Corrective Action**

**OPERATOR**

☐ Initial Report ☒ Final Report

Name of Company: Linn Operating, Inc.	Contact: Brian Wall
Address: 2130 W. Bender Hobbs, NM 88240	Telephone No. 575-738-1739
Facility Name: Turner B #103	Facility Type: Oil Production

Surface Owner Federal	Mineral Owner Federal	API No. 30-015-26665
-----------------------	-----------------------	----------------------

**LOCATION OF RELEASE**

Unit Letter B	Section 20	Township 17S	Range 31E	Feet from the 1300	North/South Line North	Feet from the 1370	East/West Line East	County Eddy
------------------	---------------	-----------------	--------------	-----------------------	---------------------------	-----------------------	------------------------	-------------

Latitude 32.8237284410225 Longitude -103.887811333549

**NATURE OF RELEASE**

Type of Release: Produced Water	Volume of Release 15 bbl.	Volume Recovered 0
Source of Release: 2" poly flow line	Date and Hour of Occurrence 07/02/2013 8:30 AM	Date and Hour of Discovery 07/02/2013 8:30 AM
Was Immediate Notice Given? <input checked="" type="checkbox"/> Yes <input type="checkbox"/> No <input type="checkbox"/> Not Required	If YES, To Whom? Mike Bratcher NMOCD	
By Whom?	Date and Hour 10/15/13 11:45 A.M.	
Was a Watercourse Reached? <input type="checkbox"/> Yes <input checked="" type="checkbox"/> No	If YES, Volume Impacting the Watercourse.	

If a Watercourse was Impacted, Describe Fully.\*  
NA

**RECEIVED**

MAY 06 2014

**NMOCD ARTESIA**

Describe Cause of Problem and Remedial Action Taken.\*



A 2" poly flow line was struck by a trakhoe being used by diversified while excavating contaminated soil from a previous leak. This resulted in a 2" cut in the line that released gas and a small amount of water, however no oil was released.

Describe Area Affected and Cleanup Action Taken.\*

The flow line was immediately shut in and repaired. There was an impact of 15 gal. of produced water. DFSI removed the impacted soil to an NMOCD approved facility. On April 10, 2001 the site was seeded and restored to its natural state per BLM guidelines.

I hereby certify that the information given above is true and complete to the best of my knowledge and understand that pursuant to NMOCD rules and regulations all operators are required to report and/or file certain release notifications and perform corrective actions for releases which may endanger public health or the environment. The acceptance of a C-141 report by the NMOCD marked as "Final Report" does not relieve the operator of liability should their operations have failed to adequately investigate and remediate contamination that pose a threat to ground water, surface water, human health or the environment. In addition, NMOCD acceptance of a C-141 report does not relieve the operator of responsibility for compliance with any other federal, state, or local laws and/or regulations.

**OIL CONSERVATION DIVISION**

Signature: Fred B Wall	Approved by Environmental Specialist: 	
Printed Name: Brian Wall	Approval Date: 5/2/14	Expiration Date: NA
Title: Construction Foreman II	Conditions of Approval: 	
E-mail Address: bwall@linenergy.com	Attached <input type="checkbox"/>	
Date: 03/25/2014 Phone: 806-367-0645		

\* Attach Additional Sheets If Necessary

2RP-1735